Plaintiffs' Exhibit 2 (Part 3 of 5)

* = Min. Charge

Claim Number: Insured:

PA123 BORDEN

= Exempt from Overhead. Profit or Taxes

+ = Overrides

Page

31

~= Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
GUEST BEDRO	OM 12.00 X 17.00 SFLW= 98.40	9 X 8.20 + o SFSW= 139.40	ffset 2.00 X 8.30 SFR = 832.32	SFC = 220.60	611.7.
I OPENED WALLS.	ALLS IN THE ROOMS ABOVE AN		THROUGHOUT		
1,189 Remove	JOIST, FLOOR BAKING SODA SPRA	220.60 LFF	0.92	202.95	
1,190 Remove	WALL STUD, 2"x4" COMPLETE CLE	611.72 SFW	0.12	73.41	
1,191 Special	CLEAN & SEAL FRAMING CEILING	408.00 SFL	0.32	130.56	
1,192 Special	CLEAN & SEAL FRAMING WALL	204.00 SFL	0.32	65,28	
1.193 Remove	DRYWALL CEIL	220.60 SFC	0,52	114.71	
-1,194 Replace	DRYWALL CEIL	220.60 SFC	1.30	297.63	
t,195 Paint	CEILING, 2 COATS + PRIME	220.60 SFC	0.59	130.15	
1.196 Remove	INSUL,CEIL,BATT,FOIL FC,9"	220.60 SFC	0.20	44.12	
1,197 Replace	INSUL, CEIL, BATT, FOIL FC, 9"	220.60 SFC	1.07	236.04	
1.198 Remove	DRYWALL WALL	611.72 SFW	0,30	183.52	
-1,199 Replace	DRYWALL WALL	611.72 SFW	1.22	766.94	
1.200 Paint	DRYWALL WALL	611.72 SFW	0.58	354,80	
1,201 Remove	WALLPAPER BORDER	74.60 LFW	0.34	25.36	
-1,202 Replace	WALLPAPER BORDER	74.60 LFW	1.34	103.73	
i,203 Remove	BATT INSULATION - WALL R19	306.00 SFW	0.19	58.14	
1,204 Replace	BATT INSULATION - WALL R19	306.00 SFW	0.82	250.92	
1.205 Remove	BASE, COLONIAL 6"	74.60 LFW	0.25	18.65	
~1,206 Replace	BASE, COLONIAL 6"	74.60 LFW	4.79	370.44	
1,207 Paint	BASE, COLONIAL 6"	74.60 LFW	0.66	49.24	
1,208 Remove	BASE, CARPET 4"	74.60 LFW	0.25	18.65	
-1,209 Replace	BASE, CARPET 4"	74:60 LFW	3.55	266.79	
1,210 Remove	DOOR TRIM SET, CUSTOM	6.50 EA	9.32	60.58	
-1,211 Replace	DOOR TRIM SET, CUSTOM	6.50 EA	80.79	531.98	
1,212 Paint	DOOR TRIM SET, CUSTOM	6.50 EA	22.14	143.91	
1,213 Rem/Reset		1.00 EA	60.36	60.36	
1,214 Clean		1.00 EA	5.24	5.24	
	DOOR,		35,16	35.16	
1,215 Paint	DOOR ACCESSORY	1.00 EA			
	DOOR ACCESSORIES	1.00 EA	34.00	34.00	
	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	65.85	131.70	
1,218 Clean	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	12.00	24.00	
1,219 Paint	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	38.00	• 76.00	
1,220 Remove	WINDOW TRIM SET, CUSTOM	2.00 EA	10.72	. 21.44	
-1,221 Replace	WINDOW TRIM SET, CUSTOM	2.00 EA	81.04	163.42	
1,222 Paint	WINDOW TRIM SET, CUSTOM	2.00 EA	2.50	5.00	
1,223 Remove	CASEMENT ANDERSON VYN/WOO		21.69	43.38	
1,724 Replace	CASEMENT ANDERSON VYN/WOO		695.00	1,390.00	
1,225 Paint	WINDOW, CASEMENT, LG	2:00 EA	37.66	75.32	
1,226 Remove	DOOR, EXT, WOOD, PH, SLIDER	1.00 EA	13.55	· 13.55	
1,227 Replace	DOOR, EXT, WOOD, PH, SLIDER	1.00 EA	805.34	805.34	
1,228 Paint	DOOR, EXT, WOOD, PH, SLIDER	1.00 EA	36.04	36.04	
1,229 Remove	CARPET & PAD, EXCELLENT (SY)	24.51 SYF	2.07	50.74	

* = Min. Charge

Claim Number:

PA123

Exempt from Overhead, Profit or Taxes

Overrides

~ = Waste Applied

Insured:

BORDEN

32 Page

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
-1,230 Replace	CARPET & PAD, EXCELLENT (SY)	24.51 SYF	33,55	1,062.35
1,231 Rem/Reset		24.51 SYF	2.80	68.63
1,232 Special	SAND & FINISH DAMAGED FLOOR	220.60 SFF	1.56	344.14
1,233 Remove	WIRING, RESIDENCE	220.60 SF	0.10	22.06
1,234 Replace	WIRING, RESIDENCE	220.60 EA	2.75	606.65
1,235 Remove	RECEPTACLE, DUPLEX/SWITCH	11.00 EA	4.32	47.52
1,236 Replace	RECEPTACLE, DUPLEX/SWITCH	11.00 EA	22.00	242.00
1,237 Remove	OUTLET, TELEPHONE/CABLE	2.00 EA	4.32	8.64
1,238 Replace	OUTLET, TELEPHONE/CABLE	2.00 EA	20.35	40.70
1,238 Remove	RECEPTACLE, DRYER	1.00 EA	8.58	8.58
1,240 Replace	RECEPTACLE, DRYER	1.00 EA	63.77	63.77
1,241 Remove	WALL FIXTURE, VERY GOOD	1.00 EA	8.21	8.21
1,242 Replace	WALL FIXTURE, VERY GOOD	1.00 EA	125.11	125.11
1.243 Remove	CEILING FIXTURE, GOOD	1.00 EA	9.35	9.35
1,244 Replace	CEILING FIXTURE, GOOD	1.00 EA	104.31	104.31
1,245 Remove	FLUOR, FIXTURE, RECESS, 4×1	1.00 EA	8.40	8.40
1,246 Replace	FLUOR FIXTURE, RECESS, 4x1	1,00 EA	103.01	103.01
1,247 Replace	REGISTER, HEAT, 12" X 5"	2.00 EA	22.59	45.18
1,248 Paint	REGISTER, HEAT, 12" X 5"	2.00 EA	3.55	7.10
1,249 Special	DRAPERIES, REMOVE	3.00 EA	31.49	94.47
1,250 Special	DRAPERIES REPLACE	- 3.00 EA	135.00	405.00
1.251 Remove	SMOKE DETECTOR	1.00 EA	9.35	9.35
1,252 Replace	SMOKE DETECTOR	1.00 EA	54,53	54.53
1,253 Remove	COUNTER TOP,25",JOB BUILT	2.50 LFW	2.95	7.38
-1,254 Replace	COUNTER TOP,25",JOB BUILT	2.50 LFW	33.00	83.62
1,255 Remove	SHELF, 1" x 10"	19.30 LFW	0.90	17.37
1,256 Replace	SHELF, 1" x 10"	19.30 LFW	6,54	128.37
1,257 Paint	SHELF, 1" x 10"	19.30 LFW	1.37	26.44
1,258 Remove	CLOSET POLE, 3 1/2*	8.30 LF	0.31	2.57
-1,259 Replace	•	8.30 LF	3.10	26.18
(,260 Paint	CLOSET POLE, 3 1/2"	8.30 LF	0.87	7.22

	OYER FOR GUEST 9.00 X 8.00 X 65.60 SFR = VALLS IN ROOM ABOVE THIS AND	: 350.80 Perimete	r = 34.00	SFLW= 73.80	SFSW=
1,261 Remove	JOIST, FLOOR BAKING SODA SPRA	72.00 LFF	0.92	66.24	
i.262 Remove	WALL STUD, 2"x4" COMPLETE CLE	278.80 SFW	0.12	33.46	
i,263 Special	CLEAN & SEAL FRAMING CEILING	144.00 SFL	0.32	46.08	
1,264 Special	CLEAN & SEAL FRAMING WALL	72.00 SFL	0,32	23.04	
1,265 Remove	DRYWALL CEIL	72.00 SFC	0.52	37.44	•
-1,266 Replace	DRYWALL CEIL	72.00 SFC	1.30	104.45	
1.267 Paint	CEILING, 2 COATS + PRIME	72.00 SFC	0.59	42.48	
1,268 Remove	INSUL, CEIL, BATT, FOIL FC, 9"	72.00 SFC	0.20	14.40	

* = Min. Charge

Claim Number:

PA123

Insured:

BORDEN

0

= Exempt from Overhead, Profit or Taxes = Overrides

Page

33

-= Waste Applied

. =	Waste Applied				
	Operation	2 ******	Quantity / Unit	Unit / Cost	Repl / Cost
	1,269 Replace	INSUL,CEIL,BATT,FOIL FC,9"	72.00 SFC	1.07	77.04
	1.270 Remove	DRYWALL WALL	278.80 SFW	0.30	83.64
	-1,271 Replace	DRYWALL WALL	278.80 SFW	1.22	360.78
	1,272 Paint	DRYWALL WALL	278.80 SFW	0.58	161,70
	1,273 Remove	WALLPAPER BORDER	34.00 LFW	0.34	11.56
	-1,274 Replace	WALLPAPER BORDER	34.00 LFW	1.34	49.32
	1.275 Remove	BATT INSULATION - WALL R19	278.80 SFW	0.19	52.97
	1,276 Replace	BATT INSULATION - WALL R19	278.80 SFW	0.82	228.62
	1,277 Remove	BASE, COLONIAL 6"	34.00 LFW	0.25	8,50
	4,278 Replace	BASE, COLONIAL 6"	34.00 LFW	4.79	175.96
	1,279 Paint	BASE, COLONIAL 6*	34.00 LFW	0.66	22.44
	1,280 Remove	BASE, 4	34.00 LFW	0.25	8.50
	~1,281 Replace	BASE, 4"	34.00 LFW	3.55	122.66
	1,282 Paint	BASE, 4	34.00 LFW	0.65	22.10
	1,283 Remove	DOOR TRIM SET, CUSTOM	3.50 EA	9.32	32.62
	-1,284 Replace	DOOR TRIM SET, CUSTOM	3.50 EA	80.79	286.37
	1,285 Paint	DOOR TRIM SET, CUSTOM	3.50 EA	22.14	. 77.49
		DOOR EXTERIOR	1.00 EA	60.36	60.36
	1,287 Clean	DOOR,	1.00 EA	5.24	5.24
	1,288 Paint	DOOR	1.00 EA	35.16	35.16
		DOOR ACCESSORIES	· 1.00 EA	34.00	34.00
		DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	65.85	131.70
	1,291 Clean	DOOR, CLOSET, BIPASS, LOUVER		12.00	24.00
	(292 Paint	DOOR, CLOSET, BIPASS, LOUVER		38.00	76.00
	1,293 Remove	DOOR, CLOSER HANDICAPP	1.00 EA	3 8 .73	38.73
	1,294 Replace	DOOR, CLOSER HANDICAPP	1.00 EA	590.00	590.00
	1.295 Remove	WINDOW TRIM SET, CUSTOM	3.00 EA	10.72	32.16
	4,296 Replace	WINDOW TRIM SET, CUSTOM	3.00 EA	81.04	245.12
	1,297 Paint	WINDOW TRIM SET, CUSTOM	3.00 EA	2.50	7.50
	1,298 Remove	CASEMENT ANDERSON VYN/WO		21.69	65.07
	1,299 Replace	CASEMENT ANDERSON VYN/WO	*	695.00	2,085.00
	1,300 Paint	WINDOW, CASEMENT, LG	3.00 EA	37.66	112.98
	i,301 Remove	UNDERLAYMENT, LAUAN, 1/4"	72.00 SFF	0.49	35.28
	~1,302 Replace	UNDERLAYMENT, LAUAN, 1/4*	72.00 SFF	0.84	71.11
	1,303 Remove	CERAMIC FLOOR, THIN SET, 12"X		0.71	51.12
	-1,304 Replace	CERAMIC FLOOR, THIN SET, 12"X		11.00	818.24
	1,305 Remove	WIRING, RESIDENCE	72.00 SF	0.10	7.20
	1,305 Replace	WIRING, RESIDENCE	72.00 EA	2.75	198.00
	1,306 Replace	CEILING FIXTURE, GOOD	1.00 EA	9.35	9.35
	1,307 Remove	CEILING FIXTURE, GOOD	1.00 EA	104.31	104.31
	1,308 Replace	REGISTER, HEAT, 12" X 5"	3.00 EA	22.59	67.77
	1,309 Replace	REGISTER, HEAT, 12" X 5"	3.00 EA	3,55	10.65
	(,311 Special	DRAPERIES, REMOVE	3.00 EA	31.49	94.47
	•	DRAPERIES, REPLACE	3.00 EA	135.00	405.00
)	1,312 Special	SMOKE DETECTOR	1.00 EA	9.35	9,35
	1,313 Remove		1.00 EA	54.53	54.53
	1,314 Replace	SMOKE DETECTOR	1.00 EA	- 54.23	21.22

Claim Number:

* = Min. Charge

Insured:

PA123 BORDEN



= Exempt from Overhead, Profit or Taxes

Page

SFLW= 196.80

34

= Overrides ~= Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
1,315 Remove -1,316 Replace 1,317 Paint 1,318 Remove -1,319 Replace 1,320 Paint	SHELF, 1" x 10" SHELF, 1" x 10" SHELF, 1" x 10" CLOSET POLE, 3 1/2" CLOSET POLE, 3 1/2" CLOSET POLE, 3 1/2"	9.00 LFW 9.00 LFW 9.00 LFW 9.00 LF 9.00 LF 9.00 LF	0.90 6.54 1.37 0.31 3.10 0.87 4.32	8.10 59.87 12.33 2.79 28.39 7.83 12.96
1,321 Remove 1,322 Replace	RECEPTACLE, DUPLEX/SWITCH RECEPTACLE, DUPLEX/SWITCH		22.00	66.00

OUT OF ORDER	LR ON MAIN FL24.00 X 14.00	X 8.20		336.00 SFW = 623	.20 SFLW= 196.80
	CRSW = 114.80	3rk = 3	959.20	Perimeter = 76.00	
CEILING IS P	LASTER HEAVY SMOKE INSIDE I	DD V VLL DJ VLIEKTOK	WALLS.	FLOOR JOIST	
ARE BURNT	IN CRAWL SPACE AREA AND WAI	KKAINI N	DIMO 4 AL		
1,323 Remove	JOIST, CEILING & FLOOR COMPLE	336.00 L	FF ·	0.57	191.52
1,323 Remove	JOIST, CEILING & FLOOR COMPLE	336.00 L	FF	2.14	752.20
1,324 Replace	WALL STUD, 2"x4" COMPLETE	311.50 S	FW	0.72	224.28
1,325 Replace	WALL STUD, 2"x4" COMPLETE	311.50 S	FW	1.82	566.93
1,327 Remove	WALL STUD, 2"x4" COMPLETE CLE	311.50 S		0.12	37.38
	CLEAN & SEAL FRAMING CEILING	336.00 S		0.32	107.52
1,328 Special	CLEAN & SEAL FRAMING WALL	311.50 \$		0.32	99.68
1,329 Special	SHORING, CEILING RAFTERS	1.00 I		295.00	295.00
1,330 Special	PLASTER & WIRE LATH 3 COATS	1.00 \$		1.15	1.15
1,331 Remove	PLASTER & WIRE LATH 3 COATS	336.00 8		6.20	2,090.32
-1,332 Replace	CEILING, 2 COATS + PRIME	336.00		0.59	198.24
1,333 Paint	INSUL, CEIL, BATT, FOIL FC,9"	336.00		0.20	67.20
1,334 Remove	INSUL, CEIL, BATT, FOIL FC, 9"	336.00		1.07	359.52
1,335 Replace	DRYWALL WALL	623.20		0.30	186.96
1,336 Remove		623.20		1,22	780.95
-1.337 Replace	DRYWALL WALL DRYWALL WALL	623.20		0,58	361.46
1,338 Paint		76.00		5.38	408.88
1,339 Paint	STENCILING	76.00		0.25	19.00
1,340 Remove	BASE, COLONIAL, 3 1/2"	76.00		2.56	202.22
-1,341 Replace	BASE, COLONIAL, 3 1/2"	76.00		0.65	49,40
1,342 Paint	BASE, COLONIAL, 3 1/2"	1.00		9.32	9.32
1,343 Remove	DOOR TRIM SET, CUSTOM	1.00		80.79	82.95
-1,344 Replace	DOOR TRIM SET, CUSTOM	1.00		22.14	22.14
1,345 Paint	DOOR TRIM SET, CUSTOM			0.43	32.68
1,346 Remove	MOLDING, CROWN, 4 5/8"	76.00		4.55	347.76
-1,347 Replace	MOLDING, CROWN, 4 5/8*	76.00		10.72	10.72
1,348 Remove	OPENING, CASED	1.00		82.36	85.36
-1,349 Replace	OPENING, CASED	1.00		30.99	30.99
1,350 Paint	OPENING, CASED	1.00			26.80
1,351 Remove	WINDOW TRIM SET, CUSTOM	2.50		10.72	204.16
-1,352 Replace	WINDOW TRIM SET, CUSTOM	2.50	EA	81.04	204.10

* = Min. Charge

Claim Number:

PA123

Insured:

BORDEN

Overrides

Exempt from Overhead, Profit or Taxes

Page

35

_		
~÷=	Waste	Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
1.353 Paint	WINDOW TRIM SET, CUSTOM	2.50 EA	2.50	6.25
17	SHEATHING FLOOR, PLYWOOD	336.00 SFC	0.47	157.92
	SHEATHING FLOOR, PLYWOOD	336.00 SFC	1.87	637.58
1.356 Remove	OAK FLOOR, 2 1/4", CLEAR	336.00 SFF	0.64	215.04
-1	OAK FLOOR, 2 1/4", CLEAR	336.00 SFF	7.90	3,263.13
	SAND AND FINISH FLOORS	336.00 SFF	3.15	1,058.40
1,359 Replace	WINDOW, BOW CASEMENT, 26 X 2	1.00 EA	1,160.00	1,160.00
1,360 Remove	WINDOW, CASEMENT, LG	1.00 EA	41.00	41.00
1,361 Paint	WINDOW, CASEMENT, LG	1.00 EA	55,00	55.00
1,362 Remove	CASEMENT ANDERSON VYN/WOO	4.00 EA	21.69	86.76
1,363 Replace	CASEMENT ANDERSON VYN/WOO		695.00	2,780,00
1,364 Paint	WINDOW, CASEMENT, LG	4.00 EA	37.66	150.64
1365 Remove	WIRING, RESIDENCE	336,00 SF	0.10	33.60
1,366 Replace	WIRING, RESIDENCE	336.00 EA	2.75	924.00
1.367 Remove	RECEPTACLE, DUPLEX/SWITCH	10.00 EA	4.32	43.20
1,368 Replace	RECEPTACLE, DUPLEX/SWITCH	10.00 EA	22.00	220.00
1,369 Replace	REGISTER, HEAT, 12" X 5"	2.00 EA	22.59	45.18
1,370 Paint	REGISTER, HEAT, 12" X 5"	2.00 EA	3.55	7.10
1,371 Special	DRAPERIES, REMOVE/RESET	4.00 EA	31.49	125.96
1,372 Replace	BUILT IN DOORS BELOW CASE AF	1.00 LFW	900.00	900.11
1,373 Paint	BUILT IN -	1.00 -LFW	74.00	74.00
1,374 Remove	MOLDING, CROWN, 4 5/8" MULTI	5.80 LFW	0.43	2.49
1,375 Replace	MOLDING, CROWN, 4 5/8" MULTI	5.80 LFW	2.76	16.67
1,376 Paint	MOLDING, CROWN, 4 5/8" MULTI	5.80 LFW	0.70	4.06
1,377 Remove	FIREPLACE MANTEL, BEAM	1.00 LF	25.00	25.00
1,378 Replace	FIREPLACE MANTEL, BEAM	1.00 LF	567.00	567.00
1,379 Paint	FIREPLACE MANTEL, BEAM	1.00 LF	75.00	75.00
1,380 Rem/Reset	FIREPLACE, GAS, EX	1.00 EA	185.00	185.00

Interior

MAIN STAIR CASE

14.60 X 4.80 X 12.00 + offset 9.70 X 7.20 SFLW= 175.20

SFSW = 57.60

SFR = 778.32

SFC = 139.92Perimeter = 53.20 SFW = 638.40

THE CEILING HEIGHT IS AN AVERAGE. THE WALLS WERE OPENED UNDER THE STAIRS AND THERE IS HEAVY SMOKE ON THE STAIRWAY CHAMBERS. I ALSO CRAWLED INTO THE CRAWL SPACE AND FOUND EXTENSIVE DAMAGE TO THE LANDING FRAMING AND SILLS.

1.381 Remove	JOIST FLOOR COMPLETE	139.60 LFF	0.57	79.57
~1,382 Replace	JOIST FLOOR COMPLETE	139.60 LFF	2.14	312,52
1,383 Special	SCAFFOLD & SHORING CEILING JC	1.00 LS	295.00	295.00
L384 Remove	WALL STUD, 2"x4" FRONT WALL	125.00 SFW	0.72	90.00
1,385 Replace	WALL STUD, 2"x4" COMPLETE	125.00 SFW	1.82	227.50
1,386 Special	CLEAN & SEAL FRAMING CEILING	70,08 SFL	0.32	22.43
1,387 Special	CLEAN & SEAL FRAMING WALL	513.40 SFL	0.32	164.29
1,388 Remove	DRYWALL WALL, 1/2", TAPED	638.40 SFW	0.30	191.52

* = Min. Charge

Claim Number:

PA123

Exempt from Overhead, Profit or Taxes

BORDEN Insured:

Exempt from Over	rhead, Profit or Taxes			Page 36
= Overrides				
= Waste Applied				
Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
4,389 Replace	DRYWALL WALL,1/2", TAPED	638.40 SFW	1.22	797.25
1,390 Paint	CEILING, 2 COATS + PRIME	139.92 SFC	0.59	82.55
1,391 Remove	INSUL,CEIL,BATT,FOIL FC,9"	139.92 SFC	0.20	27.98
1,392 Replace	INSUL,CEIL,BATT,FOIL FC,9"	139.92 SFC	1.07	149.71
1,392 Replace	DRYWALL WALL	638.40 SFW	0,30	191.52
1,394 Replace	DRYWALL WALL	638.40 SFW	1.22	799.49
1,394 Replace 1,395 Paint	WALLS, 2 COATS	638.40 SFW	0.58	370.27
(,396 Paint	STENCILING	9.70 LFW	5.38	52.19
	BASE, COLONIAL, 3 1/2"	53.20 LFW	0.25	13.30
1,397 Remove	BASE, COLONIAL, 3 1/2"	53.20 LFW	2.56	143.85
4,398 Replace	BASE, COLONIAL, 3 1/2"	53.20 LFW	0.65	34.58
1,399 Paint	BASE SHOE, PINE	53.20 LFW	0.27	14.36
1,400 Remove	BASE SHOE, PINE	53.20 LFW	1.58	86.49
1,401 Replace	BASE SHOE, PINE	53.20 LFW	0.62	32.98
i,402 Paint	SHEATHING FLOOR, PLYWOOD	38.40 SFC	0.47	18.05
1,403 Remove	SHEATHING FLOOR, PLYWOOD	38.40 SFC	1.87	75.65
1,404 Replace	OAK FLOOR, 2 1/4°, CLEAR	38.40 SFF	0.64	24.58
1,405 Remove	OAK FLOOR, 2 1/4", CLEAR	38.40 SFF	7,90	372.92
1,406 Replace	SAND AND FINISH FLOORS	38,40 SFF	3.15	120.96
1,407 Special	DECROATIVE PANELS TRIMMED	16.00 LFW	4.00	64.00
1,408 Remove	DECROATIVE PANELS TRIMMED	16.00 LFW	35.00	560.54
1,409 Replace	DECROATIVE PANELS TRIMMED	16.00 LFW	9.00	144.00
1,410 Paint		53.20 LFW	0.25	13.30
1,411 Remove	CHAIR RAIL, 3 1/2"	53.20 LFW	3.24	182.61
-1,412 Replace	CHAIR RAIL, 3 1/2"	53.20 LFW	0.65	34.58
1,413 Paint	CHAIR RAIL, 3 1/2"	1.00 EA	9.32	9.32
1,414 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	81.87
-1,415 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14
1,416 Paint	DOOR TRIM SET, CUSTOM	3.00 EA	10.72	32.16
1,417 Remove	WINDOW TRIM SET, CUSTOM	3.00 EA	81.04	245.12
-1.418 Replace	WINDOW TRIM SET, CUSTOM	3.00 EA	31.26	93,78
1,419 Paint	WINDOW TRIM SET, CUSTOM		0.10	13.99
1,420 Remove	WIRING, RESIDENCE	139.92 SF	2.75	384.78
1,421 Replace	WIRING, RESIDENCE	139.92 EA	4.32	8.64
1,422 Remove	RECEPTACLE, DUPLEX/SWITCH	2.00 EA	22.00	44.00
t,423 Replace	RECEPTACLE, DUPLEX/SWITCH	2.00 EA	19.36	19.36
1,424 Remove		1.00 EA	487.40	487.40
1,425 Replace		1.00 EA	9.35	9,35
1,426 Remove		1.00 EA		104.31
1,427 Replace		1.00 EA	104.31	324.00
1,428 Replace		3.00 EA	108.00	43.38
1,429 Remove			21.69	1,390.00
1,430 Replace			695,00	
1,431 Paint	WINDOW, CASEMENT, LG	2.00 EA	37.66	75.32 27.63
1,432 Rem/Re	set ANDERSON TRIPPLE CASEMENT		77.62	77.62
1,433 Replace	ANDERSON TRIPPLE CASEMENT		1,600,00	1,600.00
1,434 Paint	WINDOW, CASEMENT, LG	1.00 EA	75.00	75.00

Filed 12/16/2005 Page 8 of 50 Case 1:04-cv-00175-SJM Document 24-4

Building Repair Estimate

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

Exempt from Overhead, Profit or Taxes

Overrides

Page

37

- = Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
: A35 Rem/Reset	DOOR ONLYATTIC	1.00 EA	57.89	57,89
L436 Clean	DOOR ONLYATTIC	. 1.00 EA	3,98	3.98
1,437 Paint	DOOR ONLYATTIC	1.00 EA	22.23	22.23
•	INSULATE DOOR ONLY,	1,00 EA	77.89	77.89
1,439 Remove	RAIL&BAL.,FINISHED,3',3 PC	16.00 EA	6.80	108.80
1,440 Replace	RAIL&BAL,,FINISHED,3',3 PC	16,00 EA	185.84	2,973.44
1,440 Replace	RAIL&BAL FINISHED,3',3 PC	16.00 LF	3.34	53.44
	RAILING, OAK	9.70 LF	5.60	54.32
1,442 Kent Keset	RAILING, OAK	9.70 LF	0.36	3.49
1,443 Crean	RAILING, OAK	9.70 LF	1.32	12.80
1,444 ramu 1,445 Remove	SKIRT BOARD, 1" X 10"	15.70 LFW	1.36	21.35
1,445 Replace	SKIRT BOARD, 1" X 10"	15,70 LFW	6.90	108.94
1,446 Replace	SKIRT BOARD, 1" X 10"	53.20 LFW	15,70	835.24
1,447 Fam.	TREAD,OAK	14.00 LF	12.00	168.00
1,448 Remove	TREAD,OAK	14.00 LF	85.00	1,190.00
1,449 Replace	TREAD,OAK	14.00 RS	12.00	168.00
1,450 Panit 1,451 Remove	RISER, PINE, 3/4" X 7 1/2"	42,00 LF	1.12	47,04
1,452 Replace	RISER, PINE, 3/4" X 7 1/2"	42.00 LF	7,07	296.94
1.453 Paint	RISER, PINE, 3/4" X 7 1/2"	42.00 LF	1.46	61.32
1,454 Remove	BASE SHOE, UNDER TREAD	42.00 LFW	0.27	11.34
-1,455 Replace	BASE SHOE, PINE	- 42.00 LFW	1.58	67.77
1,456 Paint	BASE SHOE, PINE	42.00 LFW	0.62	26.04
1,450 Fame	CARPET & PAD, EXCELLENT (SY		2.07	32.19
-1,458 Replace	CARPET & PAD, EXCELLENT (SY	•	33,55	623.27
1,459 Remove	CARPET STEPS, (EA)	14.00 EA	3.77	52.78
1,459 Remove	CARPET STEPS, (EA)	14.00 EA	5.00	70.00
1,461 Replace	CARPET WASTE	6.00 SFF	8.40	51.13

2ND FLOOR HA	LL 33.20 X 4.00 . SFLW= 265.60	X		SFC = 160.07
I OPENED W	ALL LEFT WALL IS INSULATED A	ND HAS SOOT IN I	Γ.	·
i,462 Remove	JOIST, CEILING BAKING SODA SPR	160.07 LFF	0.92	147.26
1,463 Remove	WALL STUD, 2"x4" COMPLETE CLF	638.40 SFW	0.12	76.61
1,464 Special	CLEAN & SEAL FRAMING CEILING	132.80 SFL	0.32	42.50
1,465 Special	CLEAN & SEAL FRAMING WALL	638.40 SFL	0.32	204.29
1,466 Remove	DRYWALL CEIL	160.07 SFC	0.52	83.24
1,467 Replace	DRYWALL CEIL	160.07 SFC	1.30	218.94
1,468 Paint	CEILING, 2 COATS + PRIME	160.07 SFC	0.59	94.44
1,469 Remove	INSUL,CEIL,BATT,FOIL FC,9"	160.07 SFC	0.20	32.01
1,470 Replace	INSUL, CEIL, BATT, FOIL FC, 9"	160.07 SFC	1.07	171.27
.471 Remove	DRYWALL WALL	638.40 SFW	0.30	191.52
,472 Replace	DRYWALL WALL	638.40 SFW	1.22	799.49
.473 Paint	DRYWALL WALL	638.40 SFW	0.58	370.27

Case 1:04-cv-00175-SJM Filed 12/16/2005 Page 9 of 50 Document 24-4

Building Repair Estimate

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

tempt from Overhead. Profit or Taxes

Page

38

~ = Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
Operation		318.00 SFW	0.19	60.42
1,474 Remove	BATT INSULATION - WALL RIP	318.00 SFW	0.82	260.76
1,475 Replace	BATT INSULATION - WALL R19	79.80 LFW	0.25	19.95
1,476 Remove	BASE, COLONIAL 6°	79.80 LFW	4.79	395.35
1,477 Replace	BASE, COLONIAL 6"	79.80 LFW	0.66	52.67
1,478 Paint	BASE, COLONIAL 6*	79.80 LFW	5.38	429.32
1,479 Paint	STENCILING	5.00 EA	9.32	46.60
(,480 Remove	DOOR TRIM SET, CUSTOM	5.00 EA	80.79	409.36
-1,481 Replace	DOOR TRIM SET, CUSTOM	5.00 EA	22.14	110.70
1,482 Paint	DOOR TRIM SET, CUSTOM	5.00 EA	5.24	26.20
1,483 Clean	DOOR,	5.00 EA	35,16	175.80
1,484 Paint	DOOR	5.00 EA	57.89	289.45
1,485 Rem/Reset	DOOR ONLY, INT, 6 PANEL	79.80 LFW	0.43	34.31
1,486 Remove	MOLDING, CROWN, 4 5/8"	79.80 LFW	2,76	229.44
-1,487 Replace	MOLDING, CROWN, 4 5/8"	79.80 LFW	0.23	18.35
1,488 Clean	MOLDING, CROWN, 4 5/8"	160.07 SFF	0.21	33.61
i,489 Special	FLOOR PREP, RESCREW FLOOR		2,07	36.83
1,490 Remove	CARPET & PAD, EXCELLENT (SY)	·	33.55	649.66
1,491 Replace	CARPET & PAD, EXCELLENT (SY	160.70 SF	0.10	16.07
1,492 Remove	WIRING, RESIDENCE	160.70 BA	2.75	441.92
1,493 Replace	WIRING, RESIDENCE	- 5.00 EA	108.00	540.00
1,494 Replace	FIXTURE,INCNDSCENT,RECESS	2.00 EA	22.59	45.18
1,495 Replace	REGISTER, HEAT, 12" X 5"	2.00 EA	3.55	7.10
1,496 Paint	REGISTER, HEAT, 12" X 5"	1.00 EA	9.35	9.35
1,497 Remove	SMOKE DETECTOR	1.00 EA	54.53	54.53
1,498 Replace	SMOKE DETECTOR		4.32	17.28
1,499 Remove	RECEPTACLE, DUPLEX/SWITCH		22.00	00.88
1,500 Replace	RECEPTACLE, DUPLEX/SWITCH	1.00 EA	4.76	4.76
1,501 Remove	SWITCH, DIMMER TYPE	1.00 EA	65,71	65.71
1,502 Replace		1.00 EA	8,47	8.47
1,503 Remove	THERMOSTAT, GOOD	1.00 EA	62.87	62.87
1,504 Replace	THERMOSTAT, GOOD	1.00 EA	02.0.	

CLOSET	5.80 X 7.12 X 56.96 SFR =	(8.00 SFC = 41. 248.02 Perimeter		SFLW= 46.40	SFSW=
1,505 Remove 1,506 Remove 1,507 Special 1,508 Special 1,509 Remove -1,510 Replace 1,511 Paint 1,512 Remove	JOIST, CEILING BAKING SODA SPR WALL STUD, 2"x4" COMPLETE CLE CLEAN & SEAL FRAMING CEILING CLEAN & SEAL FRAMING WALL DRYWALL CEIL DRYWALL CEIL CEILING, 2 COATS + PRIME INSUL, CEIL, BATT, FOIL FC, 9"	41.30 LFF 206.72 SFW 41.30 SFL 206.72 SFL 41.30 SFC 41.30 SFC 41.30 SFC 41.30 SFC	0.92 0.12 0.32 0.32 0.52 1.30 0.59 0.20	38.00 24.81 13.22 66.15 21.48 64.54 24.37 8.26	

* = Min. Charge

Claim Number:

PA123 BORDEN

Insured:

Exempt from Overhead, Profit or Taxes
Overrides

Page

39

_	=	Waste	Applie	d
_		TT CLUE	Tibbin	

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
1.513 Replace	INSUL,CEIL,BATT,FOIL FC,9"	41.30 SFC	1.07	44.19	
1,514 Remove	DRYWALL WALL	206.72 SFW	0.30	62.02	
4,515 Replace	DRYWALL WALL	206.72 SFW	1.22	272.84	
1,515 Remove	WALLPAPER, EXCELLENT	206.72 SFW	0.41	84.76	
1,510 Replace	WALLPAPER, EXCELLENT	206.72 SFW	1.68	385.08	
1,517 Replace	WALLPAPER BORDER	25.84 LFW	0.34	8.79	
4,519 Replace	WALLPAPER BORDER	25.84 LFW	1.34	35.58	
1,520 Remove	BATT INSULATION - WALL R19	206.72 SFW	0.19	39.28	
1,520 Reniove	BATT INSULATION - WALL R19	206.72 SFW	0.82	169.5 1	
1.522 Remove	BASE, COLONIAL	25.84 LFW	0.25	6.46	
1,522 Reniove	BASE, COLONIAL	25.84 LFW	4.79	136.88	
1,323 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32	
	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	86.20	
-1,525 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14	
-*	FLOOR PREP, RESCREW FLOOR	41.30 SFF	0.21	8.67	
1,527 Special	CARPET & PAD, EXCELLENT (SY)	•	2.07	9,50	
• •	CARPET & PAD, EXCELLENT (SY)		33.55	206.80	
-1,529 Replace 1,530 Remove	WIRING, RESIDENCE	41.30 SF	0.10	4.13	
• • • •	WIRING, RESIDENCE	41.30 EA	2.75	113.57	
1,531 Replace	FIXTURE INCNDSCENT RECESS	1.00 EA	108.00	108.00	
1,532 Replace	RECEPTACLE, DUPLEX/SWITCH	- 1.00 EA	4,32	4.32	
1,533 Remove	RECEPTACLE, DUPLEX/SWITCH	1.00 EA	22.00	22.00	

Laterior

FRONT BEDRO	OOM ON RIGHT 12.50 X 14.10 SFLW= 112.50	X 9.00 + offse SFSW= 126.90	et 2.30 X 7.00 SFR = 797.15	SFC = 192.35
HEIGHT IS A INSULATION	LVERAGE. WALLS WAS OPENED A N.	ND THERE WAS SC	OOT ON THE	
1.535 Remove	JOIST, CEILING BAKING SODA SPR	1,00 LFF	0.92	0.92
1,536 Remove	WALL STUD, 2"x4" COMPLETE CLE	604.80 SFW	0.12	72.58
1,537 Special	CLEAN & SEAL FRAMING CEILING	176.25 SFL	0.32	56.40
1,538 Special	CLEAN & SEAL FRAMING WALL	604.80 SFL	0.32	193.54
1,539 Remove	DRYWALL CEIL	192.35 SFC	0.52	100.02
-1,540 Replace	DRYWALL CEIL	192.35 SFC	1.30	260.9 0
1,541 Paint	CEILING, 2 COATS + PRIME	192.35 SFC	0.59	113.49
1,542 Remove	INSUL,CEIL,BATT,FOIL FC,9"	192.35 SFC	0.20	38.47
1,543 Replace	INSUL,CEIL,BATT,FOIL FC,9"	192.35 SFC	1.07	205.81
1,544 Remove	DRYWALL WALL	604.80 SFW	0.30	181.44
1,545 Replace	DRYWALL WALL	604.80 SFW	1.22	758.50
1,546 Paint	DRYWALL WALL	604.80 SFW	0.58	350.78
1,547 Remove	BATT INSULATION - WALL R19	302.00 SFW	0.19	57.38
1,548 Replace	BATT INSULATION - WALL R19	302,00 SFW	0.82	247.64
1,549 Remove	BASE, COLONIAL	67.20 LFW	0.25	16.80
н,550 Replace	BASE, COLONIAL	67.20 LFW	4.79	334.99

* = Min. Charge

Claim Number:

PA123

Insured:

BORDEN

= Exempt from Overhead. Profit or Taxes

= Overrides

~ = Waste Applied

40 Page

	Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
	1,551 Paint	BASE, COLONIAL	67.20 LFW	0,66	44.35	
	1,552 Remove	DOOR TRIM SET, CUSTOM	6.00 EA	9.32	55.9 2	
	-1,553 Replace	DOOR TRIM SET, CUSTOM	6.00 EA	80.79	491.23	
	1,554 Paint	DOOR TRIM SET, CUSTOM	6.00 EA	22.14	132.84	
	1,555 Clean	DOOR,	2.00 EA	5.24	10.48	
	1,556 Paint	DOOR	2.00 EA	35,16	70.32	
	1,557 Rem/Reset	DOOR ONLY, INT, 6 PANEL	2.00 EA	57.89	115.78	
	1,558 Remove	WINDOW TRIM SET, CUSTOM	1.00 EA	1.50	1.50	
	1,559 Replace	WINDOW TRIM SET, CUSTOM	1.50 EA	81.04	122.67	
	1,560 Paint	WINDOW TRIM SET, CUSTOM	1.50 EA	31.26	46.89	
	1,561 Remove	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	19.36	19.36	
	1,562 Replace	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	1,700.00	1,700.00	
	1,563 Paint	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	58.00	58.00	
	1,564 Special	FLOOR PREP, RESCREW FLOOR	192.35 SFF	0.21	40.39	
	1,565 Remove	SHELF, 1" x 10"	7.00 LFW	0.90	6.30	
	1,566 Replace	SHELF, 1" x 10"	7.00 LFW	6.54	46.56	
	1,567 Paint	SHELF, 1" x 10"	7.00 LFW	1.37	9.59	
	1,568 Remove	CLOSET POLE, 3 1/2*	7.00 LF	0.31	2.17	
	-1,569 Replace	CLOSET POLE, 3 1/2"	7.00 LF	3.10	22.08	
b .	1,570 Paint	CLOSET POLE, 3 1/2"	7.00 LF	0.87	6.09	
,	1.571 Remove	WIRING, RESIDENCE	192.35 SF	- 0.10	19.24	
	1,572 Replace	WIRING, RESIDENCE	192,35 EA	2.75	528.96	
	1,573 Remove	BUILT INS 2	2.00 LFW	25.00	50.00	
	-1,574 Replace	BUILT INS 2	2.00 LFW	900.00	1,800.07	
	1,575 Paint	BUILT INS 2	2.00 LFW	75.00	150.00	
	1,576 Remove	OAK FLOOR, 2 1/4", CLEAR	192.35 SFF	0.64	123.10	
	1,577 Replace	OAK FLOOR, 2 1/4", CLEAR	192.35 SFF	7.90	1,519.57	
	1,578 Special	SAND AND FINISH FLOORS	192.35 SFF	3.15	605,90	
	1,579 Replace	REGISTER, HEAT, 12" X 5"	2.00 EA	22.59	45,18	
	1,580 Paint	REGISTER, HEAT, 12" X 5"	2.00 EA	3.55	7.10	
	1,581 Remove	SMOKE DETECTOR	1.00 EA	9.35	9.35	
	1,582 Replace	SMOKE DETECTOR	1.00 EA	54.53	54.53	
	1,583 Remove	RECEPTACLE, DUPLEX/SWITCH	9.00 EA	4.32	38.88	
	1,584 Replace	RECEPTACLE, DUPLEX/SWITCH	9.00 EA	22.00	198.00	
	1,585 Remove	FIXT,RECESS FLUOR,2X4,4BLBMF	4.00 EA	10.84	43,36	
	1,586 Replace	FIXT,RECESS FLUOR,2X4,4BLBMF	4.00 EA	243.00	972.00	
	1,587 Remove	OUTLET, TELEPHONE/CABEL	7.00 EA	4.32	30.24	
	1,588 Replace	OUTLET, TELEPHONE/CABEL	7.00 EA	20.35	142,45	
	1,589 Remove	FIXT,RECESS FLUOR,2X4,4BLBMF	1.00 EA	10.84	10.84	
	1,590 Replace	FIXT, RECESS FLUOR, 2X4, 4BLBMF	1.00 EA	156.79	156.79	

Case 1:04-cv-00175-SJM Filed 12/16/2005 Page 12 of 50 Document 24-4

Building Repair Estimate

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

Exempt from Overhead Profit or Taxes Overrides

Page

41

	Operation		Quantity / Unit		Repl / Cost
	MASTER BEDR	OOM 16.10 X 13.00 SFLW= 128.80	X 8.00 + offset SFSW= 104.00	8.70 X 9.00 SFR = 897.20	SFC = 287.60
	WALLS OPEN	IED AND HEAVY SMOKE DAMAC	ED		
		JOIST, CEILING BAKING SODA SPR	287.60 LFF	0.92	264.59
	1,591 Remove	WALL STUD, 2"x4" COMPLETE CLE	609.60 SFW	0.12	73.15
	1,592 Remove	CLEAN & SEAL FRAMING CEILING	209.30 SFL	0.32	66.98
	1,593 Special	CLEAN & SEAL FRAMING WALL	609.60 SFL	0.32	195.07
	1,594 Special	DRYWALL CEIL	287.60 SFC	0.52	149.55
	1,595 Remove	DRYWALL CEIL	287.60 SFC	1.30	384.73
	1,596 Replace	CEILING, 2 COATS + PRIME	287.60 SFC	0.59	169.68
	1,597 Paint	INSUL, CEIL, BATT, FOIL FC, 9"	287.60 SFC	0.20	57.52
	1,598 Remove	INSUL, CEIL, BATT, FOIL FC,9"	287.60 SFC	1.07	307.73
	1,599 Replace	DRYWALL WALL	609.60 SFW	0.30	182.88
	1,600 Remove	DRYWALL WALL	609.60 SFW	1.22	764.36
	-1,601 Replace	DRYWALL WALL-FAUX 3 COAT AF		2.00	1,219.20
	1,602 Paint	WALLPAPER BORDER	76.20 LFW	0.34	25.91
	1,603 Remove	WALLPAPER BORDER	76.20 LFW	1.34	105.77
	1,604 Replace	BATT INSULATION - WALL R19	304.00 SFW	0.19	57.76
	1,605 Remove	BATT INSULATION - WALL R19	304.00 SFW	0,82	249.28
,	1,606 Replace	BASE, COLONIAL	76.20 LFW	0.25	19.05
	1,607 Remove	•	76.20 LFW	4,79	378.10
	1,608 Replace	BASE, COLONIAL	76.20 LFW	0.66	50.29
	t,609 Paint	BASE, COLONIAL	3.50 EA	9.32	32.62
	1,610 Remove	DOOR TRIM SET, CUSTOM	3.50 EA	80.79	286.37
	1.611 Replace	DOOR TRIM SET, CUSTOM	3.50 EA	22.14	77.49
	t,612 Paint	DOOR TRIM SET, CUSTOM	1.00 EA	5.24	5.24
	i,613 Clean	DOOR,	1.00 EA	35.16	35.16
	1,614 Paint	DOOR	1.00 EA	57.89	57.89
		DOOR ONLY, INT, 6 PANEL	1.00 EA	10.72	10.72
	1,616 Remove	OPENING, CASED	1.00 EA	82,36	85.36
	1,617 Replace	OPENING, CASED	1.00 EA	30.99	30.99
	1,618 Paint	OPENING, CASED		1.50	3.75
	1,619 Remove	WINDOW TRIM SET, CUSTOM	2.50 EA	81.04	204.16
	1,620 Replace	WINDOW TRIM SET, CUSTOM	2,50 EA	31.26	78.15
	i,621 Paint	WINDOW TRIM SET, CUSTOM	2.50 EA	13.55	13.55
	1,622 Remove	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA	605,34	. 605.34
	1,623 Replace	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA	36.04	36.04
	1,624 Paint	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA		31.26
	1,625 Paint	WINDOW TRIM SET, CUSTOM	1.00 EA	31.26	19.36
	1,626 Remove	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	19.36	1,700.00
	1,627 Replace	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	1,700.00	58.00
_	6628 Paint	WINDOW, TRIPPLE 1/2 MOON	1.00 EA	58.00	
٠.	1,629 Remove	CASEMENT ANDERSON VYN/WO		21.69	21.69
	1,630 Replace	CASEMENT ANDERSON VYN/WO		695.00	695.00
	1,631 Paint	WINDOW, CASEMENT, LG	1.00 EA	37.66	37.66
	1,632 Special	FLOOR PREP, RESCREW FLOOR	287.60 SFF	0.21	60.40

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 Page 13 of 50

Building Repair Estimate

Claim Number:

* = Min. Charge

Insured:

PA123 BORDEN

Exem

Exempt from Overhead, Profit or Taxes

- Overrides

Pac

Page

42

~= Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
L633 Remove	WIRING, RESIDENCE	287.60 SF	0.10	28.76	• • • • • • • • • • • • • • • • • • • •
1,634 Replace	WIRING, RESIDENCE	287.60 EA	2.75	790.90	
1,635 Remove	CARPET & PAD, EXCELLENT (SY)	31.96 SYF	2.07	66.16	
1,636 Replace	CARPET & PAD, EXCELLENT (SY)		33.55	1,167.09	
1,637 Replace	REGISTER, HEAT, 12" X 5"	2.00 EA	22.59	45.18	
(.638 Paint	REGISTER, HEAT, 12" X 5"	2.00 ÉA	3.55	7.10	
1.639 Remove	SMOKE DETECTOR	1.00 EA	9.35	9.35	
1,640 Replace	SMOKE DETECTOR	1.00 EA	54.53	54.53	
L641 Remove	RECEPTACLE, DUPLEX/SWITCH	16.00 EA	4.32	69.12	
1,642 Replace	RECEPTACLE, DUPLEX/SWITCH	16,00 EA	22.00	352.00	
1,643 Remove	OUTLET, TELEPHONE/CABEL	4.00 EA	4.32	17,28	
1,644 Replace	OUTLET, TELEPHONE/CABEL	4.00 EA	20.35	81,40	
1,645 Special	DRAPERIES, REMOVE/RESET	2.00 EA	31.49	62.98	
1.646 Remove	SWITCH, DIMMER TYPE	1.00 EA	4.76	4.76	
t,647 Replace	SWITCH, DIMMER TYPE	1.00 EA	65.71	65.71	

MASTER BED	RROM CLOSET 2.70 X 2.70 X 21.60 SFR =	X 8.00 SFC = 7.25 = 93.69 Perimeter =		SFLW= 21.60	SFSW=
1,648 Remove	JOIST, CEILING BAKING SODA SPR	7.29 LFF	0.92	6.71	
1,649 Remove	WALL STUD, 2"x4" COMPLETE CLE	86.40 SFW	0.12	10.37	
1,650 Special	CLEAN & SEAL FRAMING CEILING	7.29 SFL	0.32	2.33	
1,651 Special	CLEAN & SEAL FRAMING WALL	86.40 SFL	0.32	27.65	
1,652 Remove	DRYWALL CEIL	7.29 SFC	0.52	3.79	
4,653 Replace	DRYWALL CEIL	7.29 SFC	1.30	20,32	
1,654 Paint	CEILING, 2 COATS + PRIME	7.29 SFC	0.59	4.30	
1,655 Remove	INSUL,CEIL,BATT,FOIL FC,9"	7.29 SFC	0.20	1.46	
i 656 Replace	INSUL,CEIL,BATT,FOIL FC,9"	7.29 SFC	1.07	7.80	
1,657 Remove	DRYWALL WALL	86.40 SFW	0.30	25.92	
1,658 Replace	DRYWALL WALL	86.40 SFW	1.22	126.05	
1,659 Paint	DRYWALL WALL, 5/8"FIRE RES	86.40 SFW	0.59	50,98	
1,660 Remove	SHELF, 1" x 10"	12.00 LFW	0.90	10.80	
-1,661 Replace	SHELF, 1" x 10"	12.00 LFW	6.54	79,82	
i,662 Paint	SHELF, 1" x 10"	12.00 LFW	1.37	16.44	
1,663 Remove	CARPET & PAD, EXCELLENT (SY)	0.81 SYF	2.07	1.68	
-1,664 Replace	CARPET & PAD, EXCELLENT (SY)	0.81 SYF	33.55	122.00	
1,665 Remove	BASE, COLONIAL	10.80 LFW	0.25	2.70	
⊣,666 Replace	BASE, COLONIAL	10,80 LFW	4.79	64,84	
1,667 Paint	BASE, COLONIAL	10,80 LFW	0.66	7.13	
1,668 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32	
-1,669 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	84.39	
i.670 Paint	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14	

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 Page 14 of 50 PA123 Claim Number: **Building Repair Estimate** BORDEN Insured: * = Min. Charge xempt from Overhead. Profit or Taxes 43 Page verrides - Waste Applied Repl / Cost Unit / Cost Quantity / Unit Description Operation Interior SFSW= SFW = 313.60SFLW = 68.808.60 X 11.00 X 8.00 SFC = 94.60MASTER CLOSET AREA Perimeter = 39.20 SFR = 408.2088.00 87.03 0.92 JOIST, CEILING BAKING SODA SPR 94.60 LFF 1.671 Remove 37.63 0.12 313.60 SFW WALL STUD, 2"x4" COMPLETE CLE 1.672 Remove 30.27 0.32 94.60 SFL CLEAN & SEAL FRAMING CEILING 1,673 Special 100.35 0.32 CLEAN & SEAL FRAMING WALL 313.60 SFL 1,674 Special 49.19 94.60 SFC 0.52 DRYWALL CEIL 1.675 Remove 133.83 1.30 94.60 SFC DRYWALL CEIL 1,676 Replace 55.81 0.59 94.60 SFC CEILING, 2 COATS + PRIME 1,677 Paint 18.92 0.20 94.60 SFC INSUL CEIL BATT, FOIL FC,9" 1.678 Remove 101.22 1.07 94.60 SFC INSUL, CEIL, BATT, FOIL FC,9" 1,679 Replace 94.08 0.30 313.60 SFW DRYWALL WALL 1,680 Remove 403.24 1.22 313.60 SFW DRYWALL WALL -1,681 Replace 59.00 0.59 100.00 SFW 1,682 Paint DRYWALL WALL 13.33 0.34 39.20 LFW WALLPAPER BORDER 1,683 Remove 56.19 1.34 39.20 LFW WALLPAPER BORDER 4,684 Replace 87.58 0.41 213.60 SFW WALLPAPER, EXCELLENT 1,685 Remove 314.85 1.33 213,60 SFW WALLPAPER, EXCELLENT 1,686 Replace 38.45 0.18 213.60 SFW SIZE WALLS 1,687 Special 9.80 0.25 39.20 LFW BASE, COLONIAL 1,688 Remove 200.87 4.79 39.20 LFW BASE, COLONIAL 1,689 Replace 25.87 0.66 39.20 LFW BASE, COLONIAL 1,690 Paint 1.62 0.27 6,00 LFW MOLDING, COVE, 1 3/4" 1,691 Remove 14.17 2.28 6,00 LFW MOLDING, COVE, 1 3/4* 1,692 Replace 4.20 0.70 6.00 LFW MOLDING, COVE, 1 3/4" 1,693 Paint 2.10 0.35 6.00 LFW VALANCE TRIM 1,694 Remove 46.50 7.75 6.00 LFW VALANCE TRIM 1,695 Replace 4.02 0.67 6.00 LFW 1.696 Paint VALANCE TRIM 74.56 9.32 8.00 EA DOOR TRIM SET, CUSTOM i,697 Remove 654.97 80.79 DOOR TRIM SET, CUSTOM 8.00 EA -1,698 Replace 177.12 22.14 8.00 EA DOOR TRIM SET, CUSTOM 1,699 Paint 52,40 5,24 10.00 EA DOOR. 1,700 Clean 351.60 35.16 10.00 EA

5.00 EA

94.60 SFF

94.60 SF

94.60 EA

10.51 SYF

10.51 SYF

1.00 EA

1.00 EA

3.00 EA

DOOR

DOOR ONLY, INT, 6 PANEL

REGISTER, HEAT, 12" X 5"

REGISTER, HEAT, 12" X 5"

WIRING, RESIDENCE

WIRING, RESIDENCE

FLOOR PREP, RESCREW FLOOR

CARPET & PAD, EXCELLENT (SY)

CARPET & PAD, EXCELLENT (SY)

RECEPTACLE, DUPLEX/SWITCH

1.701 Paint

1,703 Special

1,704 Remove

1,705 Replace

1,706 Remove

-1,707 Replace

1,708 Replace

1,710 Remove

1,709 Paint

1,702 Rem/Reset

289.45

19.87

260.15

21.76

447.44

22.59

3.55

12.96

9.46

57.89

0.21

0.10

2.75

2.07

33.55

22.59

3.55

4.32

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

Exempt from Overhead, Profit or Taxes Overrides

Page

44

~ = Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
,711 Replace	RECEPTACLE, DUPLEX/SWITCH	3.00 EA	22.00	66.00
,711 Remove	RECEPTACLE, G.F.I.	1.00 EA	4.32	4.32
,713 Replace	RECEPTACLE, G.F.I.	1.00 EA	50.25	50.25
.714 Remove	CEILING FIXTURE, GOOD	2.00 EA	9.35	18.70
,715 Replace	CEILING FIXTURE, GOOD	2.00 EA	104.31	208.62
,716 Remove	VANITY STRIP LIGHT,MIR,3LT	1.00 EA	9.34	9,34
717 Replace	VANITY STRIP LIGHT, MIR, 3LT	1.00 EA	99,99	99.99
,718 Rem/Reset		18.00 SF	3.40 .	61.20
719 Clean	MIRROR WALL, PLATE GLASS, ""	18,00 SF	0.40	7.20
,719 Cican ,720 Remove	ACCESSORY, BATHROOM, GD	1.00 EA	6.78	6.78
1,720 Regiace	ACCESSORY, BATHROOM, GD	1.00 EA	21.81	21.81
1,721 Replace	CABINET, BASE, EXCELLENT	6.00 LFW	8.47	50.82
1,722 Remove	CABINET, BASE, EXCELLENT	6.00 LFW	157.71	946.26
1,724 Remove	COUNTERTOP CORIAN SITE BUILT	6.00 LF	1.39	8.34
1,725 Replace	COUNTERTOP CORIAN SITE BUILT		1,200.00	1,200.00
1,726 Remove	SINKBWL, VG	1.00 EA	27.11	27.11
1,727 Replace	SINKBWL, VG	1.00 EA	437.88	437.88
1.728 Remove	FAUCET, BATH, VG	1 00 EA	22.15	22.15
1,729 Replace	FAUCET, BATH, VG	1.00 EA	94.00	94.00
1.730 Remove	SHELF, 1" x 10"	27.00 LFW	0.90	24.30
1,731 Replace	SHELF, 1" x 10"	27.00 LFW	6.54	179.60
1,732 Paint	SHELF. 1" x 10"	27.00 LFW	1.37	36.99
1,733 Remove	CLOSET POLE, 3 1/2"	27.00 LF	0.31	8.37
4,734 Replace	CLOSET POLE, 3 1/2"	27.00 LF	3,10	85.16
1,735 Paint	CLOSET POLE, 3 1/2"	27.00 LF	0.87	23.49

MASTERBATH	9.00 X 13.30 SFLW= 72.00	X 8.00 + offset SFSW= 106.40	2.70 X 6.50 SFR = 598.05	SFC = 137.25
1,736 Remove	JOIST, CEILING BAKING SODA SPR	137.25 LFF	0.92	126.27
1,737 Remove	WALL STUD, 2"x4" COMPLETE CLF	392.00 SFW	0.12	47.04
1,738 Special	CLEAN & SEAL FRAMING CEILING	119.70 SFL	0.32	38.30
1,739 Special	CLEAN & SEAL FRAMING WALL	392.00 SFL	0.32	125.44
1,740 Remove	DRYWALL CEIL	137.25 SFC	0.52	71.37
4,741 Replace	DRYWALL CEIL	137.25 SFC	1.30	189.27
1,742 Paint	CEILING, 2 COATS + PRIME	137.25 SFC	0.59	80.98
i,743 Remove	INSUL,CEIL,BATT,FOIL FC,9"	137.25 SFC	0.20	27.45
1,744 Replace	INSUL,CEIL,BATT,FOIL FC,9"	137.25 SFC	1.07	146.86
1,745 Remove	DRYWALL WALL	460.80 SFW	0.30	138.24
1,746 Replace	DRYWALL WALL	460.80 SFW	1.22	582.82
1,747 Paint	DRYWALL WALL	230.00 SFW	0.59	135.70
1,748 Remove	WALLPAPER BORDER	115.20 LFW	0.34	39.17
1,749 Replace	WALLPAPER BORDER	115.20 LFW	1.34	159.90

Claim Number:

* = Min. Charge

Insured:

PA123 BORDEN

Exempt from Overhead, Profit or Taxes)verrides

Page

45

<u>~</u> =	Waste Applied					
	Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
	1,750 Remove	BASE, CERAMITILE, THIN SET	57.60 LFW	0.68	39.17	
	~1,751 Replace	BASE, CERAM TILE, THIN SET	57.60 LFW	11.00	639.96	
	1,752 Remove	CERAMIC WALLS, THIN SET, 4"	120.00 SFW	1.47	176.40	
	1,753 Replace	CERAMIC WALLS, THIN SET, 4"	120.00 SFW	8.95	1,107.41	
	1,754 Replace	CERAMIC FIXTURE (EA)	2.00 EA	20.45	40.90	
	1,755 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32	•
	4,756 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	89.44	٠
	1,757 Paint	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14	
	1,758 Clean	DOOR,	1.00 EA	5.24	5.24	
	1,759 Paint	DOOR	1.00 EA	35.16	35.16	•
	1,760 Rem/Reset	DOOR ONLY, INT, 6 PANEL	1.00 EA	57.89	57.89	
	1,761 Remove	CASEMENT ANDERSON VYN/WOO	2,00 EA	21.69	43.38	
	1,762 Replace	CASEMENT ANDERSON VYN/WOO	2.00 EÁ	695.00	1,390.00	
	1,763 Remove	WINDOW TRIM SET, CUSTOM	2.00 EA	10.72	21.44	
	4,764 Replace	WINDOW TRIM SET, CUSTOM	2.00 EA	81.04	163.42	
	1,765 Paint	WINDOW TRIM SET, CUSTOM	2.00 EA	31.26	62.52	
	1,766 Paint	WINDOW, CASEMENT, LG	2.00 EA	37,66	75.32	
	1,767 Remove	WIRING, RESIDENCE	137.25 SF	0.10	13.73	
• •	1,768 Replace	WIRING, RESIDENCE	137.25 EA	2.75	377.44	
	1,769 Replace	REGISTER, HEAT, 12" X 5"	1.00 EA	22.59	22.59	
	1,770 Paint	REGISTER, HEAT, 12" X 5"	1.00 EA	3.55	3,55	
	1,771 Remove	RECEPTACLE, DUPLEX/SWITCH	3.00 EA	4.32	12.96	
	1,772 Replace	RECEPTACLE, DUPLEX/SWITCH	3.00 EA	22.00	66.00	
	1,773 Remove	CEILING FIXTURE, GOOD	1.00 EA	9.35	9.35	
	1,774 Replace	CEILING FIXTURE, GOOD	1.00 EA	104.31	104.31	
	1,775 Remove	RECEPTACLE, G.F.I.	1.00 ·EA	4,32	4.32	
	1,776 Replace	RECEPTACLE, G.F.I.	1.00 EA	50,25	50.25	
	1,777 Remove	SWITCH, DIMMER TYPE	1.00 EA	4.76	4.76	
	i,778 Replace	SWITCH, DIMMER TYPE	1.00 EA	65.71	65.71	
-	1,779 Remove	ACCESSORY, BATHROOM, GD	1.00 EA	6.78	6.78	
	1,780 Replace	ACCESSORY, BATHROOM, GD	1.00 EA	21.81	21.81	
	t,781 Replace	FIXTURE, INCNDSCENT, RECESS	3.00 EA	108.00	324.00	
	1,782 Remove	EXHAUST FAN WITH LIGHT, EX	1.00 EA	12.32	12.32	
	1,783 Replace	EXHAUST FAN WITH LIGHT, EX	1.00 EA	201.65	201.65	
	1,784 Remove	CERAMIC FLOOR, THIN SET, 1*X2	" 137.25 SFF	1.18	161.95	
	-1,785 Replace	CERAMIC FLOOR, THIN SET, 1"X2	" 137.25 SFF	11.00	1,563.11	
	1,786 Remove	UNDERLAYMENT, LAUAN, 1/4"	137.25 SFF	0.49	67,25	
	-1,787 Replace	UNDERLAYMENT, LAUAN, 1/4"	137.25 SFF	0.84	121.55	
	1,788 Remove	SHOWER DOORS	1.00 EA	7.13	7.13	
	1,789 Replace	SHOWER DOORS	1.00 EA	487.00	487.00	
	1,790 Remove	BATH TUB, FIBERGLASS JACUZZI	1.00 EA	45.18	45.18	
1	1,791 Replace	BATH TUB, FIBERGLASS JACUZZI	1.00 EA	1,400.00	1,400.00	
٧.	1,792 Remove	FAUCET, BATH, EX	1.00 EA	22.15	22.15	
	1,793 Replace	FAUCET, BATH, EX	1.00 EA	349.00	349.00	

Ca	se 1:04-cv-00175-SJM	Document 24-	4 Filed 12/16/2009	5 Page 17 of 50
Building Repair Estim	ate	Clai	m Number: PA123	
- -	all.	Insu	red: BORD	EN
* = Min. Charge	rhead. Profit or Taxes			
	mead, Fight of Taxes			Page 46
Overrides				
~= Waste Applied				
Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
Interior				
BATHROOM C	LOSET 2.90 X 2.70 21.60 SFR	X 8.00 SFC = 97.43 Perim	= 7.83	SFLW= 23.20 SFSW=
	TOTAL OF THE BANKIC SOLV SPE	7.83 LFF	0.92	7.20
1,794 Remove	JOIST, CEILING BAKING SODA SPI	•	0.12	10.75
1,795 Remove	WALL STUD, 2"x4" COMPLETE CLI CLEAN & SEAL FRAMING CEILING		0.32	2.51
1,796 Special	CLEAN & SEAL FRAMING WALL	89.60 SFL	0.32	28.67
1,797 Special		7.83 SFC	0.52	4.07
1,798 Remove	DRYWALL CEIL	7.83 SFC	1.30	21.03
1,799 Replace	DRYWALL CEIL CEILING, 2 COATS + PRIME	7.83 SFC	0.59	4.62
1,800 Paint	INSUL, CEIL, BATT, FOIL FC, 9"	7.83 SFC	0.20	1.57
1,801 Remove	INSUL, CEIL, BATT, FOIL FC,9"	7.83 SFC	1.07	8.38
1,802 Replace	DRYWALL WALL	89.60 SFW	0.30	26.88
(,803 Remove	DRYWALL WALL DRYWALL WALL	89.60 SFW	1.22	129.96
1,804 Replace	DRYWALL WALL	89.60 SFW	0.59	52.86
1,805 Paint	SHELF, 1" x 10"	13.50 LFW	0.90	12.15
1,806 Remove	SHELF, 1" x 10"	13.50 LFW	6.54	89.81
-1,807 Replace	SHELF, 1" x 10"	13.50 LFW	1.37	18.50
t,809 Remove	CERAMIC FLOOR, THIN SET, I"X		1.18	9.24
-1,810 Replace	CERAMIC FLOOR, THIN SET, 1"X		11.00	139.49
1.811 Remove	BASE, COLONIAL	11.20 LFW	0.25	2.80
-1,812 Replace	BASE, COLONIAL	11.20 LFW	4.79	66.75
1,813 Paint	BASE, COLONIAL	11.20 LFW	0.66	7.39
1,814 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32
1,815 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	84.39
i,816 Paint	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14
Interior				
	IAIN HALL END 1.40 X 2.2 17.60 SF	0 X 8.00 SF FR = 60.68 Per	C = 3.08 SFW = 57.60 imeter = 7.20	SFLW=11.20 SFSW=
	,	DD 200177	0.92	2.83
1,817 Remove	JOIST, CEILING BAKING SODA S		- 0.12	. 6.91
1,818 Remove	WALL STUD, 2"x4" COMPLETE C			0.99
i,819 Special	CLEAN & SEAL FRAMING CEILI		0.32	18.43
1,820 Special	CLEAN & SEAL FRAMING WALL		0.32	1.60
1,821 Remove	DRYWALL CEIL	3.08 SFC	0.52	14.85
-1,822 Replace	DRYWALL CEIL	3.08 SFC	1.30	1.82
(1,823 Paint	CEILING, 2 COATS + PRIME	3.08 SFC	0.59	0.62
1,824 Remove	INSUL,CEIL,BATT,FOIL FC,9"	3.08 SFC	0.20 1.07	3.30
1,825 Replace	INSUL,CEIL,BATT,FOIL FC,9"	3.08 SFC		17.28
1 226 Demove	DRYWALL WALL	57.60 SFW	U.JU	17.20

57.60 SFW

57.60 SFW

DRYWALL WALL

DRYWALL WALL

1,826 Remove

-1,827 Replace

90.92

1.22

Claim Number:

.....

* - Min. Charge

Insured:

PA123 BORDEN

empt from Overhead. Profit or Taxes Overrides

Page

47

Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
	The state of the s	57,60 SFW	0.59	33.98
1,828 Paint	DRYWALL WALL	7.20 LFW	0.90	6.48
1,829 Remove	SHELF, 1° x 10"	7.20 LFW	6,54	48.43
ન,830 Replace	SHELF, 1" x 10"		1.37	9.86
1,831 Paint	SHELF, 1" x 10"	7.20 LFW	2.07	0.70
1,832 Remove	CARPET & PAD, EXCELLENT (SY)		33.55	106.24
1,833 Replace	CARPET & PAD, EXCELLENT (SY)	0.34 SYF		1.80
1,834 Remove	BASE, COLONIAL	7.20 LFW	0.25	47.59
1,835 Replace	BASE, COLONIAL	7.20 LFW	4.79	
1,836 Paint	BASE, COLONIAL	7.20 LFW	0.66	4.75
1,837 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32
•••	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	84.39
1,838 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14

BEDROOM REA	AR 13.50 X 15.00 SFLW= 108.00	X 8.00 + offse SFSW= 120.00	2.40 X 8.30 SFR = 811.22	SFC = 222.42
L.840 Remove	JOIST, CEILING BAKING SODA SPR	222.42 LFF	0.92	204.63
	WALL STUD, 2"x4" COMPLETE CLE	588.80 SFW	0.12	70.66
***************************************	CLEAN & SEAL FRAMING CEILING	202.50 SFL	0.32	64.80
(,842 Special (,843 Special	CLEAN & SEAL FRAMING WALL	588.80 SFL	0.32	188.42
1,843 Special	DRYWALL CEIL	222.42 SFC	0.52	115.66
~1,844 Replace	DRYWALL CEIL	222,42 SFC	1.30	299.99
1,846 Paint	DRYWALL CEIL.,5/8"FIRE RES	222.42 SFC	0.59	131.23
1,846 Faun 1,847 Remove	INSUL,CEIL,BATT,FOIL FC,9"	222.42 SFC	0.20	44.48
1,848 Replace	INSUL,CEIL,BATT,FOIL FC,9"	222,42 SFC	1.07	237.99
1,849 Remove	DRYWALL WALL	588.80 SFW	0.30	176.64
-1,850 Replace	DRYWALL WALL	588.80 SFW	1.22	738.98
1,851 Paint	DRYWALL WALL-FAUX 3 COAT AF	588.80 SFW	2.00	1,177.60
1,852 Special	SIZE WALLS	588.80 SFW	0.21	123.65
1,853 Remove	WALLPAPER, EXCELLENT	588.80 SFW	0.41	241.41
-1,854 Replace	WALLPAPER, EXCELLENT	588.80 SFW	1.68	1.026.97
i.855 Remove	WALLPAPER BORDER	73.60 LFW	0.34	25.02
-1,856 Replace	WALLPAPER BORDER	73.60 LFW	1.34	99.57
1,857 Remove	BATT INSULATION - WALL R19	298.00 SFW	0.19	56.62
1,858 Replace	BATT INSULATION - WALL R19	298.00 SFW	0.82	244.36
1.859 Remove	BASE, COLONIAL	73.60 LFW	0.25	18.40
-1,860 Replace	BASE, COLONIAL	73.60 LFW	4.79	365.65
1,861 Paint	BASE, COLONIAL	73.60 LFW	0.66	48.58
1.862 Remove	DOOR TRIM SET, CUSTOM	5.50 EA	9.32	51.26
-1,863 Replace	DOOR TRIM SET, CUSTOM	5.50 EA	80.79	450.11
1.864 Paint	DOOR TRIM SET, CUSTOM	5.50 EA	22.14	121.77
1,865 Clean	DOOR,	2.00 EA	5.24	10.48
:,866 Paint	DOOR	2.00 EA	35.16	70.32

Claim Number:

PA123

* - Min. Charge

Insured:

BORDEN

Overrides

Exempt from Overhead, Profit or Taxes

Page

48

~ = Waste Applied

	Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
		DOOR ONLY, INT, 6 PANEL	2.00 EA	57.89	115.78
		OPENING, CASED	1.00 EA	10.72	10.72
	1,868 Remove	OPENING, CASED	1,00 EA	82.36	85.36
	1,869 Replace	OPENING, CASED	1.00 EA	. 30,99	30.99
		WINDOW TRIM SET, CUSTOM	1.00 EA	1,50	1.50
	1.871 Remove	WINDOW TRIM SET, CUSTOM	1,00 EA	81.04	82.60
	1,872 Replace	WINDOW TRIM SET, CUSTOM	1.00 EA	31.26	31.26
	1,873 Paint	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA	13.55	13.55
	1,874 Remove	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA	1.999.00	1.999.00
	1,875 Replace	DOOR, EXT, WOOD, PH, FRENCH	1.00 EA	36.04	36.04
	1,876 Paint	WINDOW TRIM SET, CUSTOM	1.00 EA	31.26	31.26
	1,877 Paint	OAK FLOOR, 2 1/4", CLEAR	222.42 SFF	0.64	142.35
	1,878 Remove	OAK FLOOR, 2 1/4", CLEAR	222.42 SFF	7.90	1,757.12
	1,879 Replace	SAND AND FINISH FLOORS	222.42 SFF	3.15	700.62
	1,880 Special	CASEMENT ANDERSON VYN/WOX		21.69	21.69
	1,881 Remove	CASEMENT ANDERSON VYN/WO	-	695.00	695.00
	1,882 Replace	WINDOW, CASEMENT, LG	1.00 EA	37.66	37.66
	1,883 Paint	FLOOR PREP, RESCREW FLOOR	222,42 SFF	0.21	46.71
	1,884 Special	WIRING, RESIDENCE	222.42 SF	0.10	22.24
ì	1,885 Remove 1,886 Replace	WIRING, RESIDENCE	222.42 EA	2.75	611.65
•	-	REGISTER, HEAT, 12" X 5"	3.00 EA	22.59	67.77
	1,887 Replace	REGISTER, HEAT, 12" X 5"	3.00 EA	3.55	10.65
	;,888 Paint	SMOKE DETECTOR	1.00 EA	9.35	9.35
	1,889 Remove	SMOKE DETECTOR	1.00 EA	54.53	54.53
	1,890 Replace 1,891 Remove	RECEPTACLE, DUPLEX/SWITCH	8.00 EA	4,32	34.56
	1,891 Remove	RECEPTACLE, DUPLEX/SWITCH	8.00 EA	22.00	176,00
	1,892 Replace	OUTLET, TELEPHONE/CABEL	3.00 EA	4.32	12.96
	1,893 Reniove	OUTLET, TELEPHONE/CABEL	3.00 EA	20.35	61.05
	1,894 Replace	DRAPERIES, REMOVE/RESET	2.00 EA	31.49	62,98
	1,895 Special	SWITCH, DIMMER TYPE	1.00 EA	4.76	4.76
	1,897 Replace		1.00 EA	65.71	65.71
	1,897 Replace	CHANDELIER, VERY GOOD	1,00 EA	19.36	19.36
	1,898 Remove	CHANDELIER, VERY GOOD	1.00 EA	487.40	487.40
	1,899 Replace	FLUOR. FIXTURE, SURFACE, 4x1	1.00 EA	7.68	7.68
	1,900 Remove	FLUOR. FIXTURE, SURFACE, 4x1	1.00 EA	108.13	108.13

HALL BATHRO		X 8.00 = 262.40	SFC = 44.80 Perimeter = 27	SFW = 217.60 .20	SFLW= 64.00	SFSW=
SMOKE FOI	LOWED PIPE CHASES UP					
ı 902 Remove	JOIST, CEILING BAKING SODA SPR	44.80	LFF	0.92	41.22	
i.903 Remove	WALL STUD, 2"x4" COMPLETE CLE	217.60	SFW	0.12	26.11	
1,904 Special	CLEAN & SEAL FRAMING CEILING	44.80	SFL	0.32	14.34	•
,905 Special	CLEAN & SEAL FRAMING WALL	217.60	SFL	0.32	69.63	

* = Min. Charge

Claim Number: Insured:

PA123 BORDEN

Exempt from Overhead, Profit or Taxes

Overrides

Page

49

~	. = Waste Applied	

	Operation	Description (Quantity / Unit	Unit / Cost	Repl / Cost
Ļ		DRYWALL CEIL	44.80 SFC	0.52	23.30
	17	DRYWALL CEIL	44,80 SFC	1.22	65.50
	-4	TEXTURE CEILING	44,80 SFC	0.77	34,50
	the management	INSUL, CEIL, BATT, FOIL FC,9"	44.80 SFC	0.20	8.96
	-1	INSUL, CEIL, BATT, FOIL FC,9"	44.80 SFC	1.07	47.94
	•	DRYWALL WALL	217.60 SFW	0.30	65.28
		DRYWALL WALL	217.60 SFW	1.22	286,12
	-,	SIZE WALLS	217.60 SFW	0.21	45.70
	1,913 Special	WALLPAPER, EXCELLENT	217.60 SFW	0.41	89.22
	1,914 Remove	WALLPAPER, EXCELLENT	217.60 SFW	1.68	388.97
	1,915 Replace	WALLPAPER BORDER	27.20 LFW	0.34	9.25
	1,916 Remove	WALLPAPER BORDER	27.20 LFW	1.34	37.40
	1,917 Replace	BATT INSULATION - WALL RIP	44.80 SFW	0.19	8.51
	1,918 Remove	BATT INSULATION - WALL R19	44.80 SFW	0.62	27.78
	1,919 Replace	BASE, COLONIAL, 3 1/2*	19.00 LFW	0.25	4.75
	4,920 Remove	BASE, COLONIAL, 3 1/2"	19.00 LFW	2.56	50.71
	1,921 Replace	BASE, COLONIAL, 3 1/2"	19.00 LFW	0.65	12.35
	1,921 Patric 1,923 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	9.32
	1,923 Reniove	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	87.64
	1,924 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14
•	1,923 Famil		1.00 EA	19.34	19.34
	1,927 Clean	REGISTER, HEAT, 12" X 5"	1.00 EA	3.18	3.18
	1,928 Paint	REGISTER, HEAT, 12" X 5"	1.00 EA	3.55	3.55
	1,929 Remove	CERAMIC FLOOR, THIN SET, 12"XI	44.80 SFF	0.71	31.81
	1,930 Replace	CERAMIC FLOOR, THIN SET, 12"X		11.00	519.04
	1,931 Remove	UNDERLAYMENT, LAUAN, 1/4"	44.80 SFF	0.49	21.95
	-1,932 Replace	UNDERLAYMENT, LAUAN, 1/4"	44.80 SFF	0.84	38.75
	1,933 Remove	WIRING, RESIDENCE	44.80 SF	0.10	4.48
	1.934 Replace	WIRING, RESIDENCE	44.80 EA	2.75	123.20
	1,935 Remove	RECEPTACLE, DUPLEX/SWITCH	2.00 EA	4.32	8.64
	1,936 Replace	RECEPTACLE, DUPLEX/SWITCH	2.00 EA	22.00	44.00
	1,937 Remove	RECEPTACLE, G.F.L.	1.00 EA	4.32	4.32
	1,938 Replace	RECEPTACLE, G.F.L	1.00 EA	50.25	50.25
	1,939 Remove	SWITCH, DIMMER TYPE	1.00 EA	4.76	4.76
	1,940 Replace	SWITCH, DIMMER TYPE	1.00 EA	65.71	65.71
	1,941 Remove	EXHAUST FAN WITH LIGHT VENT	1.00 EA	12.32	12.32
	1,942 Replace	EXHAUST FAN WITH LIGHT VENT		201.65	201.65
		CHANDELIER, VERY GOOD	1.00 EA	172.59	172.59
	1,944 Clean	CHANDELIER, VERY GOOD	1.00 EA	18.30	18.30
	1.945 Remove	FLEX STL DUCT W/VNYL CT 4"	12.00 LF	0.52	6.24
	-1,946 Replace	FLEX STL DUCT W/VNYL CT 4"	12.00 LF	2.84	34.38
6	1,947 Remove	VANITY, 36" MAHOGONY	1.00 EA	12.15	12.15
_[i,948 Replace	VANITY, 36" MAHOGONY	1.00 EA	575.00	575.00
	1,949 Paint	VANITY, 36" MAHOGONY	1.00 LF	24.51	24.51
	1,950 Replace	LAV, CULT MARB, DBL BWL, 37"	1.00 EA	172.22	172.22
	1,951 Replace	FAUCET, BATH, EX	1.00 EA	141.79	141.79

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

O O

Exempt from Overhead, Profit or Taxes

Overrides

Page

50

- = Waste Applied

 Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
 1,952 Rem/Reset	WATER CLOSET, 2 PIECE, EX	1.00 EA	94,55	94.55	
t.953 Clean	WATER CLOSET, 2 PIECE, EX	1.00 EA	8,55	8.55	
1,954 Replace	TOILET SEAT	1.00 EA	56,93	56.93	
1,955 Replace	MEDICINE CABINET	1.00 EA	186.00	186.00	
1,956 Replace	ACCESSORY, BATHROOM, BRASS	3.00 EA	78.00	234.00	
1,957 Rem/Reset		1.00 EA	141.00	141.00	
1.958 Clean	BATH TUB, CAST IRON ENAMEL	1.00 EA	12.40	12.40	
1.959 Rem/Reset		1.00 EA	28.14	28.14	
1,960 Remove	CERAMIC FLOOR, THIN SET, 1"X2"	44.80 SFF	1.18	52.86	
1,961 Replace	CERAMIC FLOOR, THIN SET, 1"X2"		11.00	546.16	
1,962 Remove	UNDERLAYMENT, LAUAN, 1/4"	44.80 SFF	0.49	21.95	
1,963 Replace	UNDERLAYMENT, LAUAN, 1/4"	44.80 SFF	0.84	43.89	
•		*			

Interior

ATTIC

 $50.00 \ X \ 30.00 \ X \ 8.00 \ SFC = 1,500.00 \ SFW = 1,280.00 \ SFLW = 400.00$

FLOORSYSTEM HAS ADDITIONAL SLEEPERS IN SOME AREAS WITH A FLOOR BUILD UP. GABLES ARE INSULATED. RAFTERS COMPLETE REQUIRED FOR WALLS BELOW ARE BEING REMOVED.

	-		-		
1,964 Remove	BATT INSULATION - WALL R19	640.00 SFW	0.19	121.60	
1,965 Replace	BATT INSULATION - WALL R19	640.00 SFW	0.82	524.80	
1,966 Remove	CEILING FIXTURE, PORCELAIN	3,00 EA	8.47	25.41	
1.967 Replace	CEILING FIXTURE, PORCELAIN	3.00 EA	64.98	194.94	
1,968 Remove	RAFTERS COMPLETE	1,500.00 LFF	0.57	855.00	
1,969 Remove	RAFTERS COMPLETE	1,500.00 LFF	3.90	5,850.00	
1,970 Remove	JOIST, FLOOR PARTIAL	368.00 LFF	0.57	209.76	
1,971 Replace	JOIST FLOOR PARTIAL	368,00 LFF	2.14	823.84	
1,972 Remove	SHEATHING FLOOR, PLYWOOD	368.00 SFC	0.47	172.96	
1,973 Replace	SHEATHING FLOOR, PLYWOOD	368.00 SFC	1.87	724.96	
1,974 Remove	WALL STUD, 2"x4" COMPLETE	448.00 SFW	0.72	322.56	
1,975 Replace	WALL STUD, 2"x4" COMPLETE	448.00 SFW	1.82	815.36	
i,976 Remove	WIRING, RESIDENCE	400.00 SF	0.10	40.00	
1,977 Replace	WIRING, RESIDENCE	400.00 EA	2.75	1,100.00	
1,978 Remove	FIBERBOARD INSULATION	25,00 SF	0.17	4.25	
1,979 Replace	FIBERBOARD INSULATION	25.00 SF	1.30	33.50	
1,980 Remove	DOOR TRIM SET, 2 1/2", 1SIDE	1.00 EA	4.66	4.66	
1,981 Replace	DOOR TRIM SET,2 1/2",1SIDE	1.00 EA	41.20	41.76	
1,982 Remove	VENT STACK, PVC PIPE	20.00 LF	1.80	36.00	
1,983 Replace	VENT STACK, PVC PIPE	20.00 LF	8.94	180.13	

PA123 Claim Number. **Building Repair Estimate** BORDEN Insured: * = Min. Charge Exempt from Overhead, Profit or Taxes 51 Page Overrides = Waste Applied Unit / Cost Repl / Cost Quantity / Unit Description Operation SFW = 0.00SFLW=0.00SFSW=0.00SFC = 0.000.00 X 0.00 X 0.00 ROOFING SFR = 0.00Perimeter = 0.00ENTIRE ROOF NEEDS REPLACEMENT. ROOF ON MAIN HOUSE NEEDS SHEATHING CLEANED FROM UNDERNEATH. 34.90 1,703.12 48.80 SQC ASPHALT SHINGLE, 3TB, 30YR 1,984 Remove 1,167.78 48.80 SQC 23.93 1,985 Special STEEP CHARGE 8,552,95 54.00 SOC 155.00 ASPHALT SHINGLE, 3TB, 30YR 1,986 Replace 1,167.78 48.80 SQC 23.93 STEEP CHARGE 1,987 Special 273.24 10,12 27.00 SQC SECOND STORY CHARGE 1,988 Special 38.18 171.05 4.48 SQC MEMBRANE ROOF, SINGLE PLY 1,989 Remove 4.48 SQC 1,209.60 270.00 MEMBRANE ROOF, SINGLE PLY 1,990 Replace 448.00 SFC 0.48 215.04 SHEATHING, ROOF, 5/8 RUBBER A 1,991 Remove 489.75 448.00 SFC 1.05 SHEATHING, ROOF, OSB, 5/8" 1,992 Replace 713.76 0.48 SHEATHING, ROOF 5/8 MAIN ATTIC 1,487.00 SFC i,993 Remove SHEATHING, ROOF, 5/8 MAIN ATT 1,487.00 SFC 1.05 1,625.59 1,994 Replace 31.90 127.60 4.00 LFF RAFTERS BACK SLOPE 1,995 Remove 270.00 0.45 ICE/WATER SHIELD 600.00 LF 1,996 Remove 2.06 1,236.00 600,00 LF ICE/WATER SHIELD 1,997 Replace 71.86 5.00 EA 14.09 FLASHING-VENT PIPES 1,998 Replace 275.16 FLASHING, DOUBLE CHIMNEY 275.00 1.00 SFL 1,999 Replace 100.00 LF 0.53 53.00 2,000 Remove RIDGE, ROLL - 90# 107.60 1.04 100.00 LF 2,001 Replace RIDGE, ROLL - 90# Interior FRONT ELEVATION-MAIN HOUS52.00 X 1.00 X 16.00 SFW = 1,696.00SFLW= 832.00 SFC = 52.00SFSW= 16.00 Perimeter = 106.00SFR = 1,748.001,138.80 1,002 Remove SIDING, VINYL, DOUBLE, 4* 1,560,00 SFW 0.73 3,167.81 1.92 SIDING, VINYL, DOUBLE, 4" 1,569.00 SFW 2,003 Replace 0.37 627.52 2,004 Remove SCAFFOLD, STEEL, 1 USE, 20'H 1,696.00 SFW 0.50 848.00 1,696.00 SFW 2,005 Replace SCAFFOLD, STEEL, 1 USE, 20'H 249.60 VAPOR BARRIER SHELTER WRAP 1,560.00 SFW 0.16 1,006 Replace 0.71 173.24 GUTTERS/DOWNSPOUT, ALUMINU 244.00 LF 1,007 Remove GUTTERS/DOWNSPOUT, ALUMINU 244.00 LF 6.26 1,527,44 1,008 Replace 72,00 LFW 0.51 36.72 1,009 Remove FASCIA, 1" X 6" 246.85 FASCIA, 1" X 6" 72.00 LFW 3.40 -1,010 Replace 162.74 206.00 LFW 0.79 1,011 Paint FASCIA, 1" X 6" 26.00 SF 0.49 12.74 SOFFIT, PLYWOOD, 1/2" 1,012 Remove 26.00 SF 56.99 SOFFIT, PLYWOOD, 1/2" 2.16 -1,013 Replace 1,014 Paint SOFFIT, PLYWOOD, 1/2" 130.20 SF 1.02 132.80 12.90 1,015 Remove MOLDING, CROWN, 4 5/8" 30.00 LFW 0.43 86.26 MOLDING, CROWN, 4 5/8" 30.00 LFW 2.76 -1,016 Replace 30.00 LFW 0.70 21.00 MOLDING, CROWN, 4 5/8" 2,017 Paint

Claim Number: Insured:

PA123 BORDEN

* = Min. Charge

xempt from Overhead. Profit or Taxes

Overrides

Page

52

~ = Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
	-	1.00 LFF	55,00	55.03
-,0 - 0 F	WALL STUD, 2" x 6"-REPAIR	104.00 SFW	0.28	29.12
.,	T & G PINE CEILING	104.00 SFW	3.06	322.92
1,020 Replace	T & G PINE CEILING	104.00 SFW	0.59	61.36
2,021 Paint	PINE CEILING	104.00 SFC	0.19	19.76
1,022 Remove	INSUL, CEIL, BATT, UNFACED, 9"	104.00 SFC	0.65	67.60
1,023 Replace	INSUL,CEIL,BATT,UNFACED,9"	5.00 LFW	25.00	125.00
2,024 Paint	POST	the state of the s	0.47	99.26
2025 Remove	SHEATHING WALL, PLYWOOD	211.20 SFC	1.87	416.07
1,026 Replace	SHEATHING WALL, PLYWOOD	211.20 SFC	1.72	1,290.00
1,027 Remove	BRICK VENEER, WALL, 4"	750.00 SFW	10,46	7,943.63
2,028 Replace	BRICK VENEER, WALL, 4"	750.00 SFW	0.70	72.80
1,029 Special	ACID WASH MASONRY SLAB	104.00 SFF	13.55	13.55
2,030 Remove	DOOR, EXT, METAL, PH, SPECIAL	1.00 EA	925.00	925.00
2,031 Replace	DOOR, EXT, METAL, PH, SPECIAL	1.00 EA	48.68	48.68
1,032 Paint	DOOR, EXT, METAL, PH, SPECIAL	1.00 EA	13.55	13.55
2,033 Remove	DOOR, GENERAL LITE	1.00 EA	755.00	755.00
1,034 Replace	DOOR, GENERAL LITE	1.00 EA	755.00 34.91	34.91
1,035 Paint	DOOR, GENERAL LITE	1.00 EA		147.00
2,036 Replace	LOCKSET, EXTERIOR	1.00 EA	147.00	74.40
.037 Replace	DEAD BOLT LOCK	1.00 EA	74.40	9.32
1,038 Remove	DOOR TRIM SET, CUSTOM	1.00 EA	9.32	81.87
1,039 Replace	DOOR TRIM SET, CUSTOM	1.00 EA	80.79	= = :
1,040 Paint	DOOR TRIM SET, CUSTOM	1.00 EA	22.14	22.14
2.041 Remove	CEILING FIXTURE, EXCELLENT	2.00 EA	9.35	18.70
1.042 Replace	CEILING FIXTURE, EXCELLENT	2.00 EA	131.43	262.86
	t SHUTTERS, VINYL, LOUVERED, H	3.00 PR	31.26	93.78
1.044 Clean	SHUTTERS, VINYL, LOUVERED, I	3.00 PR	13.60	40.80

RIGHT ELEVA	TION $1.00 \times 1.00 \times 1.$	(1.00 SFC = 1.00 Perimeter = 4.00	SFW = 4.00	SFLW= 1.00	00
1.045 Remove	SIDING, VINYL, DOUBLE, 4°	445.00 SFW	0.73	324.85	
-2,046 Replace	SIDING, VINYL, DOUBLE, 4"	445.00 SFW	1.92	898.45	
1.047 Remove	SCAFFOLD, STEEL, 1 USE, 20'H	445.00 SFW	0.37	164.65	
1,048 Replace	SCAFFOLD, STEEL, 1 USE, 20'H	445.00 SFW	0.50	222.50	
1.049 Replace	VAPOR BARRIER SHELTER WRAP	445.00 SFW	0.16	71.20	
2,050 Remove	GUTTERS/DOWNSPOUT, ALUMINU	60.00 LF	0.71	42.60	
•	GUTTERS/DOWNSPOUT, ALUMINU	60.00 LF	6.26	375.60	
1,051 Replace	FASCIA, 1" X 6"	77.00 LFW	0.79	60.83	
2,052 Paint		1.00 PR	31.26	31.26	
1,053 Rem/Reset		1.00 PR	13.60	13.60	
2,054 Clean	SHUTTERS, VINYL, LOUVERED, E)	60.00 SF	1.02	61.20	
1,055 Paint 1,056 Clean	SOFFIT, PLYWOOD, 1/2" BRICK VENEER, WALL,4"	260.00 SFW	0.37	96.20	

pair Estimate		Claim Number	5.100	
	04-cv-00175-SJM		ed 12/16/2005	

Building Repair Estim = Min. Charge	ate	Claim Num Insured:	ber: PA123 BORI		
	rhead. Profit or Taxes			Page	53
Operation		Quantity / Unit	Unit / Cost	Repl / Cos	t
2,057 Special	TUCKPOINT BRK/STN 1/4*DEEP (SI	260.00 SF	2.51	652.60)
Interior					
REAR ELEVAT	TION 0.00 X 0.00 $SFR = 0.00$	X 0.00 SFC = 0.00 Perimeter = 0.00	SFW = 0.00	SFLW= 0.00	SFSW= 0.00
	GUTTERS/DOWNSPOUT, ALUMINU	162.00 LF	0.71	135.0	
2.058 Remove	GUTTERS/DOWNSPOUT, ALUMINU		6.26	1,014.1	
1,059 Replace	SIDING, VINYL, DOUBLE, 4"	550.00 SFW	0.73	401.5	
1,060 Remove	SIDING, VINYL, DOUBLE, 4"	550.00 SFW	1.92	1,110.4	
2.062 Remove	SHEATHING, WALL, OSB, 1/2"	162.00 SFW	0,42	68.0	
-1,063 Replace	SHEATHING, WALL, OSB, 1/2"	162.00 SFW	0.86	143.3	
1,064 Remove	1-1/8 T&G	126.00 SFW	0.42	52.9	
,065 Remove	1-1/8 T & G	126.00 SFW	2.48	312.4	
1.066 Paint	PINE CEILING	126.00 SFW	0.59	74.1	
1,067 Remove	TRIM, 1" X 8"	120.00 LFW	0.28	33.0	
~!,068 Replace	TRIM, 1" X 8"	120.00 LFW	3.29	400,1	
1,069 Paint	TRIM, 1* X 8"	120.00 LFW	0.81	97.	
2.070 Remove	PADDLE FAN, GOOD	1.00 EA	28.72	28.	
1,071 Replace	PADDLE FAN, GOOD	1.00 EA	224.28	224.	2 6 35
1,072 Remove	CEILING FIXTURE, EXCELLENT	1.00 EA	9.35	9. 131.	
:,073 Replace	CEILING FIXTURE, EXCELLENT	1.00 EA	131.43	51.	
2,074 Remove	MOLDING, CROWN, 4 5/8"	120,00 LFW	0.43	345.	
~!,075 Replace	MOLDING, CROWN, 4 5/8"	120.00 LFW	2.76	84.	
2,076 Paint	MOLDING, CROWN, 4 5/8"	120.00 LFW	0.70	206.	
1,077 Remove	BRICK VENEER, WALL, 4*	120.00 SFW	1.72	1,270	
-1078 Replace	BRICK VENEER, WALL, 4"	120.00 SFW	10.46		.00
1079 Special	ACID WASH MASONRY SLAB	120.00 SFF	0.70	149	
!,080 Paint	CONCRETE FLOOR, 4"	126.00 SFF	1.19 0.43	178	
2,081 Special	POWER WASH	416.00 SF	0.43		.44
1,082 Paint	TRIM, 6" TO 12", 2 COATS	128.00 LFW	0.73	,,	•••
Interior					
LEFT ELEVA	TION 0.00 \times 0.00 \times 0.00 \times 5FR = 0.00	9 X 0.00 SFC = 0.0 Perimeter = 0.00	SFW = 0.00	SFLW= 0.00	SFSW= 0.0

 CI IO.		-			
LEFT ELEVAT	0.00 X 0.00 X SFR = 0.00	X 0.00 SFC = 0.00 Perimeter = 0.00	SFW = 0.00	SFLW= 0.00	SFSW= 0.00
1,083 Remove	GUTTERS/DOWNSPOUT, ALUMINU	92.00 LF	0.71	65.3	_
1,084 Replace	GUTTERS/DOWNSPOUT, ALUMINU SHEATHING, WALL, OSB, 1/2"	92.00 LF 365.00 SFW	6.26 0.42	575,9 153.2	
2,086 Replace 2,087 Remove 2,088 Replace	SHEATHING, WALL, OSB, 1/2" BRICK VENEER, WALL, 4" BRICK VENEER, WALL, 4"	365.00 SFW 365.00 SFW 365.00 SFW	0.86 1.72 10.46	322.: 627.: 3,865.:	30
"oss repiaco	Diddi. (Dimery)				

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

Exempt from Overhead. Profit or Taxes

Overrides

Page

- = Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
1 000 Charial	ACID WASH MASONRY SLAB	60.00 SFF	0.70	42.00
2,089 Special 2,090 Paint	CONCRETE FLOOR, 4"	60.00 SFF	1.19	71.40
1,090 Paun 1,091 Remove	GABLE VENT	1.00 LFF	0.52	0.52
1.091 Remove	GABLE VENT	1.00 LFF	60.00	60.21
2.093 Remove	DOOR, EXT, METAL, PH, SPECIAL	2.00 EA	13.55	27.10
1,093 Remove	DOOR, EXT, METAL, PH, SPECIAL	2,00 EA	966,00	1,932.00
1.095 Paint	DOOR, EXT, METAL, PH, SPECIAL	2,00 EA	48,68	97:36
-1	LOCKSET, EXTERIOR	2.00 EA	6.78	13.56
1,096 Remove	LOCKSET, EXTERIOR	2.00 EA	107.86	215.72
2,097 Replace	FASCIA, ALUMINUM	80.00 LFW	0.50	40.00
2,098 Remove	FASCIA, ALUMINUM	80.00 LFW	2.25	190.08
-1,099 Replace	SOFFIT, VINYL	119.00 LFW	0.68	80.92
1,100 Remove	SOFFIT, VINYL	119.00 LFW	2.84	346.05
-1,101 Replace	FLOOD LIGHT, DOUBLE BULB W N		11.79	11.79
1,102 Remove	FLOOD LIGHT, DOUBLE BULB W		104.53	104.53
1,103 Replace	CEILING FIXTURE, EXCELLENT	2.00 EA	9.35	18.70
2,104 Remove	CEILING FIXTURE, EXCELLENT	2.00 EA	131.43	262.86
1,105 Replace	TRIM, 1" X 8"	40.00 LFW	0.28	11.20
-2,107 Replace	TRIM, 1" X 8"	40.00 LFW	3.29	133.58
1.108 Paint	TRIM, 1" X 8"	40.00 LFW	0.81	32.40
·	AIR CONDITIONER, 3 TON	1.00 EA	54.22	54.22
2,109 Remove	AIR CONDITIONER, 3 TON	1.00 EA	1,690.00	1,690,00
2,110 Replace	SHUTTERS, VINYL	4.00 PR	9.68	38.72
2,111 Remove 2,112 Replace	SHUTTERS, VINYL	4.00 PR	64.47	257.88

GENERAL	$0.00 \ X \ 0.00$ SFR = 0.00	X 0.00 SFC = 0.00 Perimeter = 0.00	SFW = 0.00	SFLW= 0.00
1113 Special	TEMPORARY TOILET	6.00 LS	75.00	450.00
1,114 Special	PERMITS & FEES, INSURANCE	1.00 LS	3,000.00	3,000.00
1,115 Special	DUMPSTER, 30 YARD	12.00 EA	456.00	5,472.00
1116 Special	DISPOSE OF CONTENT IN HOME	1.00 SF	500.00	500.00
~!,117 Replace	DUCT, GALV- MAIN HOUSE BALAN	1.00 LF	2,900.00	2,900.07
2118 Replace	ALARM BID ITEM	1.00 EA	4,860.00	4,860.00
1119 Clean	POST CLEAN UP	10.00 HR	28.00	280.00
1,120 Replace	LANDSCAPING	1.00 SF	3,000.00	3,000.00
1,120 Replace		1.00 EA	750.00	750.00

Repair Estima Charge		Profit or Taxes		Claim Number: insured:	PA123 BORDEN	•	
Overrides Waste Applied	iionu,	Tion of Taxes				Page	55
Operation	Desc	cription	Quantity / Unit	Unit / Co	ost	Repl / Cost	
JBTOTAL				,		\$ 553,195,26	
Calculation Method Overhead	i: @	Overhead & Then Profit 10.00%				\$55,319.53	
					· ·	£609 61 4 70	
Profit	@	10.00%				\$608,514.79 \$60,851.48	
Taxes						\$ 669,366.27	
Material	(2)	6.00%					
Labor	@	0.00%					
Equipment	@	6.00%				\$11,125.94	
						\$680,492.21	

GIORDANO ASSOCIATES

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 Page 27 of 50

Phone:

Fax:

Carn Number:

PA123

Number:

Insured:

BORDEN

Address:

4838 WOLF ROAD

ERIE, PA 16505

Phone Number:

Peril:

05-Fire (hostile)

Loss Date:

03/09/03

Inspect Date:

03/09/03

Adiuster:

Phone Number:

Price Area / Database:

16505 / Marshall & Swift

Building Repair Estimate

.

PA123

* = Min. Charge

Insured:

Claim Number:

BORDEN

^ = Exempt from Overhead. Profit or Taxes

= Overrides

Page

PLAINTIFF'S

EXHIBIT

1

~= Waste Applied

Operation

Description

Quantity / Unit

Unit / Cost

Repl / Cost

Interior

ASEMENT

34.00 X 30.00 X 8.00 + offset 19.00 X 7.60 SFC = 1,164.40 SFW = 1,145.60 SFLW= 272.00 SFSW= 240.00 SFR = 2,310.00 Perimeter = 143.20

BLOCK WALLS HAVE HEAT CRACKS. IF SAVE PORTION OF FOUNDATION THEN NEED SELECTIVE DEMO. STEEL BEAM SUPPORTS ARE CEMENTED INTO THE FLOOR. CONCRETE FLOOR WILL SURELY BE DAMAGED.

Special	POWER WASH	1,145.60	SF	0.45	515.52
Special	ACID WASH MASONRY WALL	1,145.60	SFW	0.52	595.71
Special	SANDBLAST WALL BAKING SODA	1,145.60	SFW	0.67	767,55
Special	TUCKPOINT BLOCK	1,145.60	SF	2.11	2,417,22
Replace	BLOCK REPLACE DAMAGED	1.00	LF	700.00	700.56
Special	POWER WASH FLOOR	1,164.40	SF	0.45	523.98
Special	ACID WASH MASONRY FLOOR	1,164.40	SFF	0.52	605.49
Special	SANDBLAST FLOOR BAKING SOD/	1,164.40	SFW	0.67	780.15
Special	PATCH CONCRETE FLOOR	1.00	SFF	250.00	250.00
Paint	CONCRETE FLOOR, EPOSY SEAL 2	1.164.40	SFF	0.92	1.071.25
Remove	EXPOSY SEAL THE WALLS	1,145.60	SFF	0.92	1,053.95
Remove	FURRING STRIPS	555.00	SF	0.30	166.50
Replace	FURRING STRIPS	555.00	SF	1.25	693.75
Replace	WALL STUD, 2"x4" COMPLETE	80.00	SFW	1.82	145,60
Replace	DRYWALL WALL, 1/2"	555,00	SFW	1.27	719.83
Paint	SEAL DRYWALL WALL	555,00	SFW	0.25	138.75
Remove	PANELING, FINSHED, GOOD	555.00	SFW	0.27	149.85
Replace	PANELING, FINSHED, GOOD	555.00	SFW	3.23	1,842.32
Remove	BASE, COLONIAL, 3 1/2"	120.00	LFW	0.25	30.00
Replace	DRYWALL CEIL.,1/2", TAPED	1,164.40	SFC	1.27	1,495.09
Clean	DRYWALL CEIL., SEAL	1,164.40	SFC	0.25	291.10
Paint	DRYWALL CEIL., 1/2", TAPED	1,164.40	SFC	0.58	675.35

Building Repair Canade: 04-cv-00175-SJM Document 24-4 Claim Nachtle? / 16/200 pair age 28 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

2

Waste Applied

Replace BASE, COLONIAL, 3 1/2" 120.00 LFW 2.56 78.00	Operation	Description	Quantity /	'Unit	Unit / Cost	Repl / Cost
Replace BULLT IN HUTCH 1.00 LFW 450.00 450.11	Replace	BASE, COLONIAL, 3 1/2"	120.00	LFW	2.56	320,26
Paint BULLT IN HUTCH 1.00 LFW 45.00 541.31	Paint	BASE, COLONIAL, 3 1/2"	120.00	LFW	0.65	78.00
Paint BULT IN HUTCH 1.00 LFW 45.00 55.00	Replace	BUILT IN HUTCH	1.00	LFW	450.00	450,11
Replace BULT IN BENCH 12 FEET LONG 12.00 LFW 74.00 74.00 Replace BULT IN DENCH 12 FEET LONG 1.00 LFW 74.00 74.00 Replace BULT IN CABINET 9 9.00 LFW 45.00 405.30 Paint BULT IN CABINET 9 55.00 LFW 1.00 55.00 DOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 27.11 81.33 Replace DOOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 168.40 505.20 Paint DOOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 33.01 99.03 Replace LOCKSET, PASSAGE, EX 3.00 EA 33.01 99.03 Replace DOOR, INT, BIRCH, 2 SIDES 3 3.00 EA 35.846 175.38 Remove DOOR TRIM SET BOTH SIDES OF E 6.00 EA 4.66 27.96 Paint DOOR TRIM SET BOTH SIDES OF E 6.00 EA 4.66 27.96 Paint DOOR TRIM SET BOTH SIDES OF E 6.00 EA 4.66 63.96 Remove WINDOW, SLIDING, ALUM, SM 3.00 EA 22.77 63.31 89.00 Paint WINDOW, SLIDING, ALUM, SM 3.00 EA 29.90 0897.00 Paint WINDOW, SMALL, 2 COATS 3.00 EA 29.90 0897.00 Replace WINDOW, SMALL, 2 COATS 3.00 EA 22.77 63.31 WINDOW, SMALL, 2 COATS 3.00 EA 4.10.72 32.16 WINDOW, SMALL, 2 COATS 3.00 EA 4.13.09 39.27 WIRNING, RESIDENCE 1,164.40 SF 0.10 116.44 ER 2.75 3.20.10 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 4.32.9 50.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 2.2.00 484.00 12.96.00 Replace PIXTURE, INCNDSCENT, RECESS 12.00 EA 10.00 3.00.00 12.96.00 Remove ELECTRICAL FEED BID TIEM 1.00 EA 300.00 300.00 Remove ELECTRICAL FEED BID TIEM 1.00 EA 300.00 300.00 Remove ELECTRICAL FEED BID TIEM 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL BID TIEM 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 Remove ELECTRICAL FIRM CONTROL 1 1.00 EA 300.00 300.00 SECONTROL 1 1.00 EA 300.00	Paint	BUILT IN HUTCH	1.00	LFW	55.00	
Paint BUILT IN EENCH 12 FEET LONG 1.00 LFW 45.00 405.30	Replace	BUILT IN BENCH 12 FEET LONG				
Replace BUILT IN CABINET 9 9.00 LFW 1.00 55.00 25.	Paint	BUILT IN BENCH 12 FEET LONG				
Paint	Replace	•				
Remove DOOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 168.40 505.20 DOOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 33.01 99.03 Replace DOOR, INT, BIRCH, 2 SIDES 3.00 EA 33.01 99.03 Replace LOCKSET, PASSAGE, EX 3.00 EA 4.66 175.38 Remove DOOR TRIM SET BOTH SIDES OF E 6.00 EA 4.66 27.96 Paint DOOR, INT, BIRCH, 2 SIDES IN EACH SEARCH SEARC	Paint	BUILT IN CABINET 9'				
Replace DOOR, INT, BIRCH, PH, HC, FLUSH 3.00 EA 33.01 99.03 Poly 1 DOOR, INT, BIRCH, 2 SIDES 3.00 EA 33.01 99.03 Poly 3 Replace LOCKSET, PASSAGE, EX 3.00 EA 58.46 175.38 Remove DOOR TRIM SET BOTH SIDES OF C 6.00 EA 4.66 27.96 Poly 3 DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET BOTH SIDES OF C 6.00 EA 41.20 250.59 Point DOOR TRIM SET AVERAGE 3.00 EA 22.77 668.31 Remove WINDOW, SLIDING, ALUM, SM 3.00 EA 22.77 668.31 Remove WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Point	Remove	DOOR, INT, BIRCH, PH, HC, FLUSH				
Paint DOOR, INT, BIRCH, 2 SIDES 3,00 EA 33,01 99,03 Replace LOCKSET, PASSAGE, EX 3,00 EA 58,466 175,38 Remove DOOR TRIM SET BOTH SIDES OF C 6,00 EA 4,66 27,96 Replace DOOR TRIM SET BOTH SIDES OF C 6,00 EA 41,20 250,59 Paint DOOR TRIM SET BOTH SIDES OF C 6,00 EA 10,66 63,96 Remove WINDOW, SLIDING, ALUM, SM 3,00 EA 18,70 56,10 Replace WINDOW, SLIDING, ALUM, SM 3,00 EA 299,00 897,00 897,00 Replace WINDOW, SILDING, ALUM, SM 3,00 EA 22,77 68,31 Remove WINDOW, SMALL, 2 COATS 3,00 EA 22,77 68,31 WINDOW, SMALL, 2 COATS 3,00 EA 10,72 32,16 Remove WINDOW TRIM SET, AVERAGE 3,00 EA 13,09 39,27 Remove WIRNG, RESIDENCE 1,164,40 SF 0,10 116,44 WINDOW TRIM SET, AVERAGE 3,00 EA 13,09 39,27 WIRNG, RESIDENCE 1,164,40 EA 2,75 3,202,10 Remove RECEPTACLE, DUPLEX/SWITCH 22,00 EA 43,22 95,04 Replace FIXTURE,INCNIDSCENT,RECESS 12,00 EA 108,00 1,296,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 Remove 100 AMP D BDI ITEM 1,00 EA 500,00 500,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00 Remove ELECTRICAL FEDE BDI ITEM 1,00 EA 500,00 500,00 S00,00	Replace					
Replace LOCKSET, PASSAGE, EX 3.00 EA 58.46 175.38 Remove DOOR TRIM SET BOTH SIDES OF E 6.00 EA 4.66 27.96 Replace DOOR TRIM SET BOTH SIDES OF E 6.00 EA 41.20 250.59 Paint DOOR TRIM SET BOTH SIDES OF E 6.00 EA 10.66 63.96 Remove WINDOW, SLIDING, ALUM, SM 3.00 EA 18.70 56.10 Replace WINDOW, SLIDING, ALUM, SM 3.00 EA 299.00 897.00 Paint WINDOW, SMALL, 2 COATS 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 41.072 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 13.09 39.27 Remove WINING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA	Paint					
Remove DOOR TRIM SET BOTH SIDES OF E 6.00 EA 41.20 250.59	Replace					
Replace DOOR TRIM SET BOTH SIDES OF E 6.00 EA 10.66 63.96	Remove	DOOR TRIM SET BOTH SIDES OF C				
Paint DOOR TRIM SET BOTH SIDES OF E 6.00 EA 10.66 63.96 Remove WINDOW, SLIDING, ALUM, SM 3.00 EA 18.70 56.10 Replace WINDOW, SLIDING, ALUM, SM 3.00 EA 299.00 897.00 Paint WINDOW, SMALL, 2 COATS 3.00 EA 22.77 68.31 Remove WINDOW TRIM SET, AVERAGE 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace ELECTRICAL FLOBED TIEM 1.00 EA 108.00 1.296.00 Remove 100 AMP SERVICE BID ITEM 1.00 EA <td< td=""><td>Replace</td><td></td><td></td><td></td><td></td><td></td></td<>	Replace					
Remove WINDOW, SLIDING, ALUM, SM 3.00 EA 18.70 56.10 Replace WINDOW, SLIDING, ALUM, SM 3.00 EA 299,00 897.00 Paint WINDOW, SILDING, ALUM, SM 3.00 EA 22.77 68.31 Remove WINDOW TRIM SET, AVERAGE 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 2.75 3.202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.	Paint					
Replace Paint WINDOW, SLIDING, ALUM, SM 3.00 EA 299.00 897.00 Paint WINDOW, SMALL, 2 COATS 3.00 EA 22.77 68.31 Remove WINDOW TRIM SET, AVERAGE 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 11.09 39.27 Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WIRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace FIXTURE,INCNDSCENT, RECESS 12.00 EA 100.00 100.62 Remove ELECTRICAL FEED BID ITEM 1.00 EA 100.00 100.62 Remove ELECTRICAL FEED BID ITEM 1.00 EA 500.00 500.00 Remove ELECTRICAL THERMO CONTROL I 50.00 50.00	Remove					
Paint WINDOW, SMALL, 2 COATS 3.00 EA 22.77 68.31 Remove WINDOW TRIM SET, AVERAGE 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 13.09 39.27 Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WIRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 108.00 1.296.00 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 108.00 1.296.00 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 108.00 1.296.00 Replace ELECTRICAL FECB BID ITEM 1.00 EA 100.00 10.062 Remove ELECTRICAL FED BID ITEM 1.00 EA	Replace					
Remove Replace WINDOW TRIM SET, AVERAGE 3.00 EA 10.72 32.16 Replace WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 13.09 39.27 Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WIRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace FIXTURE,INCNDSCENT, RECESS 12.00 EA 100.00 100.62 Remove ELECTRICAL FEED BID ITEM 1.00 EA 100.00 100.62 Remove ELECTRICAL FIRED 1.00 EA 500.00 500.00 Remove ELECTRICAL THEM 1.00 EA 500.00 500.00 Remove ELECTRICAL THEM 1.00 EA 300.00	-					
Replace Paint WINDOW TRIM SET, AVERAGE 3.00 EA 48.17 146.21 Paint WINDOW TRIM SET, AVERAGE 3.00 EA 13.09 39.27 Remove WRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 108.00 1.296.00 Replace FEXTURE,INCNDSCENT,RECESS 12.00 EA 100.00 100.62 Remove 200 AMP SERVICE BID ITEM 1.00 EA 100.00 100.62 Remove ELECTRICAL FEED BID ITEM 1.00 EA 500.00 500.00 Remove ELECTRICAL THEM 1.00 EA 500.00 30.00 Remove ELECTRICAL THEM 1.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 34.00<						
Paint WINDOW TRIM SET, AVERAGE 3.00 EA 13.09 39.27 Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WIRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace FIXTURE,INCNDSCENT,RECESS 12.00 EA 108.00 1.296.00 Replace FIXTURE,INCNDSCENT,RECESS 12.00 EA 100.00 100.62 Remove ELECTRICAL FEED BID ITEM 1.00 EA 100.00 500.00 Remove ELECTRICAL FEED BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 10.00 3,000.00 Remove RECONNECTION FEE BID ITEM 1.00 EA	Replace					
Remove WIRING, RESIDENCE 1,164.40 SF 0.10 116.44 Replace WRNG, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 108.00 1.296.00 Replace FIXTURE,INCNDSCENT RECESS 12.00 EA 108.00 1.296.00 Replace ELECTRICAL FEED BID ITEM 1.00 EA 100.00 100.62 Remove 200 AMP SER VICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 500.00 500.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITIME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA	=					
Replace WIRING, RESIDENCE 1,164.40 EA 2.75 3,202.10 Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace FIXTURE,INCNDSCENT,RECESS 12.00 EA 100.00 100.62 Remove 200 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 500.00 300.00 Remove 100 AMP D BID ITEM 1.00 EA 50.00 50.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 10.00 3,000.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58						
Remove RECEPTACLE, DUPLEX/SWITCH 22.00 EA 4.32 95.04 Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace FIXTURE,INCNDSCENT, RECESS 12.00 EA 108.00 1.296.00 Remove EECTRICAL FEED BID ITEM 1.00 EA 100.00 500.00 Remove 100 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CRCUIT BID ITIME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 20.00 Remove RECONNECTION FEE BID ITEM 1.00 EA	Replace					
Replace RECEPTACLE, DUPLEX/SWITCH 22.00 EA 22.00 484.00 Replace FIXTURE,INCNDSCENT,RECESS 12.00 EA 108.00 1.296.00 Replace ELECTRICAL FEED BID ITEM 1.00 EA 100.00 500.00 Remove 200 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 500.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITIME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 150.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 34.00 5,950.00 Remove RECCETIACLE, DRYER 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace WIRING, FOR DRYER 1.00 EA 80.88 </td <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td>	-					
Replace FIXTURE,NCNDSCENT,RECESS 12.00 EA 108.00 1.296.00 Replace ELECTRICAL FEED BID ITEM 1.00 EA 100.00 100.62 Remove 200 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITIME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA <	Replace					
Replace ELECTRICAL FEED BID ITEM 1.00 EA 100.00 100.62 Remove 200 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITIME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.	_					
Remove 200 AMP SERVICE BID ITEM 1.00 EA 500.00 500.00 Remove 100 AMP D BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 80.88 80.88 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean </td <td>•</td> <td></td> <td></td> <td></td> <td></td> <td></td>	•					
Remove 100 AMP D BID ITEM 1.00 EA 300.00 300.00 Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 80.88 80.88 80.88 Replace WIRING, FOR DRYER 1.00 EA 20.35 20.35 20.35 Replace OUTLET, TELEPHONE 1.00 EA 20.35<	-					
Remove ELECTRICALHOOKUP 1.00 EA 50.00 50.00 Remove TWO POLE CIRCUIT BID ITME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 2						
Remove TWO POLE CIRCUIT BID ITME 300.00 EA 10.00 3,000.00 Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1,750.00 1,750.00						
Remove HOME RUN BID ITEM DIFFICULT F 175.00 EA 34.00 5,950.00 Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove ELECTRICAL THERMO CONTROL I 50.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00						
Remove RECONNECTION FEE BID ITEM 1.00 EA 150.00 150.00 Remove ELECTRICAL THERMO CONTROL I 50.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 <						•
Remove ELECTRICAL THERMO CONTROL I 50.00 EA 4.00 200.00 Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR <td< td=""><td></td><td></td><td></td><td></td><td></td><td>-</td></td<>						-
Remove RECEPTACLE, DRYER 1.00 EA 8.58 8.58 Replace RECEPTACLE, DRYER 1.00 EA 63.77 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1,750.00 1,750.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 1,750.00 1,750.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR						
Replace RECEPTACLE, DRYER 1.00 EA 63.77 Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						
Replace WIRING, FOR DRYER 1.00 EA 80.88 80.88 Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00						
Replace OUTLET, TELEPHONE 1.00 EA 20.35 20.35 Replace OUTLET, CABLE 1.00 EA 20.35 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	-	•				
Replace OUTLET, CABLE 1.00 EA 20.35 Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	-					
Replace HEAT, VENT, AC UNIT BID UNIT 1.00 EA 21,608.00 21,608.00 Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1,750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	-					
Clean CLEANING DEBRIS OFF FLOOR 48.00 HR 28.50 1,368.00 Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1,750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	=					
Remove STEEL BEAM 36' - PER VISION BLD 1.00 LF 500.00 500.00 Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	•					•
Replace STEEL BEAM 36' - PER VISION BLD 1.00 LF 1.750.00 1.750.00 Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00						
Remove STEEL, COLUMN, LOLLY CEMENT 2.00 EA 14.00 28.00 Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00						
Replace STEEL, COLUMN, LOLLY CEMENT 2.00 LF 125.00 250.00 Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	-					
Replace JACK HAMMER RENTAL AND OPE 4.00 HR 116.00 464.00 Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00						
Remove WATER HEATER, ELEC, 80 GAL 1.00 EA 49.29 Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00	_					
Replace WATER HEATER, ELEC, 80 GAL 1.00 EA 560.00 560.00	-					
500.00						
Special ROUGH IN WATER HEATER 1.00 EA 145.46 145.46	Special	ROUGH IN WATER HEATER				

Building Repair Extignated: 04-cv-00175-SJM Document 24-4ClaimFillergbetr2/16/200BA12Page 29 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

3

Wa	aste	Ap	olie	≥d																			
					 	 	 	 	 	 	 ****	 	 . <i></i>										

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost	•
 Remove	SINK,UTILITY,SGL BWL,W/HNGNG	1.00	EA	35.67	35.67	
Replace	SINK,UTILITY,SGL BWL,W/HNGNG	1.00	EA	248.12	248.12	
Special	ROUGH IN LAUNDRY SINK	1.00	EA	200.00	200.00	
Replace	FAUCET	1.00	EA	141.79	141. 7 9	
Special	ROUGH IN WASHER	1.00	EA	134.79	134.79	
Replace	SUMP PUMP AND LINES	1.00	EA	298.00	298.00	
Remove	FIBERGLASS PIT FOR PUMP	1.00	EA	125.00	125.00	
Remove	COPPER TUBING, L, 1"	200.00	LF	1.47	294.00	
Replace	COPPER TUBING, L, 1"	200.00	LF	10,24	2,081.40	
Replace	GAS LINE PIPE, BLACK STEEL, 1"	25.00	LF	16,44	414.29	
Replace	WASTE LINE, CAST IRON, 4"	20.00	LF	18.17	371.65	
Remove	WASTE LINE, MISC	1.00	LF	100.00	100.00	
Remove	STOVE, COAL-BURNING, GD	1.00	EA	85.00	85.00	
Replace	STOVE, COAL-BURNING, GD	1.00	EA	649.00	649.00	
Replace	DUCT, FLEX STEEL, 8"	30.00		3.29	99.91	

CRAWL SPAC	E FRONT OF HOUS20.00 X 34.00 SFSW= 119.00		0 SFC = = 1,058.00	= 680.00 SFI Perimeter = 1	W = 378.00	SFLW= 70.00
Special	POWER WASH WALLS	378,00	SF	0.45		170,10
Special	ACID WASH MASONRY WALL	378.00	SFW	0.52		196.56
Special	SANDBLAST WALL BAKING SODA	378.00	SFW	0.67		253.26
Special	TUCKPOINT BLOCK	378.00	SF	2.11		797.58
Special	POWER WASH FLOOR	680.00	SF	0.45		306.00
Special	ACID WASH MASONRY FLOOR	680.00	SFF	0.52		353.60
Special	SANDBLAST FLOOR BAKING SOD/	100.00	SFW	0.67		67.00
Paint	CONCRETE FLOOR, EPOSY SEAL 2	680.00	SFF	0.92		625.60
Paint	EXPOSY SEAL THE WALLS	378.00	SFF	0.92		347.76
Remove	WASTE LINE, MISC	1.00	LF	75.00		75.00
Replace	WIRING, RESIDENCE	680.00	EA	2,75		1,870.00
Remove	SMOKE DETECTOR	1.00	EA	9.35	•	9.35
Replace	SMOKE DETECTOR	1.00	EA	54,53		54.53
Remove	WASTE LINE, PVC PIPE, 4"	60,00	LF	1.80		108.00
Replace	WASTE LINE, PVC PIPE, 4"	60,00		14.16		861.63
Remove	FIBERBOARD INSULATION	216.00		0.17		36.72
Replace	FIBERBOARD INSULATION	216.00		1.21		270,00
Remove	OPENING, CASED	1.00		10.72	-	10.72
Replace	OPENING, CASED	1.00		82.36		85.36
Paint	OPENING, CASED	1.00		30.99		30.99
Replace	VAPOR BARRIER, POLYETHELENE	680.00		0.55		374.00

Building Repair Estate 1:04-cv-00175-SJM Document 24-Claim Nitable 12/16/2005 A123 Page 30 of 50

* = Min. Charge Insured: BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides Page

Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
RAWLSPACE	E BACK OF HOME 34.00 X 20.00 SFSW= 70.00	X 3.50 SFC SFR = 1,058.00	= 680.00	SFLW= 119.00
Special	POWER WASH WALLS	378.00 SF	0.45	170.10
Special	ACID WASH MASONRY WALL	378.00 SFW	0.52	196.56
Special	SANDBLAST WALL BAKING SODA	378.00 SFW	0.67	253.26
Special	TUCKPOINT BLOCK	378.00 SF	2.11	797.58
Special	POWER WASH FLOOR	680.00 SF	0.45	306.00
Special	ACID WASH MASONRY FLOOR	680.00 SFF	0.52	353.60
Special	SANDBLAST FLOOR BAKING SOD/	378.00 SFW	0.67	253.26
Paint	CONCRETE FLOOR, EPOSY SEAL 2	680.00 SFF	0.92	625.60
Paint	EXPOSY SEAL THE WALLS	680.00 SFF	0.92	625.60
Remove	WASTE LINE, MISC	1.00 LF	75.00	75.00
Replace	WIRING, RESIDENCE	680.00 EA	2.75	1,870.00
Remove	SMOKE DETECTOR	1.00 EA	9.35	9,35
Replace	SMOKE DETECTOR	1.00 EA	54.53	54,53
Remove	WASTE LINE, PVC PIPE, 4"	60.00 LF	1.80	108.00
Replace	WASTE LINE, PVC PIPE, 4"	60.00 LF	14.16	861,63
Remove	FIBERBOARD INSULATION	216.00 SF	0.17	36.72
Replace	FIBERBOARD INSULATION	216.00 SF	1.21	270.00
Remove	OPENING, CASED	1.00 EA	10.72	10.72
Replace	OPENING, CASED	1.00 EA	82.36	85 .36
Paint	OPENING, CASED	1.00 EA	30.99	30.99
Replace	VAPOR BARRIER, POLYETHELENE	680.00 SF	0.55	374.00

ST.	AIRWAY	9.70 X 3.40	X 8.00	+ offse	at 4.00 X 3.30	SFC = 46.18 $SFW = 262.40$
		SFLW= 77.60	SFSW	= 27.20	SFR = 308.58	Perimeter = 32.80
	STAIRS LEA	DING TO STUDIO ARE BURNT O	UT. THEY	LEAD TO) GARAGE	
	CEILING AN	ID SMOKED ENTERED THE CEIL	ING.			
	Replace	WALL STUD, 2"x4" COMPLETE	14.00		11.00	154.00
	Remove	DRYWALL ROOM,1/2",TAPED	308.58	SFR	0.25	77.14
	Replace	DRYWALL ROOM,1/2",TAPED	308.58	SFR	1.27	400.51
	Remove	BATT INSULATION - WALL R11	77.60	SFW	0.19	14.74
	Replace	BATT INSULATION - WALL R11	77.60	SFW	0.55	42.68
	Special	SEAL & PAINT ROOM, 2 COATS	308,58	SFR	0.76	234.52
	Remove	STAIR STRINGER, 2" X 10"	16.00	LF	0.88	14.08
	Replace	STAIR STRINGER, 2" X 10"	21.00	LF	6.06	128.65
	Paint	STAIR STRINGER, 2" X 10"	21.00	LF	1.88	39.48
	Remove	STAIR STRINGERS-5 STEP	10,00	EA	8.21	82.10
	Replace	STAIR STRINGERS-5 STEP	10.00	EA	55.00	561.36
	Remove	STAIR TREAD, OAK, 3'	10.00	EA	4.24	42.40
	Replace	STAIR TREAD, OAK, 3'	10.00	EA	34.21	342.10
	Paint	STAIR TREAD, OAK, 3'	10.00	EA	6.00	60.00
	Remove	RISER, OAK, 3/4" X 7 1/2"	9.00	LF	1.12	10.08

Building Repair Estable 1:04-cv-00175-SJM Document 24- Claim File 1:2/16/20 Tai 23 Page 31 of 50

* = Min. Charge

^ = Exempt from Overhead, Profit or Taxes

= Overrides Page

Insured:

BORDEN

5

Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost
Replace	RISER, OAK, 3/4" X 7 1/2"	9.00 LF	15.00	135.00
Paint	RISER, OAK, 3/4" X 7 1/2"	9.00 LF	4.00	36.00
Remove	SHEATHING FLOOR, LANDING	11.84 SFC	0.47	5,56
Replace	SHEATHING FLOOR, LANDING	11.84 SFC	1.87	23.33
Replace	CARPET METAL STRIP	.3.00 LFW	1.74	5.42
Remove	CARPET & PAD, GOOD (SY)	1.00 SYF	2.07	2.07
Replace	CARPET & PAD, GOOD (SY)	1.00 SYF	16.65	17.75
Remove	OAK FLOOR, 2 1/4", CLEAR	11.84 SFF	0.64	7.58
Replace	OAK FLOOR, 2 1/4", CLEAR	11.84 SFF	7.42	109.32
Special	SAND AND FINISH FLOORS	11.84 SFF	1.95	23.09
Remove	BASE, COLONIAL, 3 1/2"	27.00 LFW	0.25	6.75
Replace	BASE, COLONIAL, 3 1/2"	27.00 LFW	2.56	72.06
Paint	BASE, COLONIAL, 3 1/2"	27.00 LFW	0.65	17.55
Remove	CHAIR RAIL, 3 1/2"	32.80 LFW	0.25	8.20
Replace	CHAIR RAIL, 3 1/2"	32.80 LFW	3.24	111.51
Paint	CHAIR RAIL, 3 1/2"	32.80 LFW	0.65	21.32
Remove	DOOR TRIM SET,2 1/2",1SIDE	1.00 EA	4.66	4.66
Replace	DOOR TRIM SET,2 1/2",1SIDE	1.00 EA	41.20	41.76
Paint	DOOR TRIM SET,2 1/2",1SIDE	1.00 EA	10.66	10,66
Remove	RAILING, OAK	11.00 LF	1.19	13.09
Replace	RAILING, OAK	11.00 LF	7.16	78.7 6
Remove	SWITCH ONLY	1.00 EA	4.32	4.32
Replace	SWITCH ONLY	1.00 EA	3.50	3.50
Replace	CEILING FIXTURE, EXCELLENT	1.00 EA	131,43	131.43
Replace	WIRING, RESIDENCE	46.18 EA	2.75	127.00
Remove	CASEMENT ANDERSON VYN/WOO	1.00 EA	21.69	21.69
Replace	CASEMENT ANDERSON VYN/WOO	1.00 EA	625.00	625.00
Paint	WINDOW, CASEMENT, LG	1.00 EA	37.66	37.66

Interior

GARAGE

 $24.60 \ X \ 24.50 \ X \ 8.50 \ SFC = 602.70 \ SFW = 834.70 \ SFLW = 209.10$ $SFSW = 208.25 \ SFR = 1,437.40 \ Perimeter = 98.20$

STAIRS THAT LEAD TO STUDIO BURNT BAD AND ALLOWED SMOKE TO ENTER CEILING. I PULLED A LIGHT FIGURE DOWN AND SMOKE IN CEILING AND APPEARS TO BE IN WALLS. FIRE DEPARTMENT CUT NUMEROUS WALLS OUT. DOORS SMELL TO MUCH TO SAVE, AND THE HANDLING, CLEANING, STAINING FEES WILL BE TO CLOSE TO NEW PRICE.

Remove	DRYWALL CEIL.,5/8"FIRE RES	602,70 SFC	0.52	313.40
Replace	DRYWALL CEIL.,5/8"FIRE RES	602.70 SFC	1.30	794.36
Remove	INSUL,CEIL,BATT,FOIL FC,9*	602.70 SFC	0.20	120,54
Replace	INSUL,CEIL,BATT,FOIL FC,9"	602.70 SFC	1.07	644.89
Special	TEXTURE CEILING	602.70 SFC	0.77	464,08
Remove	DRYWALL WALL, 5/8"FIRE RES	834.70 SFW	0.30	250.41
Replace	DRYWALL WALL, 5/8"FIRE RES	834.70 SFW	1.30	1.115.99
Paint	DRYWALL WALL, 5/8"FIRE RES	834.70 SFW	0.58	484.13
Remove	BATT INSULATION - WALL R19	834.70 SFW	0.19	158.59
Replace	BATT INSULATION - WALL R19	834.70 SFW	0,62	517.51

Building Repail@ate04-cv-00175-SJM Document 24-4 Claimil@dmb@t/16/2005PA1Page 32 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

6

= Waste Applied

waste Applied			·		
Operation	•	- •	Unit / Cost	Repl / Cost	
Remove	WALL STUD, 2"x4" COMPLETE	192.00 SFW	0.72	138.24	• • •
Replace	WALL STUD, 2"x4" COMPLETE	192.00 SFW		349.44	
Special	CLEAN & SEAL FRAMING CEILING		0.32	192.86	
Special	CLEAN & SEAL FRAMING WALL	644.70 SFL	0.32	206.30	
Remove	GARAGE DOOR, FGLASS, DOUBLE	1.00 EA	99.26	99.26	
Replace	GARAGE DOOR, FGLASS, DOUBLE	1.00 EA	890.00	890.00	
Clean	GARAGE DOOR, PAINT	1.00 EA	75.00	75.00	
Remove	GARAGE DOOR OPENER	1.00 EA	24.64	24.64	
Replace	GARAGE DOOR OPENER	1.00 EA	312.00	312.00	
Remove	WINDOW TRIM SET, CUSTOM	2.00 EA	10.72	21.44	
Replace	WINDOW TRIM SET, CUSTOM	2.00 EA	81.04	163.42	
Paint	WINDOW TRIM SET, CUSTOM	2.00 EA	31.26	62.52	
Clean	WINDOW, CASEMENT, LG	2.00 EA	9.49	18.98	
Paint	WINDOW, CASEMENT, LG	2.00 EA	37.66	75.32	
Remove	DOOR TRIM SET, CUSTOM	3.00 EA	9.32	27.96	
Replace	DOOR TRIM SET, CUSTOM	3.00 EA	80.79	245.61	
Paint	DOOR TRIM SET, CUSTOM	3.00 EA	22.14	66.42	
Remove	DOOR ONLY,INT,LAUAN,FLUSH	2.00 EA	13.55	27,10	
Replace	DOOR ONLY,INT,LAUAN,FLUSH	2.00 EA	123.00	246.00	
Paint	DOOR ONLY,INT,LAUAN,FLUSH	2.00 EA	20.62	41.24	
Remove	OPENING, CASED	1.00 EA	10.72	10.72	
Replace	OPENING, CASED	1.00 EA	82.36	85.36	
Paint	OPENING, CASED	1.00 EA	30.99	30.99	
Replace	BUILT IN NEXT TO AC UNIT	1.00 LFW	250.00	250.11	
Remove	SHELF, CABINET GRADE PLY	40.00 LFW	0.90	36.00	
Replace	SHELF, CABINET GRADE PLY	40,00 LFW	8.54	346.08	
Paint	SHELF, CABINET GRADE PLY	40.00 LFW	1.37	54.80	
Remove	BASE, RUBBER, 4"	76.00 LFW	0.25	19.00	
Replace	BASE, RUBBER, 4"	76.00 LFW	1.55	119.70	
Remove	DOOR, EXT, METAL, PH, PANEL	2.00 EA	13,55	27.10	
Replace	DOOR, EXT, METAL, PH, PANEL	2.00 EA	446.30	892.60	
Paint	DOOR, EXT, METAL, PH, PANEL	2.00 EA	48.68	97.36	
Remove	LOCKSET, EXTERIOR	2.00 EA	6.78	13.56	
Replace	LOCKSET, EXTERIOR	2.00 EA	85.00	170,00	
Remove	DOOR, ALUM, STORM	1.00 EA	12.32	12.32	
Replace	DOOR, ALUM, STORM	1.00 EA	236.02	236.02	
Special	CUT AND FIT DOG DOOR	1.00 LF	75.00	75.00	
Special	POWER WASH FLOOR	602.70 SF	0.45	271.21	
Paint	CONCRETE FLOOR, EPOSY SEAL 2	602.70 SFF	0.92	554.48	
Clean	CLEAN DRAIN OUT	1.00 EA	45.00	. 45.00	
Remove	WIRING, RESIDENCE	602.70 SF	0.10	60.27	
Replace	WIRING, RESIDENCE	602.70 EA	2.75	1,657,43	
Remove	RECEPTACLE, DUPLEX/SWITCH	4.00 EA	4,32	17.28	
Replace	RECEPTACLE, DUPLEX/SWITCH	4.00 EA	22.00	88.00	
Remove	RECEPTACLE, G.F.I.	1.00 EA	4.32	4.32	
Replace	RECEPTACLE, G.F.I.	1.00 EA	50.25	50.25	
Remove	SMOKE DETECTOR	1.00 EA	9.35	9.35	
Replace	SMOKE DETECTOR	1.00 EA	54.53	54.53	
Remove	CEILING FIXTURE, PORCELAIN	4.00 EA	8.47	33,88	

Building Repair Cash Ratt: 04-cv-00175-SJM Document 24-4 Clain Nacht 24/16/2005 A128 age 33 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides Page 7

Waste Applied

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
 Replace	CEILING FIXTURE, PORCELAIN	4.00 EA	64.98	259.92	
Remove	FAUCET, SINGLE LEVER HOSE PLU	1.00 EA	19.36	19.36	
Replace	FAUCET, SINGLE LEVER HOSE PLU	1.00 EA	126.16	126,16	

Interior

STUDIO	18.60 X 16.60	$X = 9.00 \qquad SFC = 308.76$	SFW = 633.60	SFLW= 167.40
	SFSW= 149.40	SFR = 942.36 Perimet	er = 70.40	
HEIGHT IS AVERAGE. PULLEI	LIGHT CEILING I	FULL OF SMOKE. THE STA	AIRS	
ARE BURNT FROM UNDERNE	ATH. BUILT INS H	EAVILY SMOKED CANNO	T	
CLEAN UNDERNETH OR HAR	DWARE TO PREVE	NT SMOKE ODOR WINDO	OWS TO	

HEAVILY SMOKED TO CLEAN, HARDWARE ON WINDOWS DAMAGED

Remove	DRYWALL CEIL	308.76	SFC	0.52	160.56
Replace	DRYWALL CEIL	308.76	SFC	1.22	387.53
Remove	INSUL,CEIL,BATT,FOIL FC,9"	308.76	SFC	0.20	61.75
Replace	INSUL,CEIL,BATT,FOIL FC,9"	308.76	SFC	1.07	330.37
Replace	SCAFFOLD, STEEL, CATHERDALE (633,60	SFW	0.25	158.40
Remove	DRYWALL WALL	633.60	SFW	0.30	190.08
Replace	DRYWALL WALL	633,60	SFW	1.22	803.88
Remove	BATT INSULATION - WALL R19	633.60	SFW	0.19	120.38
Replace	BATT INSULATION - WALL R19	633,60	SFW	0.62	392.83
Special	CLEAN & SEAL FRAMING CEILING	308.76	SFL	0.32	98.80
Special	CLEAN & SEAL FRAMING WALL	633.60	SFL	0.32	202.75
Paint	CEILING, 2 COATS + PRIME	308.76	SFC	0.59	182.17
Remove	PANELING, FINSHED, GOOD	633.60	SFW	0.27	171.07
Replace	PANELING, FINSHED, GOOD	633.60	SFW	3.23	2,103.24
Remove	MOLDING, COVE, 2 3/4"	70.40	LFW	0.27	19.01
Replace	MOLDING, COVE, 2 3/4"	70.40	LFW	2.56	187.54
Paint	MOLDING, COVE, 2 3/4"	70.40	LFW	0.70	49.28
Replace	CHAIR RAIL, 3 1/2"	70.40	LFW	3.24	239.36
Paint	CHAIR RAIL, 3 1/2"	70.40	LFW	0.65	45.76
Remove	BASE, COLONIAL, 3 1/2"	70.40	LFW	0.25	17.60
Replace	BASE, COLONIAL, 3 1/2"	70.40	LFW	2.56	187.88
Paint	BASE, COLONIAL, 3 1/2"	70.40	LFW	0,65	45.76
Remove	WINDOW TRIM SET, CUSTOM	5.00	EA	10.72	53.60
Replace	WINDOW TRIM SET, CUSTOM	5.00	EA	81.04	408.54
Paint	WINDOW TRIM SET, CUSTOM	5,00	EA	31.26	156.30
Remove	DOOR TRIM SET, CUSTOM	2.00	EA	9.32	18.64
Replace	DOOR TRIM SET, CUSTOM	2.00	EA	80.79	163.74
Paint	DOOR TRIM SET, CUSTOM	2.00	EA	22.14	44.28
Replace	BUILT IN DOORS BELOW CASE AB	3.00	LFW	1,200.00	3,601.31
Paint	BUILT IN	3.00	LFW	74.00	222.00
Replace	BUILT IN CABINET LOWER 4 FEET	2.00	LFW	450.00	900.30
Paint	BUILT IN CABINET LOWER 4 FEET	2.00	LFW	55.00	110.00
Remove	MOLDING, CROWN, 4 5/8" MULTI F	18.60	LFW	0.43	8.00
Replace	MOLDING, CROWN, 4 5/8" MULTI F	18.60	LFW	2.76	53.48
Paint	MOLDING, CROWN, 4 5/8" MULTI F	18.60	LFW	0.70	13,02
Remove	TRIM, 1" X 10"	40.00	LFW	0.28	11.20

Building Repair Case 1:04-cv-00175-SJM Document 24-4 Claim Files bdr 2/16/200 A12 Page 34 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

8

Waste Applied

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost
Replace	TRIM, I" X 10"	40.00	LFW	2.23	91.66
Paint	TRIM, 1" X 10"	40.00	LFW	0.88	35.20
Remove	TRIM, 1" X 8"	20.00	LFW	0.28	5.60
Replace	TRIM, 1" X 8"	20.00	LFW	1.92	39.39
Paint	TRIM, 1" X 8"	20.00	LFW	0.81	16.20
Special	DRAPERIES RODS, REMOVE/RESE	5.00	EA	31,49	157.45
Rem/Reset	REGISTER, HEAT, 12" X 5"	3.00	EA	19.34	58.02
Clean	REGISTER, HEAT, 12" X 5"	3.00	EA	3.18	9.54
Paint	REGISTER, HEAT, 12" X 5"	3.00	EA	3.55	10.65
Paint	FLOOR, 1 COAT SEAL	308.76	SFF	0.34	104.98
Remove	CARPET & PAD, EXCELLENT (SY)	34.31	SYF	2.07	71.02
Replace	CARPET & PAD, EXCELLENT (SY)	34.31	SYF	33.55	1,252.66
Remove	WIRING, RESIDENCE	308.76	SF	0.10	30.88
Replace	WIRING, RESIDENCE	309,76	EA	2.75	851.84
Remove	RECEPTACLE, DUPLEX/SWITCH	13.00	EA	4.32	56.16
Replace	RECEPTACLE, DUPLEX/SWITCH	13.00	EA	22.00	286.00
Remove	OUTLET, TELEPHONE/CABLE	3.00	EA	4.32	12.96
Replace	OUTLET, TELEPHONE/CABLE	3.00	EA	20.35	61.05
Replace	FIXTURE, INCNDSCENT, RECESS	6.00	EA	108.00	648.00
Rem/Reset	CHANDELIER REMOVE AND BOX	2.00	EA	95.00	190.00
Clean	CHANDELIER, VERY GOOD	2.00	EA	18.30	36.60
Remove	CASEMENT ANDERSON VYN/WOO	5.00	EA	21.69	108.45
Replace	CASEMENT ANDERSON VYN/WOO	5.00	EA	695.00	3,475.00
Paint	WINDOW, CASEMENT, LG	5.00	EA	37.66	188.30

STUDIO BEDRO AVERAGE H	OOM 14.00 X 13.00 SFLW= 126.00 EIGHT FOR CEILING. SAME EXPL	SFSV	V= 117.00	SFR = 756.00	SFC = 198.00	558.00
Remove	DRYWALL CEIL	198.00	SFC	0.52	102.96	
Replace	DRYWALL CEIL	198.00	SFC	1.22	252.41	
Paint	CEILING, 2 COATS + PRIME	198.00	SFC	0.59	116.82	
Remove	INSUL,CEIL,BATT,FOIL FC,9"	198.00	SFC	0.20	39.60	
Replace	INSUL,CEIL,BATT,FOIL FC,9"	198.00	SFC	1.07	211.86	
Replace	SCAFFOLD, STEEL, CATHERDALE (558.00	SFW	0.25	139.50	
Remove	DRYWALL WALL	558.00	SFW	0.30	167.40	
Replace	DRYWALL WALL	558.00	SFW	1.22	701.41	
Paint	DRYWALL WALL SIZE	558.00	SFW	0.21	117.18	
Remove	WALLPAPER, VERY GOOD	558.00	SFW	0,35	195.30	
Replace	WALLPAPER, VERY GOOD	558.00	SFW	1.86	1,095.91	
Replace	WALLPAPER BORDER	62.00	LFW	1.34	86.06	
Remove	BATT INSULATION - WALL R19	279.00	SFW	0.19	53.01	
Replace	BATT INSULATION - WALL R19	279.00	SFW	0.62	172.98	
Special	CLEAN & SEAL FRAMING CEILING	198,00	SFL	0.32	63.36	
Special	CLEAN & SEAL FRAMING WALL	558.00	SFL	0.32	178.56	
Replace	WALL STUD, 2" x 4" MINI	1.00	LFF	165.00	165.02	
Remove	BASE, COLONIAL, 3 1/2"	62.00	LFW	0.25	15.50	

Building Repair Esasat :04-cv-00175-SJM Document 24-4ClaimFiled to 2/16/200 A12 Page 35 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Page 9

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost
- Replace	BASE, COLONIAL, 3 1/2"	62.00	LFW	2,56	166,38
Paint	BASE, COLONIAL, 3 1/2"	62.00	LFW	0.65	40.30
Remove	WINDOW TRIM SET, CUSTOM	1.00	EA	10.72	10.72
Replace	WINDOW TRIM SET, CUSTOM	1.00	EA	81.04	84.38
Paint	WINDOW TRIM SET, CUSTOM	1.00	EA	31,26	31.26
Remove	DOOR TRIM SET, CUSTOM	3.00	EA	9.32	27.96
Replace	DOOR TRIM SET, CUSTOM	3.00	EA	80.79	245.61
Paint	DOOR TRIM SET, CUSTOM	3.00	EA	22.14	66.42
Remove	DOOR, INT, PH, 6 PANEL	1.00	EA	30.49	30,49
Replace	DOOR, INT, PH, 6 PANEL	1.00	EA	137,84	137.84
Paint	DOOR, INT, PH, 6 PANEL	1.00	EA	35.16	35,16
Replace	LOCKSET, PASSAGE	1.00	EA	95.00	95.00
Remove	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	30.49	30.49
Replace	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	225,00	225.00
Paint	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	16.91	16.91
Replace	BUILT IN DOORS BELOW CASE AB	2.00	LFW	1,200.00	2,400.22
Paint	BUILT IN	2.00	LFW	74.00	148.00
Replace	BUILT IN CABINET LOWER 6 FEET	1.00	LFW	450.00	450.30
Paint	BUILT IN CABINET LOWER 6 FEET	1.00	LFW	55.00	55.00
Remove	MOLDING, CROWN, 4 5/8" MULTI F	14.00	LFW	0.43	6.02
Replace	MOLDING, CROWN, 4 5/8" MULTI F	14.00	LFW	2.76	40.25
Paint	MOLDING, CROWN, 4 5/8" MULTI F	14.00	LFW	0.70	9.80
Special	DRAPERIES RODS, REMOVE/RESE	1.00	EA	31.49	31.49
Rem/Reset		2.00	EA	19.34	38.68
Clean	REGISTER, HEAT, 12" X 5"	2.00	EA	3.18	6.36
Paint	REGISTER, HEAT, 12" X 5"	2.00	EA	3,55	7.10
Paint	FLOOR, I COAT SEAL	198.00	SFF	0.34	67.32
Remove	CARPET & PAD, EXCELLENT (SY)	22.00	SYF	2.07	45.54
Replace	CARPET & PAD, EXCELLENT (SY)	22.00	SYF	33.55	839.66
Remove	WIRING, RESIDENCE	198.00	SF	0.10	19.80
Replace	WIRING, RESIDENCE	198.00	EA	2.75	544.50
Remove	RECEPTACLE, DUPLEX/SWITCH	10.00	EA	4.32	43.20
Replace	RECEPTACLE, DUPLEX/SWITCH	10.00	EA	22,00	220.00
Remove	SWITCH, DIMMER TYPE	3.00	EA	4.76	14.28
Replace	SWITCH, DIMMER TYPE	3.00		65.71	197.13
Remove	OUTLET, TELEPHONE/CABLE	2.00		4.32	8.64
Replace	OUTLET, TELEPHONE/CABLE	2.00		20.35	40.70
Replace	FIXTURE,INCNDSCENT,RECESS	5.00		108.00	540.00
Rem/Reset	CHANDELIER REMOVE AND BOX	1.00	EA	95.00	95.00
Clean	CHANDELIER, VERY GOOD	1.00	EA	18.30	18.30
Remove	FLUOR. FIXTURE, RECESS, 4x1	1.00	EA	8.40	8.40
Replace	FLUOR. FIXTURE,RECESS,4x1	1.00	EA	103.01	103.01
Remove	CASEMENT ANDERSON VYN/WOC	1.00	EA	21.69	21.69
Replace	CASEMENT ANDERSON VYN/WOC	1.00		695.00	695.00
Paint	WINDOW, CASEMENT, LG	1.00		37.66	37.66
Remove	SHELF, CABINET GRADE PLY		LFW	0.90	3.60
Replace	SHELF, CABINET GRADE PLY		LFW	8.54	34.61
Paint	SHELF, CABINET GRADE PLY		LFW	1.37	5.48
Remove	CLOSET POLE, 3 1/2"	4.00		0.31	1.24

Building Repair Connect 24-4 Clair Nachtle 2/16/2005 A123 age 36 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

10

Paint

STAIR TREAD, OAK, 3'

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
Replace	CLOSET POLE, 3 1/2"	4,00 LF	3.10	12.62	
Paint	CLOSET POLE, 3 1/2"	4.00 LF	0.87	3.48	
Replace	CABINET GRADE BOX STAIRS OU	1.00 LFW	250.00	250.03	

Interior

STAIRWAY TO	O KITCHEN FROM 18.90 X 3.70	X 8.00 SFR =		= 69.93 Perimeter	SFW = 361.60	SFLW= 151.20
STAIRS FRO	<i>SFSW= 29.60</i> OM UNDERNEATH ARE BURNT ANI					
	NG HEAVY SOOT INCLUDING FRAM					
Remove	DRYWALL CEIL	69.93			0.52	36.36
Replace	DRYWALL CEIL	69.93			1.22	96.16
Remove	INSUL,CEIL,BATT,FOIL FC,9"	69.93			0.20	13.99
Replace	INSUL,CEIL,BATT,FOIL FC,9"	69.93			1.07	74.83
Remove	DRYWALL WALL	361.60			0,30	108.48
Replace	DRYWALL WALL	361.60	SFW		1.22	472.04
Remove	BATT INSULATION - WALL R19	151,20	SFW		0.19	28.73
Replace	BATT INSULATION - WALL R19	151.20	SFW		0.62	93.74
Special	CLEAN & SEAL FRAMING CEILING	69,93	SFL		0.32	22.38
Special	CLEAN & SEAL FRAMING WALL	361.60	SFL		0.32	115.71
Paint	CEILING, 2 COATS + PRIME	69.93	SFC		0.59	41.26
Remove	PANELING, FINSHED, GOOD	361.60	SFW		0.27	97.63
Replace	PANELING, FINSHED, GOOD	361.60	SFW		3.23	1,224.68
Remove	MOLDING, COVE, 2 3/4"	45.20	LFW		0.27	12.20
Replace	MOLDING, COVE, 2 3/4"	45.20	LFW		2.56	120.42
Paint	MOLDING, COVE, 2 3/4"	45.20			0.70	31.64
Replace	CHAIR RAIL, 3 1/2"	45. 2 0			3.24	157.71
Paint	CHAIR RAIL, 3 1/2"	45.20			0.65	29.38
Remove	BASE, COLONIAL, 3 1/2"	45.20			0.25	11.30
Replace	BASE, COLONIAL, 3 1/2"	45.20			2.56	123.37
Paint	BASE, COLONIAL, 3 1/2"	45.20			0.65	29.38
Remove	DOOR TRIM SET, CUSTOM	2.00			9.32	18.64
Replace	DOOR TRIM SET, CUSTOM	2.00			0.79	163.74
Paint	DOOR TRIM SET, CUSTOM	2.00			2.14	44.28
Remove	MOLDING, CROWN, 4 5/8" MULTI F	45.20			0.43	19.44
Replace	MOLDING, CROWN, 4 5/8" MULTI F	45.20			2.76	126.90
Paint	MOLDING, CROWN, 4 5/8" MULTI F	45.20			0.70	31.64
Remove	RAILING, OAK	36.00			1.19	42.84
Replace	RAILING, OAK	36.00			7.16	257.76
Paint	RAILING, OAK	36.00			1.32	
Remove						47.52
	STAIR STRINGER, 2" X 10" TRIM	36.00			0.88	31.68
Replace	STAIR STRINGER, 2" X 10"	36.00			6.06	220.55
Paint	STAIR STRINGER, 2" X 10"	36.00			1.88	67.68
Remove	STAIR STRINGERS-14 STEP	14.00			8.21	114.94
Replace	STAIR STRINGERS-14 STEP	14.00			5.00	1.065.91
Remove	STAIR TREAD, OAK, 3'	14.00			4.24	59.36
Replace	STAIR TREAD, OAK, 3'	14.00	ĽΑ	3	4.21	478.94

14.00 EA

6.00

84.00

Building Repaile 04-cv-00175-SJM Document 24-4 Claim Repaile 16/2005 PAIP age 37 of 50

* = Min. Charge Insured: BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides Page 11

= Waste Applied

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost	
 Remove	RISER, OAK, 3/4" X 7 1/2"	13.00	LF	1.12	14,56	
Replace	RISER, OAK, 3/4" X 7 1/2"	13.00	LF	15.00	195.00	
Paint	RISER, OAK, 3/4" X 7 1/2"	13.00	LF	4.00	52.00	
Remove	CARPET & PAD, EXCELLENT (SY)	7.77	SYF	2.07	16.08	
Replace	CARPET & PAD, EXCELLENT (SY)	7.77	SYF	33.55	362.25	
Remove	CARPET STEPS, (EA)	13.00	EA	3.77	49.01	
Replace	CARPET STEPS, (EA)	13.00	EA	5.00	65.00	
Replace	CARPET WASTE	3.19	SFF	8.40	27.18	
Remove	WIRING, RESIDENCE	69.93	SF	0.10	6.99	
Replace	WIRING, RESIDENCE	69.93	EA	2.75	192.31	
Remove	SWITCH, DIMMER TYPE	1.00	EA	4.76	4.76	
Replace	SWITCH, DIMMER TYPE	1.00	EA	65.71	65.71	
Replace	FIXTURE,INCNDSCENT,RECESS	2.00	EA	108,00	216.00	
Remove	THERMOSTAT, EXCELLENT	1.00	EA	8.47	8.47	
Replace	THERMOSTAT, EXCELLENT	1.00	EA	124,00	124.00	

Interior

PANTRY	11.90 X 4.40 SFLW= 97.58	X 8.20 + SFSW= 36.00	offset 6.20 X 6.50 8 SFR = 466.58	SFC = 92.66
ALL SHELV	ING CABINET GRADE			10.000
Remove	JOIST, CEILING & FLOOR COMPLE	129.00 LFF	0.57	73.53
Replace	JOIST, CEILING & FLOOR COMPLET	129.00 LFF	2.14	288.79
Remove	WALL STUD, 2"x4" COMPLETE	373.92 SFW	0.72	269.22
Replace	WALL STUD, 2"x4" COMPLETE	373.92 SFW	1.82	680.53
Remove	DRYWALL CEIL	92.66 SFC	0,52	48.18
Replace	DRYWALL CEIL	92.66 SFC	1,22	123.89
Paint	CEILING, 2 COATS + PRIME	92.66 SFC	0.59	54.67
Remove	INSUL,CEIL,BATT,FOIL FC,9"	92.66 SFC	0.20	18.53
Replace	INSUL,CEIL,BATT,FOIL FC,9"	92.66 SFC	1,07	99.15
Remove	DRYWALL WALL	373.92 SFW	0.30	112.18
Replace	DRYWALL WALL	373.92 SFW	1.22	476.83
Paint	DRYWALL WALL	373.92 SFW	0.58	216.87
Remove	BATT INSULATION - WALL R19	77.00 SFW	0.19	14.63
Replace	BATT INSULATION - WALL R19	77.00 SFW	0.62	47.74
Remove	BASE, COLONIAL, 3 1/2"	45.60 LFW	0.25	11.40
Replace	BASE, COLONIAL, 3 1/2"	45.60 LFW	2.56	124.39
Paint	BASE, COLONIAL, 3 1/2"	45.60 LFW	0.65	29.64
Remove	BASE SHOE, PINE	45.60 LFW	0.27	12.31
Replace	BASE SHOE, PINE	45.60 LFW	1.58	73.58
Paint	BASE SHOE, PINE	45.60 LFW	0.62	28.27
Remove	DOOR TRIM SET, CUSTOM	6.50 EA	9.32	60,58
Replace	DOOR TRIM SET, CUSTOM	6.50 EA	80.79	531,98
Paint	DOOR TRIM SET, CUSTOM	6.50 EA	22,14	143.91
Remove	DOOR, INT, PH, 6 PANEL	3.00 EA	30.49	91.47
Replace	DOOR, INT, PH, 6 PANEL	3.00 EA	199.00	597.00
Paint	DOOR, INT, PH, 6 PANEL	3.00 EA	35.16	105.48
Replace	LOCKSET, PASSAGE	3.00 EA	95.00	285.00

Building Repair Case 1:04-cv-00175-SJM Document 24-4 Claim Manual 16/2005 A1 Bage 38 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Page

12

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost
Remove	DOOR, CLOSET, BIFOLD,PANEL SC	1.00		30.49	30.49
Replace	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	225.00	225,00
Paint	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	16.91	16.91
Rem/Reset	REGISTER, HEAT, 12" X 5"	1.00	EA	19.34	19.34
Clean	REGISTER, HEAT, 12" X 5"	1.00	EA	3.18	3.18
Paint	REGISTER, HEAT, 12" X 5"	1.00	EA	3.55	3.55
Remove	SHEATHING FLOOR, PLYWOOD	92.66	SFC	0.47	43.55
Replace	SHEATHING FLOOR, PLYWOOD	92.66	SFC	1.87	182.54
Remove	CERAMIC FLOOR, THIN SET, 12"X1	92.66	SFF	0.71	65.79
Replace	CERAMIC FLOOR, THIN SET, 12"X1	92.66	SFF	11.00	1,045.50
Remove	UNDERLAYMENT, 3/4	92.66	SFF	0.49	45.40
Replace	UNDERLAYMENT,3/4"	92.66	SFF	1.87	177.50
Remove	WIRING, RESIDENCE	92.66	SF	0.10	9.27
Replace	WIRING, RESIDENCE	92.60	EA	2.75	254,65
Remove	RECEPTACLE, DUPLEX/SWITCH	4.00	EA	4.32	17.28
Replace	RECEPTACLE, DUPLEX/SWITCH	4.00	EA	22.00	88.00
Replace	FIXTURE, INCNDSCENT, RECESS	2.00	EA	108.00	216.00
Remove	FLUOR. FIXTURE, RECESS, 4x1	1.00	EA	8.40	8.40
Replace	FLUOR. FIXTURE, RECESS, 4x1	1,00	EA	103.01	103.01
Remove	SHELF, CABINET GRADE PLY	28.00	LFW	0.90	25,20
Replace	SHELF, CABINET GRADE PLY	28.00	LFW	8.54	242.26
Paint	SHELF, CABINET GRADE PLY	28.00	LFW	1.37	38.36
Remove	CLOSET POLE, 3 1/2"	3.00	LF	0.31	0.93
Replace	CLOSET POLE, 3 1/2"	3.00	LF	3.10	9.46
Paint	CLOSET POLE, 3 1/2"	3.00	LF	0.87	2.61

w					
	ni	P	T1	n	r

		SFC = 24.53 Perimeter = 19	SFW = 162.52 2.82	SFLW= 41.90	SFSW=
JOIST, CEILING & FLOOR COMPLE	49.06	LFF	0.57	27.96	
JOIST, CEILING & FLOOR COMPLE	49.06	LFF	2.14	109.82	
WALL STUD, 2"x4" COMPLETE	162.52	SFW	0.72	117.01	
WALL STUD, 2"x4" COMPLETE	162.52	SFW	1.82	295,79	
DRYWALL CEIL	24.53	SFC	0.52	12.76	
DRYWALL CEIL	24.53	SFC	1.22	40.77	
CEILING, 2 COATS + PRIME	24.53	SFC	0.59		
TEXTURE CEILING	24.53	SFC	0.77	18.89	
INSUL,CEIL,BATT,FOIL FC,9"	24.53	SFC	0.20	4.91	
INSUL,CEIL,BATT,FOIL FC,9"	24,53	SFC	1.07		
DRYWALL WALL	162.52	SFW	0.30		
DRYWALL WALL	162,52	SFW	1.22		
SIZE WALLS	162.52	SFW	0.21		
WALLPAPER, EXCELLENT	162.52	SFW	0.41		
WALLPAPER, EXCELLENT	162.52	SFW	1.68		
WALLPAPER BORDER	19.82	LFW	0.34		
WALLPAPER BORDER	19.82	LFW	1.34	27.51	
	JOIST, CEILING & FLOOR COMPLE' JOIST, CEILING & FLOOR COMPLE' WALL STUD, 2"x4" COMPLETE WALL STUD, 2"x4" COMPLETE DRYWALL CEIL DRYWALL CEIL CEILING, 2 COATS + PRIME TEXTURE CEILING INSUL, CEIL, BATT, FOIL FC, 9" INSUL, CEIL, BATT, FOIL FC, 9" DRYWALL WALL DRYWALL WALL SIZE WALLS WALLPAPER, EXCELLENT WALLPAPER, EXCELLENT WALLPAPER BORDER	JOIST, CEILING & FLOOR COMPLE JOIST, CEILING & FLOOR COMPLE WALL STUD, 2"x4" COMPLETE WALL STUD, 2"x4" COMPLETE DRYWALL CEIL DRYWALL CEIL CEILING, 2 COATS + PRIME TEXTURE CEILING UNSUL, CEIL, BATT, FOIL FC, 9" DRYWALL WALL DRYWALL WALL SIZE WALLS WALLPAPER, EXCELLENT WALLPAPER BORDER 49.06 49	JOIST, CEILING & FLOOR COMPLE 49.06 LFF JOIST, CEILING & FLOOR COMPLE 49.06 LFF WALL STUD, 2"x4" COMPLETE 162.52 SFW WALL STUD, 2"x4" COMPLETE 162.52 SFW DRYWALL CEIL 24.53 SFC DRYWALL CEIL 24.53 SFC CEILING, 2 COATS + PRIME 24.53 SFC TEXTURE CEILING 24.53 SFC INSUL, CEIL, BATT, FOIL FC, 9" 24.53 SFC DRYWALL WALL 162.52 SFW DRYWALL WALL 162.52 SFW SIZE WALLS 162.52 SFW WALLPAPER, EXCELLENT 162.52 SFW WALLPAPER, EXCELLENT 162.52 SFW WALLPAPER BORDER 19.82 LFW	JOIST, CEILING & FLOOR COMPLE	JOIST, CEILING & FLOOR COMPLE

Case 1:04-cv-00175-SJM Document 24-4_{Claim} Filed 12/16/2005 A12 Page 39 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Page

13

	Operation	Description	Quantity /	Unit	·	Repl / Cost
	Remove	BATT INSULATION - WALL R19	41.90	SFW	0.19	7,96
	Replace	BATT INSULATION - WALL R19	41.90	SFW	0.62	25.98
	Remove	BASE, COLONIAL, 3 1/2"		LFW	0.25	4.95
	Replace	BASE, COLONIAL, 3 1/2"	19.82	LFW	2.56	58,40
	Paint	BASE, COLONIAL, 3 1/2"	19.82	LFW	0,65	12.88
	Remove	BASE SHOE, PINE	19.82	LFW	0.27	5,35
	Replace	BASE SHOE, PINE	19.82	LFW	1.58	32.85
	Paint	BASE SHOE, PINE	19,82	LFW	0.62	12.29
	Remove	DOOR TRIM SET, CUSTOM	1.00	EA	9,32	9.32
	Replace	DOOR TRIM SET, CUSTOM	1.00	EA	80.79	87.64
	Paint	DOOR TRIM SET, CUSTOM	1.00	EA	22.14	22.14
	Remove	DOOR, INT, PH, 6 PANEL	1.00		30.49	30.49
	Replace	DOOR, INT, PH, 6 PANEL	1.00		199.00	199.00
	Paint	DOOR, INT, PH, 6 PANEL	1.00		35.16	35.16
	Remove	WINDOW TRIM SET, CUSTOM	1.00		10.72	10.72
	Replace	WINDOW TRIM SET, CUSTOM	1.00		81.04	84.38
	Paint	WINDOW TRIM SET, CUSTOM	1.00		31.26	31.26
	Remove	CASEMENT ANDERSON VYN/WOO			21.69	21.69
	Replace	CASEMENT ANDERSON VYN/WOO			695.00	695.00
	Replace	LOCKSET, PASSAGE	1.00		95.00	95.00
	-	REGISTER, HEAT, 12" X 5"	1.00		19.34	19.34
	Clean	REGISTER, HEAT, 12" X 5"	1.00		3.18	3.18
	Paint	REGISTER, HEAT, 12" X 5"	1.00		3.55	3.55
	Remove	SHEATHING FLOOR, PLYWOOD	24.53		0.47	11.53
			24.53		1.87	55,13
	Replace	SHEATHING FLOOR, PLYWOOD			0.71	17.42
	Remove	CERAMIC FLOOR, THIN SET, 12"XI			11.00	296.07
	Replace	CERAMIC FLOOR, THIN SET, 12"X1	24.53 24.53		0.49	12.02
	Remove	UNDERLAYMENT, 3/4				
	Replace	UNDERLAYMENT,3/4"	24.53		1.87	46,99
	Remove	WIRING, RESIDENCE	24.53		0.10	2.45
	Replace	WIRING, RESIDENCE	24.53		2.75	67.46
	Remove	RECEPTACLE, DUPLEX/SWITCH	2.00		4.32	8.64
	Replace	RECEPTACLE, DUPLEX/SWITCH	2.00		22.00	44.00
	Remove	RECEPTACLE, G.F.I.	1.00		4.32	4.32
	Replace	RECEPTACLE, G.F.I.	1.00		50,25	50.25
	Remove	EXHAUST FAN WITH LIGHT VENT			12.32	12.32
	Replace	EXHAUST FAN WITH LIGHT VENT			201.65	201.65
	Remove	FLEX STL DUCT W/VNYL CT 4"	12.00		0.52	6.24
	Replace	FLEX STL DUCT W/VNYL CT 4"	12.00		2.84	34.38
	Remove	VANITY, 36" MAHOGONY	1.00		12.15	- 12.15
	Replace	VANITY, 36" MAHOGONY	1.00		425.00	425.00
	Paint	VANITY, 36" MAHOGONY	1.00		24.51	24.51
	Replace	LAV, CULT MARB, DBL BWL, 37"	1.00		172.22	172,22
	Replace	FAUCET, BATH, EX	1.00		141.79	141.79
	Special	ROUGH IN 2 FIXTURES	1.00		684.32	684.32
	Replace	WATER CLOSET, 2 PIECE, EX	1,00		228,28	228.28
	Replace	TOILET SEAT	1.00		56.93	56.93
-	Replace	MEDICINE CABINET	1.00		186.00	186.00
	Replace	ACCESSORY, BATHROOM, GD	3.00	EA	21.81	65.43

Building Repair (24-4 Claim Hand) 2/16/2005 A12 age 40 of 50

* = Min. Charge

Insured:

BORDEN

Page

14

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Operation Description Quantity / Unit Unit / Cost Repl / Cost

Interior

PAN	TRY CLO	SET 2.40 X 1.90 X 15.58 SFR =		SFC = 4.56 Perimeter = 8.0	SFW = 70.52 60	SFLW= 19.68	SFSW=
	Remove	JOIST, CEILING & FLOOR COMPLE	9.12	LFF	0.57	5.20	
	Replace	JOIST, CEILING & FLOOR COMPLE	9.12	LFF	2.14	20.42	
	Remove	WALL STUD, 2"x4" COMPLETE	70.52	SFW	0.72	50.77	
	Replace	WALL STUD, 2"x4" COMPLETE	70.52	SFW	1.82	128.35	
	Remove	DRYWALL CEIL		SFC	0.52	2.37	
	Replace	DRYWALL CEIL	4.56	SFC	1.22	16.41	
	Paint	CEILING, 2 COATS + PRIME	4.56	SFC	0.59	2.69	
	Remove	INSUL,CEIL,BATT,FOIL FC,9"	4.56	SFC	0.20	0.91	
	Replace	INSUL,CEIL,BATT,FOIL FC,9"	4.56	SFC	1.07	4.88	
	Remove	DRYWALL WALL	70.52	SFW	0.30	21.16	
	Replace	DRYWALL WALL	70.52	SFW	1.22	106.68	
	Paint	DRYWALL WALL	70.52	SFW	0.58	40.90	
	Remove	BATT INSULATION - WALL R19	19.68	SFW	0.19	3.74	
	Replace	BATT INSULATION - WALL R19	19.68	SFW	0.62	12.20	
	Remove	BASE, COLONIAL, 3 1/2"	8.60	LFW	0.25	2.15	
	Replace	BASE, COLONIAL, 3 1/2"	8.60	LFW	2.56	29.67	
	Paint	BASE, COLONIAL, 3 1/2"	8.60	LFW	0.65	5,59	
	Remove	BASE SHOE, PINE	8.60	LFW	0.27	2.32	
	Replace	BASE SHOE, PINE	8.60	LFW	1.58	15.12	
	Paint	BASE SHOE, PINE	8.60	LFW	0.62	5.33	
	Remove	DOOR TRIM SET, CUSTOM	1.00	EA	9.32	9.32	
	Replace	DOOR TRIM SET, CUSTOM	1.00	EA	80.79	87.64	
	Paint	DOOR TRIM SET, CUSTOM	1.00	EA	22.14	22.14	
	Remove	SHEATHING FLOOR, PLYWOOD	4.56	SFC	0.47	2.14	
	Replace	SHEATHING FLOOR, PLYWOOD	4.56	SFC	1.87	17.79	
	Remove	CERAMIC FLOOR, THIN SET, 12"X1	4.56	SFF	0.71	3.24	
	Replace	CERAMIC FLOOR, THIN SET, 12"X1	4.56	SFF	11.00	76.40	
	Remove	UNDERLAYMENT 3/4"	4.56	SFF	0.49	2.23	
	Replace	UNDERLAYMENT, 3/4"	4.56	SFF	1.87	8.74	
	Remove	WIRING, RESIDENCE	4.56	SF	0.10	0.46	
	Replace	WIRING, RESIDENCE	4.56	EA	2.75	12.54	
	Remove	SHELF, CABINET GRADE PLY	8.00	LFW	0.90	7.20	
	Replace	SHELF, CABINET GRADE PLY	8.00		8.54	69.22	
	Paint	SHELF, CABINET GRADE PLY	8.00	LFW	1.37	10.96	

Building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-4 Clair in the building Repair Connact: 04-cv-00175-SJM Document 24-cv-00175-SJM Document 24-cv-00

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides Page 15

Waste Applied

Operation Description Quantity / Unit Unit / Cost Repl / Cost

KITCHEN 17.00 X 16.00 X 8.80 + offset 20.00 X 6.80 SFC = 408.00 SFW = 700.48 SFLW= 149.60 SFSW= 140.80 SFR = 1,108.48 Perimeter = 79.60

CABINETS AND BUILT IN HIGH QUALITY. CORIAN COUNTERTOPS. WITH CENTER ISLAND. ALL APPLIANCE TOP OF LINE.

Remove	JOIST, CEILING & FLOOR COMPLE	816.00	LFF	0.57	465,12
Replace	JOIST, CEILING & FLOOR COMPLE	816.00	LFF	2.14	1,826.78
Remove	WALL STUD, 2"x4" COMPLETE	700.48	SFW	0.72	504.35
Replace	WALL STUD, 2"x4" COMPLETE	700.48	SFW	1.82	1,274.87
Remove	DRYWALL CEIL	408.00		0.52	212.16
Replace	DRYWALL CEIL	408.00	SFC	1.22	508.61
Paint	CEILING, 2 COATS + PRIME	408.00	SFC	0.59	240.72
Special	TEXTURE CEILING	408.00	SFC	0.77	314.16
Remove	INSUL,CEIL,BATT,FOIL FC,9"	408.00	SFC	0.20	81.60
Replace	INSUL,CEIL,BATT,FOIL FC,9"	408.00	SFC	1.07	436.56
Remove	DRYWALL WALL	700,48	SFW	0.30	210.14
Replace	DRYWALL WALL	700.48	SFW	1.22	875,23
Special	SIZE WALLS	700.48	SFW	0.21	147.10
Remove	WALLPAPER, EXCELLENT	700.48	SFW	0.41	287.20
Replace	WALLPAPER, EXCELLENT	700.48	SFW	1.68	1,200,21
Remove	WALLPAPER BORDER	79.60	LFW	0.34	27.06
Replace	WALLPAPER BORDER	79.60	LFW	1.34	107.61
Special	REPLACE SKYLIGHT CHUTE DRYV	1.00		250.00	250.00
Paint	CHUTE	1.00		75.00	75.00
Remove	SKYLIGHT, FIXED, LARGE	1.00	EA	45.18	45.18
Replace	SKYLIGHT, FIXED, LARGE	1.00	EA	745.00	745.00
Replace	SCAFFOLD, STEEL, 1 USE, 15'H	1.00	SFW	55.00	55.00
Remove	BATT INSULATION - WALL R19	700.48	SFW	0.19	133.09
Replace	BATT INSULATION - WALL R19	700.48	SFW	0.62	434.30
Remove	BASE, COLONIAL, 3 1/2"	79.60	LFW	0.25	19.90
Replace	BASE, COLONIAL, 3 1/2"	79.60	LFW	2,56	211.43
Paint	BASE, COLONIAL, 3 1/2"	79.60	LFW	0.65	51.74
Remove	BASE SHOE, PINE		LFW	0.27	21.49
Replace	BASE SHOE, PINE		LFW	1.58	127.30
Paint	BASE SHOE, PINE		LFW	0,62	49.35
Remove	DOOR TRIM SET, CUSTOM	7.00		9.32	65.24
Replace	DOOR TRIM SET, CUSTOM	7.00	EA	80.79	573.10
Paint	DOOR TRIM SET, CUSTOM	7.00	EA	22.14	154,98
Remove	DOOR, INT, PH, 6 PANEL	1.00	EA	30.49	30.49
Replace	DOOR, INT, PH, 6 PANEL	1.00	EA	199.00	199.00
Paint	DOOR, INT, PH, 6 PANEL	1.00	EA	35.16	35.16
Remove	TRIM, 1" X 10"	152.00	LFW	0.28	42.56
Replace	TRIM, 1" X 10"	152.00	LFW	2.23	348.32
Paint	TRIM, 1" X 10"	152.00		0.88	133.76
Remove	TRIM, 1" X 8"	98.00	LFW	0.28	27.44
Replace	TRIM, 1" X 8"	98.00		1.92	193.02
Paint	TRIM, 1" X 8"	98.00		0.81	79.38
Remove	WINDOW TRIM SET, CUSTOM	3.00		10.72	32.16
Replace	WINDOW TRIM SET, CUSTOM	3.00		81.04	245.12
					— · - · - · - ·

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 PA123 Page 42 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Page

16

Waste Applied

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost
 Paint	WINDOW TRIM SET, CUSTOM	3.00	EA	31,26	93.78
Remove	CASEMENT ANDERSON VYN/WOC	3.00	EA	21.69	65.07
Replace	CASEMENT ANDERSON VYN/WOC	3.00	EA	456,00	1,368.00
Paint	WINDOW, CASEMENT, LG	3.00	EA	37.66	112.98
Replace	LOCKSET, PASSAGE	1.00	EA	95.00	95.00
Remove	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	30.49	30.49
Replace	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	225.00	225.00
Paint	DOOR, CLOSET, BIFOLD, PANEL SC	1.00	EA	16.91	16.91
Remove	OPENING, CASED	1.00	EA	10.72	10.72
Replace	OPENING, CASED	1.00	EA	82,36	85.36
Paint	OPENING, CASED	1.00	ĒΑ	30.99	30.99
Replace	REGISTER, HEAT, 12" X 5"	4,00	EA	22.59	90,36
Paint	REGISTER, HEAT, 12" X 5"	4.00	EA	3.55	14.20
Remove	SHEATHING FLOOR, PLYWOOD	408.00	SFC	0.47	191.76
Replace	SHEATHING FLOOR, PLYWOOD	408.00	SFC	1.87	772.22
Remove	UNDERLAYMENT3/4"	408.00	SFF	0.49	199.92
Replace	UNDERLAYMENT3/4"	408.00	SFF	1.87	781.56
Remove	CERAMIC FLOOR, THIN SET, 12"X1	408.00	SFF	0.71	289.68
Replace	CERAMIC FLOOR, THIN SET, 12"X1	408.00	SFF	11.00	4,514.24
Remove	WIRING, RESIDENCE	408.00	SF	0.10	40.80
Replace	WIRING, RESIDENCE	408.00	EA	2.75	1,122.00
Remove	RECEPTACLE, DUPLEX/SWITCH	17.00	EA	4.32	73.44
Replace	RECEPTACLE, DUPLEX/SWITCH	17.00		22,00	374.00
Replace	FIXTURE_INCNDSCENT,RECESS	10.00		108.00	1,080.00
Remove	CHANDELIER, VERY GOOD	2.00		19.36	38.72
Replace	CHANDELIER, VERY GOOD	2.00		487.40	974.80
Remove	SWITCH, DIMMER TYPE	1.00		4.76	4.76
Replace	SWITCH, DIMMER TYPE	1.00		65.71	65.71
Remove	COOK TOP, COUNTER TOP, EX	1.00		17.74	17.74
Replace	COOK TOP, COUNTER TOP, EX	1.00		757.54	757,54
Remove	OVEN, BUILT IN, DELUXE	1.00		36.83	36.83
Replace	OVEN, BUILT IN, DELUXE	1.00		713.75	713.75
Remove	OVEN, BUILT IN, DELUXE 2 ND UN			36.83	36.83
Replace	OVEN, BUILT IN, DELUXE 2ND UN			713.75	713.75
Remove	ELECTRIC STOVE	1.00		37,65	37.65
Replace	ELECTRIC STOVE	1.00		526.06	526.06
Remove	DISHWASHER, EXCELLENT	1.00		33.89	33.89
Replace	DISHWASHER, EXCELLENT	1.00		522.11	522.11
Special	ROUGH IN DISHWASHER	1.00		134.79	134.79
Remove	REFRIGERATOR	1.00		16.94	16.94
Replace	REFRIGERATOR	1.00		799.00	799.00
Remove	MICROWAVE OVEN	1.00		7.75	7.75
Replace	MICROWAVE OVEN	1.00		799.00	799.00
Remove	CABINET, BASE, EXCELLENT	25.00		8.47	211.75
Replace	CABINET, BASE, EXCELLENT	25.00		211.00	5,275.00
Remove	CABINET, WALL, EXCELLENT	17.00		6.86	116.62
Replace	CABINET, WALL, EXCELLENT	17.00		195.00	
Remove	CABINETFULL LENGHT	11.00		8.47	3,315.00 93.17
IXCIIIO VC	CUDIND IL OPP PENQUI	11.00	LL YY	X 44 /	9117

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 PA123 age 43 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Page

17 :

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
Remove	COUNTERTOP CORIAN SITE BUILT	31.90 LF	1.39	44.34	
Replace	COUNTERTOP CORIAN SITE BUILT	1.00 LF	7,900.00	7,900.00	
Remove	MOLDING, CROWN, 4 5/8"	17.00 LFW	0.43	7.31	
Replace	MOLDING, CROWN, 4 5/8"	17.00 LFW	4.55	79.31	
Replace	DESK BUILT IN	1.00 LFW	1,400,00	1,400.00	
Special	ROUGH IN KITCHEN SINK SUPL	1.00 EA	498.08	498.08	
Remove	SINK, KITCH, PE, DBL BWL, GD	1.00 EA	27.11	27.11	
Replace	SINK, KITCH, PE, DBL BWL, GD	1.00 EA	272.64	272.64	
Remove	FAUCET, KITCH, 2 VLV W/SPRAY,	1.00 EA	20.35	20.35	
Replace	FAUCET, KITCH, 2 VLV W/SPRAY.	1.00 EA	184.31	184.31	
Remove	SOAP DISPENSER, SURFACE MTD	1.00 EA	6.45	6.45	
Replace	SOAP DISPENSER SURFACE MTD	1.00 EA	63,10	63.10	
Special	DRAPERIES, REMOVE/RESET	2.00 EA	31.49	62.98	
Replace	THERMOSTAT, EXCELLENT	1.00 EA	86.04	86.04	
Replace	CHILD QUARDS	1.00 LFW	200.00	200.03	
Remove	WATER PURIFICATION CENTER KE	1.00 EA	22.59	22.59	
Replace	WATER PURIFICATION CENTER LE	1.00 EA	568.41	568.41	

Interior

DEN

14.00 X 17.00 X 8.20 + offset 29.40 X 16.70 SFC = 728.98 SFW = 782.28 SFLW=114.80 SFSW=139.40 SFR = 1,511.26 Perimeter = 95.40 ROCK AND PLASTER. REMOVING ALL. REPLACING

CEILING DOUBLE LAYER OF ROCK AND PLASTER. REMOVING ALL. REPLACING WITH 5/8 ROCK AND SOUND BOARD LAYER FOR SAME NOISE PROTECTION.

Remove	JOIST, CEILING & FLOOR COMPLE	1,457.96	LFF	0.57	831.04
Replace	JOIST, CEILING & FLOOR COMPLE	1,457.96	LFF	2.14	3,263.94
Remove	WALL STUD, 2"x4" COMPLETE	782.28	SFW	0.72	563.24
Replace	WALL STUD, 2"x4" COMPLETE	782.28	SFW	1.82	1,423.75
Remove	DRYWALL CEIL	728.98	SFC	0,52	379.07
Replace	DRYWALL CEIL	728.98	SFC	1.30	958.52
Remove	PLASTER & WIRE LATH,3 COATS	728.98	SF	1.15	838.33
Replace	SOUND BOARD CEILING, 1/2"	728.98	SFC	1.12	825.93
Paint	CEILING, 2 COATS + PRIME	728.98	SFC	0.59	430,10
Special	TEXTURE CEILING	728.98	SFC	0.77	561.31
Remove	INSUL,CEIL,BATT,FOIL FC,9"	728.98	SFC	0.20	145.80
Replace	INSUL,CEIL,BATT,FOIL FC,9"	728.98	SFC	1.07	780.01
Remove	DRYWALL WALL	782,28	SFW	0.30	234.68
Replace	DRYWALL WALL	782,28	SFW	1.22	975.03
Special	SIZE WALLS	782.28	SFW	0.21	164.28
Remove	WALLPAPER, EXCELLENT	782,28	SFW	0.41	320.73
Replace	WALLPAPER, EXCELLENT	782.28	SFW	1.68	1,337.63
Remove	WALLPAPER BORDER	95.40	LFW	0.34	32.44
Replace	WALLPAPER BORDER	95.40	LFW	1,34	128.79
Remove	BASE, COLONIAL, 3 1/2"	95.40	LFW	0.25	23.85
Replace	BASE, COLONIAL, 3 1/2"	95.40	LFW	2.56	251.88
Paint	BASE, COLONIAL, 3 1/2"	95.40	LFW	0.65	62.01
Remove	DOOR TRIM SET, CUSTOM	4.00	EA	9.32	37.28
Replace	DOOR TRIM SET, CUSTOM	4.00	EA	80.79	327.48

Building Repair Estimate Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 PA12 Page 44 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

Waste Applied

Page

18

 Paint Remove	DOOR TRIM SET, CUSTOM				
	DOOK IKIMI SEI, CUSIOM	4.00	EA	22.14	88,56
	MOLDING, CROWN, 4 5/8"	95,40	LFW	0.43	41.02
Replace	MOLDING, CROWN, 4 5/8"	95,40	LFW	4.55	436.03
Remove	SHEATHING FLOOR, PLYWOOD	728.98	SFC	0.47	342.62
Replace	SHEATHING FLOOR, PLYWOOD	728.98	SFC	1.87	1,372.46
Remove	SHEATHING FLOOR, PLYWOOD 21	728.98	SFC	0.47	342.62
Replace	SHEATHING FLOOR, PLYWOOD 21	728.98	SFC	1.87	1,372.46
Remove	CARPET & PAD, EXCELLENT (SY)	81,00	SYF	2.07	167.67
Replace	CARPET & PAD, EXCELLENT (SY)		SYF	33.55	2,957.59
-	CARPETWASTE FACTOR	33.55		2.80	93.94
Remove	DOOR, EXT, ANDERSON FRENCH	1.00	EA	13.55	13.55
Replace	DOOR, EXT, ANDERSON FRENCH		EA	1,999.00	1,999.00
Paint	DOOR, EXT, ANDERSON FRENCH		EA	136.00	136.00
Remove	WINDOW, CASEMENT, LG	2.00	EA	21.69	43.38
Replace	WINDOW, CASEMENT, LG	2.00	EA	695.00	1,390.00
Paint	WINDOW, CASEMENT, LG	2,00	EA	37.66	75.32
Remove	WIRING, RESIDENCE	728.98	SF	0.10	72.90
Replace	WIRING, RESIDENCE	728.98		2.75	2,004.69
Remove	RECEPTACLE, DUPLEX/SWITCH	14.00		4.32	60.48
Replace	RECEPTACLE, DUPLEX/SWITCH	14.00		22.00	308.00
Replace	FIXTURE, INCNDSCENT, RECESS	12.00		108,00	1,296.00
Remove	SWITCH, DIMMER TYPE	3.00		4.76	14.28
Replace	SWITCH, DIMMER TYPE	3.00		65.71	197.13
Replace	REGISTER, HEAT, 12" X 5"	4.00		22.59	90.36
Paint	REGISTER, HEAT, 12" X 5"	4.00		3.55	14.20
Remove	CABINET, BASE, WET BAR		LFW	15.00	1,431.00
Replace	CABINET, BASE, WET BAR		LFW	800.00	800.00
Replace	CABINET, UPPER WET BAR		LFW	595.00	595.00
Remove	COUNTER TOP CORIAN JOB BUILT			2.71	10.84
Replace	COUNTER TOP CORIAN JOB BUILT			600.00	600.00
Remove	SINK, WET BAR	1.00		27.11	27.11
Replace	SINK, WET BAR	1.00		128.70	128.70
Remove	FAUCET, SINGLE LEVER	1.00		19.36	19.36
Replace	FAUCET, SINGLE LEVER	1.00		126.16	126.16
Special	ROUGH IN KITCHEN SINK SUPL	1.00		498.08	498.08
Remove	DOOR, CLOSET, BIFOLD, PANEL	2.00		30.49	60.98
Replace	DOOR, CLOSET, BIFOLD, PANEL	2.00		169.07	338.14
Paint	DOOR, CLOSET, BIFOLD, PANEL	2.00		16.91	33.82
Special	SANDBLAST FIRE PLACE	117.00		1.55	181.35
Rem/Reset		1.00		185.00	185.00
Replace	CLEAN DOUBLE CHIMNEY	1.00		175.00	175.59
Special	DRAPERIES, REMOVE/RESET	2.00		31.49	62.98

Interior

ORMAL DINING ROOM

17.00 X 12.00 X 8.20 + offset 5.30 X 3.00 SFLW= 139.40 SFSW= 98.40

SFC = 219.90 SFW = 524.80

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 Page 45 of 50

Building Repair Estimate

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

Overrides

= Waste Applied

Page 19

0	peration	Description	Quantity i		Unit / Cost	Repl / Cost
	Remove	JOIST, CEILING & FLOOR COMPLE	439.70	LFF	0.57	250.63
	Replace	JOIST, CEILING & FLOOR COMPLE	439.70	LFF	2.14	984.36
	Remove	WALL STUD, 2"x4" COMPLETE	524.80	SFW	0.72	377.86
	Replace	WALL STUD, 2"x4" COMPLETE	524.80	SFW	1.82	955.14
	Remove	DRYWALL CEIL	219.90	SFC	0.52	114.35
	Replace	DRYWALL CEIL	219.90	SFC	1.30	296.72
	Paint	CEILING, 2 COATS + PRIME	219.90		0.59	129.74
Interior	Special	TEXTURE CEILING	219.90		0.77	169.32
	Remove	INSUL,CEIL,BATT,FOIL FC,9"	219.90	SFC	0.20	43.98
FOYI	Replace	INSUL,CEIL,BATT,FOIL FC,9"	219.90	SFC	1.07	235.29
	Remove	DRYWALL WALL	524.80	SFW	0.30	157.44
FI	Replace	DRYWALL WALL	524.80	SFW	1.22	660.90
SC	Paint	DRYWALL WALL, 5/8"FIRE RES	262.40	SFW	0.58	152.19
RI	Special	SIZE WALLS	262.40	SFW	0.21	55.10
S۱	Remove	WALLPAPER, EXCELLENT	262.40	SFW	0.41	107.58
	Replace	WALLPAPER, EXCELLENT	262,40	SFW	1.68	478.62
	Remove	WALLPAPER BORDER	64.00	LFW	0.34	21.76
	Replace	WALLPAPER BORDER	64.00	LFW	1.34	86.71
	Remove	BASE, COLONIAL, 3 1/2"	64,00	LFW	0.25	16.00
	Replace	BASE, COLONIAL, 3 1/2"	64.00	LFW	2.56	171.50
	Paint	BASE, COLONIAL, 3 1/2"	64.00	LFW	0.65	41.60
	Remove	DOOR TRIM SET, CUSTOM	2.00	EA	9.32	18.64
	Replace	DOOR TRIM SET, CUSTOM	2.00	EA	80.79	163.74
	Paint	DOOR TRIM SET, CUSTOM	2.00	EA	22.14	44.28
	Remove	CHAIR RAIL, 3 1/2"	64.00	LFW	0.25	16.00
	Replace	CHAIR RAIL, 3 1/2"	64.00	LFW	3.24	217.60
	Paint	CHAIR RAIL, 3 1/2"	64.00	LFW	0.65	41.60
	Remove	MOLDING, CROWN, 4 5/8"	64.00	LFW	0.43	27.52
	Replace	MOLDING, CROWN, 4 5/8"	64.00	LFW	4.55	293.16
	Remove	OPENING, CASED	1.00	EA	10.72	10.72
	Replace	OPENING, CASED	1.00	EA	82,36	85.36
	Paint	OPENING, CASED	1.00	EA	30.99	30.99
	Remove	WINDOW TRIM SET, CUSTOM	2.50	EA	10.72	26.80
	Replace	WINDOW TRIM SET, CUSTOM	2.50	EA	81.04	204.38
	Paint	WINDOW TRIM SET, CUSTOM	1.00	EA	2.50	2.50
	Remove	SHEATHING FLOOR, PLYWOOD	219.90	SFC	0.47	103.35
	Replace	SHEATHING FLOOR, PLYWOOD	219.90	SFC	1.87	420.48
	Remove	SHEATHING FLOOR, PLYWOOD 21	219.90	SFC	0.47	103.35
	Replace	SHEATHING FLOOR, PLYWOOD 21	219.90		1.87	420.48
	Remove	CARPET & PAD, EXCELLENT (SY)	24.43		2.07	50.57
	Replace	CARPET & PAD, EXCELLENT (SY)	24,43		33,55	1,059.66
	Rem/Reset	CARPETWASTE FACTOR	24.43		2.80	68.40
	Replace	WINDOW, BOW CASEMENT, 26 X 2	1.00		1,700.00	1,700.00
	Remove	WINDOW, CASEMENT, LG	1.00		41.00	41.00
	Paint	WINDOW, CASEMENT, LG	1.00		55,00	55.00
	Remove	WIRING, RESIDENCE	219.90		0.10	21.99
	Replace	WIRING, RESIDENCE	219.90		2.75	604.72
	Remove	RECEPTACLE, DUPLEX/SWITCH	6.00		4.32	25.92
	Replace	RECEPTACLE, DUPLEX/SWITCH	6.00		22.00	132.00

Document 24-4 Filed 12/16/2005 Page 46 of 50 Claim Number: Case 1:04-cv-00175-SJM Building Repair Estimate

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead. Profit or Taxes

= Overrides

Waste Applied

Page 21

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
- Replace	SHEATHING FLOOR, PLYWOOD	233.16 SFC	1.87	445,27	
Remove	UNDERLAYMENT3/4"	233.16 SFF	0.49	114.25	
Replace	UNDERLAYMENT3/4"	233.16 SFF	1.87	446.64	
Remove	CERAMIC FLOOR, THIN SET, 12"X1	233.16 SFF	0.71	165.54	
Replace	CERAMIC FLOOR, THIN SET, 12"X1	233.16 SFF	11.00	2,591.00	
Remove	WIRING, RESIDENCE	233.16 SF	0.10	23.32	
Replace	WIRING, RESIDENCE	233,16 EA	2.75	641.19	
Remove	RECEPTACLE, DUPLEX/SWITCH	14.00 EA	4.32	60.48	
Replace	RECEPTACLE, DUPLEX/SWITCH	14.00 EA	22.00	308.00	
Remove	CEILING FIXTURE, EXCELLENT	3.00 EA	9.35	28.05	
Replace	CEILING FIXTURE, EXCELLENT	3.00 EA	131,43	394.29	
Remove	DOOR BELL, EXCELLENT	1.00 EA	8.47	8.47	
Replace	DOOR BELL, EXCELLENT	1.00 EA	147.35	147.35	
Replace	REGISTER, HEAT, 12" X 5"	2,00 EA	22.59	45.18	
Paint	REGISTER, HEAT, 12" X 5"	2.00 EA	3.55	7.10	
Remove	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	33.89	67.78	
Replace	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	188.49	376.98	
Paint	DOOR, CLOSET, BIPASS, LOUVER	2.00 EA	38,00	76.00	
Remove	DOOR, INT, PH, 6 PANEL 36"	2.00 EA	30.49	60.98	
Replace	DOOR, INT, PH, 6 PANEL 36"	2.00 EA	295,00	590.00	
Paint	DOOR, INT, PH, 6 PANEL 36"	2.00 EA	35.16	70.32	
Remove	LOCKSET, PASSAGE, EX	2.00 EA	8.47	16.94	
Replace	LOCKSET, PASSAGE, EX	2.00 EA	78.00	156.00	
Remove	DEAD BOLT LOCK	2.00 EA	6.45	12.90	
Replace	DEAD BOLT LOCK	2.00 EA	74,40	148,80	
Rem/Reset	KICK PLATES AND HAND PLATES	2.00 EA	87.07	174.14	

Interior

CLOSET	2.70 X 6.10 50.02 SFR	X = 8.20 = 160.79	SFC = 16.47 Perimeter = 17	SFW = 144.32 7.60	SFLW= 22.14	SFSW=
FLOOR JOIS	T DAMAGED				·	
Remove	JOIST FLOOR COMPLETE	16.47	LFF	0.57	9.39	
Replace	JOIST FLOOR COMPLETE	16.47	LFF	2.14	36.87	
Remove	WALL STUD, 2"x4" FRONT WALL	144.32	SFW	0.72	103.91	
Replace	WALL STUD, 2"x4" COMPLETE	144.32	SFW	1.82	262.66	
Remove	PLASTER & WIRE LATH,3 COATS	16.47	SF	1.15	18.94	
Replace	PLASTER & WIRE LATH,3 COATS	16.47	SF	5.72	94.56	
Remove	DRYWALL WALL,1/2", TAPED	144.32	SFW	0.30	43.30	
Replace	DRYWALL WALL,1/2", TAPED	144.32	SFW	1.22	194,48	
Paint	CEILING, 2 COATS + PRIME	16.47	SFC	0.59	9.72	
Remove	INSUL,CEIL,BATT,FOIL FC,9"	16.47	SFC	0.20	3.29	÷
Replace	INSUL,CEIL,BATT,FOIL FC,9"	16.47	SFC	1.07	17.62	
Remove	DRYWALL WALL	144.32	SFW	0.30	43.30	
Replace	DRYWALL WALL	144.32	SFW	1.22	196.72	
Paint	WALLS, 2 COATS	144.32	SFW	0.58	83.71	
Remove	BASE, COLONIAL, 3 1/2"	17.60	LFW	0.25	4.40	
Replace	BASE, COLONIAL, 3 1/2"	17.60	LFW	2.56	52.71	

Building Repair established Claim | Document 24-4 Claim | Repair |

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

= Overrides

= Waste Applied

Page

22

Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
Paint	BASE, COLONIAL, 3 1/2"	17.60 LFW	0.65	11.44	
Remove	BASE SHOE, PINE	17.60 LFW	0.27	4.75	
Replace	BASE SHOE, PINE	17.60 LFW	1.58	30.24	
Paint	BASE SHOE, PINE	17.60 LFW	0.62	10.91	
Remove	MOLDING, CROWN, 4 5/8"	17.60 LFW	0.43	7.57	
Replace	MOLDING, CROWN, 4 5/8"	17.60 LFW	2.76	56.91	
Paint	MOLDING, CROWN, 4 5/8"	17.60 LFW	0.70	12.32	
Remove	DOOR TRIM SET, CUSTOM	1.50 EA	9.32	13.98	
Replace	DOOR TRIM SET, CUSTOM	1.50 EA	80.79	122.63	
Paint	DOOR TRIM SET, CUSTOM	1,50 EA	22.14	33.21	
Remove	SHEATHING FLOOR, PLYWOOD	16.47 SFC	0.47	7.74	
Replace	SHEATHING FLOOR, PLYWOOD	16,47 SFC	1.87	40.06	
Remove	UNDERLAYMENT, LAUAN, 3/4"	16.47 SFF	0.49	8.07	
Replace	UNDERLAYMENT, LAUAN, 3/4"	16.47 SFF	1.87	41.43	
Remove	CERAMIC FLOOR, THIN SET, 12"X1	16.47 SFF	0.71	11.69	
Replace	CERAMIC FLOOR, THIN SET, 12"X1	16.47 SFF	11.00	207.41	
Remove	WIRING, RESIDENCE	16.47 SF	0.10	1.65	
Replace	WIRING, RESIDENCE	16.47 EA	2.75	45.29	
Remove	CLOSET POLE, 3 1/2"	6.10 LF	0.31	1.89	
Replace	CLOSET POLE, 3 1/2"	6.20 LF	3.10	19.56	
Paint	CLOSET POLE, 3 1/2"	6.10 LF	0.87	5.31	
Remove	SHELF, 1" x 10"	12.20 LFW	0.90	10.98	
Replace	SHELF, 1" x 10"	12.20 LFW	6.54	81.15	
Paint	SHELF, 1" x 10"	12.20 LFW	1,37	16.71	
Replace	COAT HOOKS	4.00 LFW	5.56	22.66	
Remove	CEILING FIXTURE, PORCELAIN	1.00 EA	8,47	8.47	
Replace	CEILING FIXTURE, PORCELAIN	1.00 EA	64.98	64.98	

Interior

PINK ROOM REAR IST FLOOR 20.60 X 14.30 X 8.00 + offset 2.80 X 6.80 SFC = 313.62SFW = 667.20SFLW= 164.80 SFSW= 114.40 SFR = 980.82Perimeter = 83.40

EXAMINE THE PIPE CASE IN CLOSET. HEAVY SMOKE, EXAMINED BELOW JAGUZZI TUB AND NOTICE SMOKE BLOW UP. NOTICE BLOW UP AROUND BASE TRIM. WALL AND CEILING FULL OF SMOKE. THE ROOM ABOVE THIS ROOM ALSO HAS SIGNS OF HEAVY SMOKE IN WALLS SO KNOW IT PASSED THROUGH THIS ROOM. WINDOWS WILL NEVER CLEAN AND THE HARDWARE ON THE WINDOWS IS DAMAGED. ROUGH FIBERGLASS UNDER TUB SMOKED

Remove	JOIST, FLOOR BAKING SODA SPRA	313.62 LFF	0.92	288.53
Remove	WALL STUD, 2"x4" COMPLETE CLE	667.20 SFW	0.12	80,06
Special	CLEAN & SEAL FRAMING CEILING	313.62 SFL	0.32	100.36
Special	CLEAN & SEAL FRAMING WALL	667.20 SFL	0.32	213.50
Remove	DRYWALL CEIL	313.62 SFC	0.52	163.08
Replace	DRYWALL CEIL	313.62 SFC	1.30	418.55
Paint	CEILING, 2 COATS + PRIME	313.62 SFC	0.59	185.04
Remove	INSUL,CEIL,BATT,FOIL FC,9"	313.62 SFC	0.20	62.72
Replace	INSUL,CEIL,BATT,FOIL FC,9"	313.62 SFC	1.07	335,57
Remove	DRYWALL WALL	667.20 SFW	0.30	200.16

Building Repail Repail O4-cv-00175-SJM Document 24-4 Claim Hadmond 16/2005 PAIL age 48 of 50

* = Min. Charge

Insured:

BORDEN

^ = Exempt from Overhead, Profit or Taxes

Waste Applied

= Overrides Page 23

Operation	Description	Quantity /	Unit	Unit / Cost	Repl / Cost
Replace	DRYWALL WALL	667.20	SFW	1,22	834.63
Paint	DRYWALL WALL	667.20	SFW	0.58	386.98
Special	DRYWALL POST	1.00	LS	176.41	176.41
Remove	BATT INSULATION - WALL R19	333.50	SFW	0.19	63.36
Replace	BATT INSULATION - WALL R19	333.50	SFW	0.82	273.47
Remove	BASE, COLONIAL, 3 1/2"	83.40	LFW	0.25	20.85
Replace	BASE, COLONIAL, 3 1/2"	83.40	LFW	2.56	221.16
Paint	BASE, COLONIAL, 3 1/2"	83.40	LFW	0.65	54.21
Remove	DOOR TRIM SET, CUSTOM	4.50	EA	9.32	41.94
Replace	DOOR TRIM SET, CUSTOM	4.50	EA	80.79	368.24
Paint	DOOR TRIM SET, CUSTOM	4.50	EA	22.14	99,63
Rem/Reset	DOOR, INT, PH, 6 PANEL	1.00	EΑ	60.36	60.36
Clean	DOOR, INT, PH, 6 PANEL	1.00	EA	5.24	5.24
Paint	DOOR, INT, PH, 6 PANEL	1.00	EA	35.16	35,16
Rem/Reset	DOOR ACCESSORIES	1.00	EA	34.00	34.00
Rem/Reset	DOOR, INT, POCKET	1.00	EA	60.14	60.14
Clean	DOOR, INT, POCKET	1.00	EA	3.88	3.88
Paint	DOOR, INT, POCKET	1.00	EA	20.71	20.71
Remove	WINDOW TRIM SET, CUSTOM	3.00		10.72	32.16
Replace	WINDOW TRIM SET, CUSTOM	3.00		81.04	245.12
Paint	WINDOW TRIM SET, CUSTOM	3.00		2.50	7.50
Remove	CASEMENT ANDERSON VYN/WOC	3.00	EA	21.69	65.07
Replace	CASEMENT ANDERSON VYN/WOC	3,00	EA	695.00	2,085.00
Paint	WINDOW, CASEMENT, LG	3.00	EA	37.66	112.98
Clean	DOOR, SLIDING, WOOD, 8'	1.00		22.00	22.00
Paint	DOOR, SLIDING, WOOD, 8'	1.00	EA	62.00	62.00
Remove	CARPET & PAD, EXCELLENT (SY)	34.85	SYF	2.07	72.14
Replace	CARPET & PAD, EXCELLENT (SY)	34.85		33.55	1,409.25
Rem/Reset	CARPETWASTE FACTOR	34,85		2.80	97.58
Remove	WIRING, RESIDENCE	313.62		0.10	31.36
Replace	WIRING, RESIDENCE	313.62		2,75	862,45
Remove	RECEPTACLE, DUPLEX/SWITCH	9.00		4.32	38.88
Replace	RECÉPTACLE, DUPLEX/SWITCH	9.00		22.00	198.00
Remove	SWITCH, DIMMER TYPE	4.00		4.76	19.04
Replace	SWITCH, DIMMER TYPE	4.00		65.71	262.84
Replace	FIXTURE,INCNDSCENT,RECESS	14.00		108.00	1,512.00
Remove	OUTLET, TELEPHONE/CABLE	3.00		4.32	12.96
Replace	OUTLET, TELEPHONE/CABLE	3.00		20.35	61.05
Remove	THERMOSTAT, EXCELLENT	2.00		8.47	16.94
Replace	THERMOSTAT, EXCELLENT	2.00		86.04	172.08
Replace	REGISTER, HEAT, 12" X 5"	5.00		22.59	112.95
Paint	REGISTER, HEAT, 12" X 5"	5.00		3.55	17.75
Special	DRAPERIES, REMOVE	3.00		31.49	94,47
-	DRAPERIES, REPLACE	3.00		135.00	
=	TV MOUNT FOR WALL	1.00		25.00	405.00
	TV MOUNT FOR WALL	1.00		12.00	25.00 12.00
	CERAMIC FLOOR, THIN SET, 1"X1"	175.00		1.18	12.00
	CERAMIC FLOOR, THIN SET, 1"X1"	175.00		11.00	206.50 1,989.89
•		A + D . O O 1		11.00	1.767.67

Case 1:04-cv-00175-SJM Document 24-4 Filed 12/16/2005 Page 49 of 50

Building Repair Estimate

Claim Number:

PA123

* = Min. Charge

Insured:

BORDEN



Exempt from Overhead, Profit or Taxes

Overrides

Page

24

~ = Waste Applied

					· · · · · · · · · · · · · · · · · · ·	
	Operation	Description	Quantity / Unit	Unit / Cost	Repl / Cost	
••	Remove	COLEMAN JACUZZI HORIZON SER	1.00 EA	53.79	53,79	
	Replace	COLEMAN JACUZZI HORIZON SER	1.00 EA	3,200.00	3,200.00	
	Remove	SMOKE DETECTOR	1.00 EA	9,35	9.35	
	Replace	SMOKE DETECTOR	1.00 EA	54.53	54.53	

Interior							
CLOSET IN I	PINK ROOM	5.40 X 8.40 68.88 SFR	X = 8.20 R = 271.68	SFC = 45.36 Perimeter = 2	SFW = 226.32 27.60	SFLW= 44.28	SFSW=
	torra et ood d	VD 10 00D 1 0DD		Y 1995	0.00	41.50	
Remove	·				0.92	41.73	
Remove	•				0.12	27.16	
Special	CLEAN & SEAL F.				0.32	29.03	
Special	CLEAN & SEAL F	RAMING WALL	226.32		0.32	72.42	
Remove			45.36		0.52	23.59	
Replace			45.36		1.30	69.81	
Paint	CEILING, 2 COAT		45.36		0.59	26.76	
Remove	• •		45.36		0.20	9.07	
Replace			45.36		1.07	48.54	
Remove			226.32		0.30	67.90	
Replace			226.32		1.22	296.76	
Paint	WALLS, 2 COATS		226,32	SFW	0.58	131.27	
Remove	BATT INSULATIO	N - WALL R19	- 226.32	SFW	0.19	43.00	
Replace	BATT INSULATIO	N - WALL R19	226,32	SFW	0.82	185.58	
Remove	BASE, COLONIAL	., 3 1/2"	27.60	LFW	0.25	6.90	
Replace	BASE, COLONIAL	., 3 1/2"	27.60	LFW	2,56	78.31	
Paint	BASE, COLONIAL	., 3 1/2"	27.60	LFW	0.65	17.94	
Remove	DOOR TRIM SET,	CUSTOM	1.50	EA	9.32	13.98	
Replace	DOOR TRIM SET,	CUSTOM	1.50	EA	80.79	122.63	
Remove	CARPET & PAD, E	EXCELLENT (SY)	5.04	SYF	2.07	10.43	
Replace	CARPET & PAD, E	EXCELLENT (SY)	5.04	SYF	33.55	409.13	
Rem/Res	set CARPETWASTE F.	ACTOR	5.04	SYF	2.80	14.11	
Remove	WIRING, RESIDER	NCE	45.60	SF	0.10	4,56	
Replace	WIRING, RESIDER	NCE	45.60		2,75	125.40	
Remove			1.00		70,60	70.60	
Replace	SERVICE PANEL,		1.00		871.95	871.95	
Special	CHECK & TEST N				300.00	300.00	
Replace	FIXTURE, INCNDS	· ·	1.00		108.00	108.00	
Remove	SHELF, 1" x 10"		73.60		0.90	66.24	
Replace	SHELF, 1" x 10"		73.60		6.54	489.59	
Paint	SHELF, 1" x 10"		73.60		1.37	100.83	
Replace	SMALL BUILT IN			LFW	175.00	175.03	
Paint	SMALL BUILT IN			LFW	15.00	15.00	
Remove	CLOSET POLE, 3 1	1/2"	6.00		0.31		
Replace	CLOSET POLE, 3 1		6.00		3.10	1.86	
Paint	CLOSET POLE, 3 1					18.92	
гаши	CLUSE I PULE, 3 I	172	6.00	Lľ	0.87	5.22	

Building Repair Estimate Case 1:04-cv-00175-SJM Document 24-4 Claim Number: 16/2005 PA Page 50 of 50 Insured: BORDEN * = Min. Charge ^ = Exempt from Overhead, Profit or Taxes Page 25 # = Overrides Waste Applied Operation Description Quantity / Unit Unit / Cost Repl / Cost Interior SFSW= **BATHROOM IN PINK ROOM** 6.30 X 8.30 X 8.20 SFC = 52.29SFW = 239.44SFLW= 51.66 68.06 SFR = 291.73Perimeter = 29.20SMOKE ALL UNDER TUBS AND IN WALLS FOLLOWED PIPES UP 0.92 Remove JOIST, FLOOR BAKING SODA SPRA 52.29 LFF 48.11 Remove WALL STUD, 2"x4" COMPLETE CLF 239.44 SFW 0.12 28.73 Special CLEAN & SEAL FRAMING CEILING 104,58 SFL 0.32 33.47 Special CLEAN & SEAL FRAMING WALL 239.44 SFL 0.32 76.62 Remove DRYWALL CEIL 52.29 SFC 0.52 27.19 Replace DRYWALL CEIL 52.29 SFC 1.22 74.64 Paint CEILING, 2 COATS + PRIME 52.29 SFC 0.59 30.85 52.29 SFC Remove INSUL, CEIL, BATT, FOIL FC, 9" 0.20 10.46 52.29 SFC Replace INSUL, CEIL, BATT, FOIL FC, 9" 1.07 55.95 Remove DRYWALL WALL 239.44 SFW 0.30 71.83 Replace 184.00 SFW DRYWALL WALL 1.22 231.29 CEMENT BOARD 55.00 LS Special 3.55 195.25 Special SIZE WALLS 55.00 SFW 0.21 11.55 Remove WALLPAPER, EXCELLENT 55.00 SFW 0.41 22.55 Replace WALLPAPER, EXCELLENT 55.00 SFW 1.68 100.32 Remove WALLPAPER BORDER 29.20 LFW 0.34 9.93 Replace WALLPAPER BORDER 29.20 LFW 1.34 40.08 Remove CERAMIC WALLS, THIN SET, 4" 184.00 SFW 1.47 270.48 CERAMIC WALLS, THIN SET, 4" Replace 184.00 SFW 11.00 2,075.23 Replace CERAMIC FIXTURE (EA) 1.00 EA 20.45 20,45 Remove **BATT INSULATION - WALL R19** 239.44 SFW 0.19 45.49 Replace **BATT INSULATION - WALL R19** 239.44 SFW 0.62 148.45 Remove BASE, COLONIAL, 3 1/2" 9.00 LFW 0.25 2.25 Replace BASE, COLONIAL, 3 1/2" 9.00 LFW 2.56 24.02 Paint BASE, COLONIAL, 3 1/2" 9.00 LFW 0.65 5.85 Remove DOOR TRIM SET, CUSTOM 2.00 EA 9,32 18.64 Replace DOOR TRIM SET, CUSTOM 2.00 EA 80.79 163.74 Paint DOOR TRIM SET, CUSTOM 2.00 EA 22.14 44.28 Remove DOOR, INT, PH, 6 PANEL 1.00 EA 30.49 30.49 Replace DOOR, INT, PH, 6 PANEL 1.00 EA 100.00 100.00 Paint DOOR, INT, PH, 6 PANEL 1.00 EA 35.16 35.16 Remove WINDOW TRIM SET, CUSTOM 1.00 EA 10.72 10.72 WINDOW TRIM SET, CUSTOM Replace 1.00 EA 81.04 84.38 Paint WINDOW TRIM SET, CUSTOM 1.00 EA 31,26 31.26 Remove CASEMENT ANDERSON VYN/WOC 1.00 EA 21.69 21.69 Replace CASEMENT ANDERSON VYN/WOC 1.00 EA 695.00 695.00 Paint WINDOW, CASEMENT, LG 1.00 EA 37.66 37.66 Rem/Reset REGISTER, HEAT, 12" X 5" 1.00 EA 19.34 19,34 Clean REGISTER, HEAT, 12" X 5" 1.00 EA 3.18 3.18 Paint REGISTER, HEAT, 12" X 5" 1.00 EA 3,55 3.55 Remove SHEATHING FLOOR, PLYWOOD 52.29 SFC 0.47 24.58 Replace SHEATHING FLOOR, PLYWOOD 52.29 SFC 1.87 107.04 Remove CERAMIC FLOOR, THIN SET, 12"X1 52.29 SFF 0.71 37.13

52.29 SFF

11.00

601 43

Replace

CERAMIC FLOOR, THIN SET, 12"X1